

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016195/UPS3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100427396-04

Claimant
Vehicle No : SGG850T **Insured Vehicle No :** SKV1908D

Date of Loss: 31/08/2019 **Nature of Claim:** TP **Claim No:** 5911771652SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|------------------------------------|-----------------------------------|--------------------|-------------------|
| Reg No: | SGG850T | Engine No: | VQ25382959A |
| Make & Model: | NISSAN TEANA, 2.5 (A) | Chassis No: | JN1BBUJ32Z0000583 |
| Reg. Date: | 18/09/2008 (Man. Year: 2008) | Odometer: | 175881 km |
| Colour: | Silver | | |
| Engine Capacity: | 2496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/55 R17 | Rear Tyre Size: | 215/55 R17 |
| Front Left Side: | Dayton 6 mm | Rear Left Side: | Dayton 6 mm |
| Front Right Side: | Dayton 6 mm | Rear Right Side: | Dayton 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 3,364.76 | 2,802.42 | 562.34 | 16.71 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,620.00 | 920.00 | 700.00 | 43.21 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$) | 4,984.76 | 3,722.42 | 1,262.34 | 25.32 |
| Approved Total (Overridden) (\$) | | 2,600.00 | | |
| (\$) | 4,984.76 | 2,600.00 | 2,384.76 | 47.84 |
| + GST 7.00/7.00% (\$) | 348.93 | 182.00 | 166.93 | 47.84 |
| Nett Amount (\$) | 5,333.69 | 2,782.00 | 2,551.69 | 47.84 |
| + Loss of Use (4.0 x \$60.00/day) (\$) | | 240.00 | | |
| + Doc/Search Fee (\$) | | 2.00 | | |
| Nett Liability (\$) | | 3,024.00 | | |

INSPECTION

Date of Assignment: 26/02/2020

Date Inspected: 26/02/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *HEADLAMP RH | Scratched | 2,188.60 FL | *2,188.60 FL |
| 2 | 1 | | *FRONT BUMPER | Deep Cut | 720.00 FL | *720.00 FL |
| 3 | 1 | | *FRONT BUMPER RETAINER RH | Not Necessary | 55.50 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER RETAINER LH | Not Necessary | 55.50 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER CHROME RH | Necessary | 121.20 FL | *121.20 FL |
| 6 | 1 | | *FRONT BUMPER CHROME LH | Not Necessary | 121.20 FL | *- FL |
| 7 | 1 | | *FRONT FENDER SHIELD RH | Not Necessary | 99.40 FL | *- FL |
| 8 | 1 | | *HEADLAMP LOWER BRACKET RH | Not Necessary | 30.00 FS | *- FS |
| 9 | 1 | | *HEADLAMP NOZZLE RH | Serviceable | 233.90 FS | *- FS |
| 10 | 1 | | *HEADLAMP NOZZLE COVER RH | Cut | 75.60 FS | *75.60 FS |
| 11 | 1 | | *FRONT HEADLAMP RH (NPA) | Repair | 0.00 FS | *- FS |
| 12 | 1 | | *BONNET (NPA) | Repair | 0.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 3,700.90 | 3,105.40 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 336.14 | 302.98 |
| Total Parts (\$\$) | 3,364.76 | 2,802.42 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | LABOUR TO REMOVE & REFIT NECESSARY PARTS | New | 600.00 | 300.00 |
| 2 | SPRAY PAINT ON THE AFFECTED AREAS | New | 800.00 | 600.00 |
| 3 | ANTI-RUST COATING | New | 180.00 | 0.00 |
| 4 | WIRING | New | 40.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 1,620.00 | 920.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >