*ASS, REC. BY	RI RI	E:03/A191	9016196/Fcd	300 Species	d Instruction:	
Sunveyor: MUNION Prom (Person Estimated Co	chin lee ying	ASSIGN.	MENT (Office)	Ds	ate/Time: 12/9/190	10:04cm
^	'S/TP RES/OD RES/	SMNIS	Bill to: OI L OI Bearry	Insured: Tel:	SMA 4975B 9143 6036	
of Folicy No: Sum Insured:		lleif the 2	# 02-(7 Claim No: _ Excess:	3 423	D2ICC08F	
Make of Veh (Client's Recor	d)			D.	0.A 9/9/2019	
CA / REV Date/Time:	1 REP. / REV 24 HRS 3.27pm@12/9/19	Person Contacte	d: Mr.fol	Vel	H.O.D. Endorsement:	
Date/Time	Action/Instruction I SMA 1501L - X SMA 4975B -					
	Dismantle: 19/9					
×						

ASSI	1	NIN	11	NE
ASSI	1	NIV	ш	INI

2001	ACTURE AT
From Date:	Veli No: SMN 1501 L Yr Regn: Jul / 2019
	Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: SMN 1501 L	Make: Honda Vezel a.c. 1496
at Workshop m/s M.S. poune Beating wksp	Calour Porple NG: Insured / Std / NI / NA
of 2 Kaki Bukit Ave 2 # 02-17	Sp.Reading 000 596 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: RU1-1320729 .
Claims No.	Gen, Conf. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering Inorder Dammed / Leaked / Burnt or
(Client's Record)	Brake: (Inorder) Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) STD A/Rim or
	Tyre Size: F: 215/60 R 1 6
(Policy Condition)	R: 215/60R16
Remark: The veh had commenced its N/S 0/9	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	ТОУО / УОКО ог
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal 7 P/Bal 7
GIA / PR Seen: Consistent? : Yes or No	L/Bal 7 L/Bal 7
Est. Repairs: days Res.: Yes or No	D.O.A. 09/09/2019 D.O.I. 12/09/19
Lum Sum: % 3 Val.: Yes or No	Survey held at M.S. Panel Beating wksp
CA / REV / REP. / 24 HRS	Des. of Damager: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Frt 0/5 & N/S / N/S Front D/S Front
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Range 13000 - \$14000	
Repair dos 10 das	
190gs	, marin
	- 1 1 - 2
	stakes.
MV: \$86000	23[1]
PV: \$38356	
NV : \$47000	. /
Date/Time, File Pass to? Proli Report	V
. Fran. Keport	ays Of Repair:
) : Final Report Roate/Time, File Return to?	esurvey No. of Trip: Survey Fee: 180
Add Fee:	: Site Insp. (\$) S+165, 49
	Interview (\$
Report Format: DAR	
ump Sum / I.B.I: (\$	/ Militia
,	: Weekend (\$
	TOTAL 178 x

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	11 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt					Pending for Sur Report Cancel Case	vey
Main Reference					Claim Details		Document	s	Show All
CLAIM SU	BFOLDER DE	TAILS	PARTY PARTY AND		STATISTICS COLUMNS	[Create	ed by adjuster]	DI MINIMA DE LA CASA DEL CASA DE LA CASA DEL CASA DE LA	
Insured:	WONG AH	LUI, ID: S0327	338E						
Main Claimant:	AH HWEE	LEE, ID: S7708	3487H						
Vehicle Reg No.:	SMN150	1L			Date of Loss:	: 09/09/2019 16:00 - :59			
Claim Type	TP / 342	3980221SG			Policy/Cover Note No.:				
Vehicle Reg No. (Insured):	SMA4975B			Policy No. (Claimant):					
(4.1.4.4.4.4.7.1					Excess:				
Repairer:	M.s Panel	Beating Worksh	op (HQ) 2 KAK	I BUKIT AVE	6, # 02 . 17 AU	тонив @	KAKI BUKIT, 4179	21 Kaki Bukit - Tel:	
Handling Insurer:	WZ.Tan@a	ig.com					ed by Tan, Bennie -		
Adjuster:	23/09/20	Consultants Pte 19]	Ltd (HQ) - Tel:	6256-3561	[Handled by I	PARASUF	RAM SHANMUGAM] [Final Rpt o	lue
ASSOCIA	TED MAIL RE	CEIVED					1	/iew All Compose	Case Mai
 AIG_SG 	(13/09/2019):	Request To Upl	oad TP GIA Re	port					
ALL ASSO	CIATED TAS	KS⊟				View A	All Search Tasks	Create New Task	Complet
Due Dat	e Priority	Type Task	Group Sub	ject Han	dler Assign	ned By	Completed On	Created On	Done
No results.									
No results.									

Your password will expire in 3 days. Click here to change it.

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying

To: assignments, Admin A

Fong, Andy-SY Cc:

9/12/2019 10:04:35 AM Sent:

Attachments: 9117 - AIG PRI 20190911110550.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards Lee Ying, Chin Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Advocates & Solicitors
 UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11 The Alexcier, Singapore 159929

Telephone: 6538 6250 Facsimile: 6538 1860

Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

AIG Asia Pacific Insurance Pte Ltd

Date

11th September 2019

Attention :

Motor Claims

From

Mr Stanley Bay / Miss Pauline Ong

(Hor, Yinrul)

Insurer of SMA 4975B

Our Ref.

SB/PO/Acc/2019-9117

Your Ref.

Facsimile:

6835-7416

No. of Pages :

7 (including this page)

IMMEDIATE ATTENTION

Dear Yin Rul,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SMN 1501L & SMA 4975B & SLV 9692K AT OPEN SPACE CARPARK OF BLK 271 BUKIT BATOK EAST AVENUE 4 ON 09-09-2019 @ 4.10 P.M.

We act for the owner of vehicle registration no. SMN 1501L.

We are instructed by our client to notify you of the above accident involving our client's said vehicle and your insured's vehicle registration no. SMA 4975B driven at the material time. A copy of our client's motor accident report is enclosed herein.

As a result of the above accident, our client's said vehicle was damaged. Before our client proceeds to repair her damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair her said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our client's right nor shall it be deemed as a waiver of any of her rights, as such our client's rights are expressly reserved.

Yours faithfully

Mr Stanley Bay / Miss Pauline Ong

Enc

Details of Repairers

M.S. Panel Beating Workshop 2 Kaki Bukit Ave 2

#02-17 Singapore 417921

Tel No.: 9143-6036 (Mr. Loh); Fax No. 6747-8306

> Back to OneMotoring

Enquire	PARI	F/COE	Rebate	for Registered	Vehicle
---------	------	-------	--------	----------------	---------

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: ` Vehicle Details	487H
Vehicle No.:	SMN1501L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Purple
Manufacturing Year:	2019
Engine No.:	L15B5570741
Chassis No.:	RU11320729
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$24,039.00
Original Registration Date:	26 Jul 2019
First Registration Date:	26 Jul 2019
Transfer Count:	0 1
Actual ARF Paid: Intended PARF Rebate Details	\$15,655.00 × 50% = \$78275
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2029
PARF Rebate Amount: Intended COE Rebate Details	\$11,741.00
COE Expiry Date:	25 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$27,000.00
COE Rebate Amount:	\$26,615.00
Total Rebate Amount:	\$38,356.00

The information contained herein is correct as at 16 Sep 2019

Remains: 9 years 10 months: 16 days (118.5)

Depri: \$8000 (yearly \$666.66 (months))

118 5x \$666.66 = \$78999.21

\$78999.21 + \$7827.5 = \$86826.71

LOQIII Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS. We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login

Mercedes R300L. 7 Seater MPV. Ideal For COE Renewal.



Direct Owner



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

▼ 20 results/page

29 vehicles

Post an Ad

Honda Vezel 1.5a x

Model

Ways of Selling

Advanced Search:

Honda Vezel 1.5a x

Any

2019

Eng Cap

Any

Mileage

Any Available

Search Selection

Available

Honda Vezel 1.5A X Honda

\$71,777

\$6,770 /yr

Depreciation

27-Feb-2019

1,496 cc

SUV

PERMIUNIAN.

2019 Model Vezel, Vitas Ready, Deliver Immediate, High Accessories With GPS, IRoad Recording Camera, High Trade In Your Existing Car, 5 Years Or 130,000Km Warranty, Flexible Loan Package Up To 7 To 10 Years, GST Included, Call Us For More Details.

Veh Type

HTS Motor

Posted: 14-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$85,777

\$7,860 /yr

04-Sep-2019

1.496 cc

5 km

SUV Available

New Model Vezel, Vitas Ready, Fast Deliver, High Accessories With, IRoad Recording Camera, 3M Tinted, High Trade In Your Existing Car, 5 Years Or 130,000Km Warranty, Flexible Loan Package Up To 95% Available 7 To 10 Years, GST Included, Call Us For More Details.

Posted: 14-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda Vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X Honda Sensing

\$85,800

\$8,050 /yr

20-Jun-2019

1.496 cc

10 km

SUV

Available

PREMIUM AD

5 Years Warranty! 3 x Free Servicing! 2019 Latest Model! VITAS Ready Stock Of White, Flexible Loan And High Trade In. Dynamic And Responsive, Rugged And Aggressive Styling, Advanced Technology. Call Us Today!

Shuang Hup Credit

Posted: 12-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$88,988

\$8,680 /yr

20-Feb-2019

1,496 cc

51 km

SUV

Available

FREMIUM AD

High Trade In Your Existing Car, Warranty 5 Years Or 130,000km. Loan Available 8 Years, Call Us For More Details. Balloon Scheme Loan Available Too!

Vincar Pte Ltd

Posted: 11-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda Vezel, vezel, Used Honda



Strut / Stabilizer Bar

Honda Brio 1.2 (2011) Strut/ Stabilizer Bars

More info about this product



Honda Vezel 1.5A X

\$85,800

\$8,380 /vr

15-Jan-2019

1.496 cc

SUV

Available

2019 New Facelifted Honda Vezel, Low Fuel Consumption. 5 Years Or 130000km Warranty, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. View To Appreciate. Call Our Friendly Sales Executive For Viewing.

Posted: 09-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$82,800

\$7,890 /yr

17-Apr-2019

1.496 cc

30 km

SUV

Available

5 Years / 130,000km Comprehensive Warranty By Reputable Workshop, Free Servicing, Attractive Bank / In-House Interest Rate! Low Fuel Consumption, Low Maintenance. Please Call To Arrange For Viewing.

Posted: 08-Sep-2019 Tags: 2019 Honda Vezel, 2019 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

是的可以是这个人的。	ACCIDENT STATEMENT					
Date Of Report	10/09/2019 12:35					
Date Of Accident	09/09/2019 16:10					
Exact Location Of Accident	271 BUKIT BATOK EAST AVE 4					
Country/State of Loss	SINGAPORE					
	DETAILS OF OWN VEHICLE					
Vehicle Registration Number	SMN1501L					
Insured/Policyholder						
Name Of Registered Owner	AW HWEE LEE					
NRIC No	S7708487H					
Email Address	TAS_ASHLEY@HOTMAIL.COM					
Mobile Phone No	(LOCAL) +65-96755918					
Alternative Phone No	OTHERS-96755918					

Vehicle Particulars

 Manufacturer
 HONDA

 Model
 VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number GA486754

Cover Note Number

Driver

 Name of Driver
 AW HWEE LEE

 NRIC No
 \$7708487H

 Date Of Birth
 30/03/1977

 Occupation
 OUTDOOR

 Date Of Driving Pass
 08/10/1999

Driving Experience 19 YEARS AND 11 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96755918

Fax Number

Contact Number OTHERS-96755918

EMail Address TAS_ASHLEY@HOTMAIL.COM

Address

191A RIVERVALE DRIVE #04-916

Postcode

541191

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?
Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-6659999 - FAX NO: 66655793

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SMA4975B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

VEHICLE B

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 15

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLV9692K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE HIRE

Name of Driver

VEHICLE C

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my daims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my daims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (d) any Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Dece 5 Time: 10 9 2019

1208 HER .

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

NRIC/FIN No.: AY

Accident Sketch Plan

SKETCH PLAN	
SKETCH PLAN	Vehicle A - SMAI 15011 B - SMA 49751 C - SLV 96921
B B	Vehicle Motorcycle
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
Vehiole	
Reter to police report	4 .
-	
DECLARATION I/We declare the foregoing perticulars are true in every respect. Please be advised that your learner may have a fourteen (1.4) days clause whereby the clefm against on from the day of occurrence. Kindly check your policy for more details.	l
Policyholder's Signature Date & Time: 10 4 20 Date & Time: Date & Time: 10 4 20 Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FB4 No.:

Annex D

NOTICE OF REPORTING

This is to confirm that <u>Aw Hwee Lee (A1)</u>, NRIC/FIN: <u>S7708487H</u>, has reported to the Police a traffic accident. The traffic accident does not consist of the below following criteria:

- i) Involvement with foreign vehicle
- ii) Involvement with Pedestrian/Cyclist
- iii) Involving parties obtained more then 3 days of Medical Leave
- iv) Government property damage
- v) Hit and Run Accident

Incident happened on 09/09/2019 at 1610hrs, at open space carpark in front of Blk 271 Bukit Batok East Avenue 4.

Involving the following vehicles:

- VI) SMN1501L
- V2) SLV9692K
- V3) SMA4975B

Brief Facts:

On 09/09/2019 at about 1610hrs A1 was inside a hair salon nearby when she heard a loud collision sound. A1 went out to make a check and discovered that V3's front left had hit onto the front right of V1. Due to the impact V1 move and hit onto V2. V1 was parked in parking lot no: 407 beside V2 who was parking in lot no: 408.

If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SSSgt T03316 Shaniza

Date: 09/09/2019 Time: 1920hrs

S/D Ref: 136

Police Post/Unit: Bukit Batok NPC

WIL 21 BUKET BATOK EAST AVE .
SINGAPORE 659840

TEL : 66659999

\$1261

1001	991886	Frt Number Plate		CON	AC	Qu	1	N	C	INC	Vehicle No: SMN	100	L	
1002	1991887	live Ni		MB.	7		by	_	_			C	ОМ	ACQ
1003	1221007	Hert Number Dist. O. 11		H	7		360	_	72	004011	Fuse Box			LUIV
1001	1 331700	I'm Rupman	-	379	1		1		_	000000	Relay Box			-
1005	992341	Frt Bunner Cline	é	BUL	1		5	_	74	995053	Wiper Washer Tunk		-	+
1006	1 331372	Frt Bumper Bracket		ec	/		741	())	75	993052	Wiper Washer Tank Motor			-
1007	1991462	Frt Bumner Side Date:	=	-80	-	5	-	10	76	000170	Alternator Assy		\neg	_
1008	1 //1433	Pri Halmana D. 1 c		MA	/	1	/	10	77	330100	Alternator Belt		1	+
1009	221210	IFI Bumper Dages	(70	2		\$300	10	79	002660	Power Steering Pump		-	_
1010	801166	Frt Bumpag C.						-	70	992009	Power Steering Belt		-	+
1011	991427	Frt Bumper Protector						_	19 3	994431	Power Steering Cooler Diag	-	-	+
1012						_		10		112036	Power Steering Hora	-	-	-
1013	1 771 363	Firt Dummer O III			-			10:	31	010050	IABS Pump Control Unit	-	+	
1011	1 2213011	Firt Daniel A.	C	ra		\leq	\$150	100	16 .	174066	Brake Mactau D.	-	+	-
						-	4120	103	, ,	20403	Brake Booster Puny Asset	_	+	+
			0	ra	7	-	3500	108		21002	Engine Ton Cover	-	-	-
			3	C		-	200	1,08	3	11016	Engine Under Cover	-	+	-
1018	991355	Frt RH Bumper Fog Lamp Cover	0	V	1	/	3	108	0 1.5	90946	Engine Mounting	-	+	-
1019	995079	Frt LH Bumper Fog Lamp Cover	BVA	spin,	7	-	5320	108	/ / >	90949	Engine Mounting For	-	-	-
1020	995080	Fet PLI Dumper Fog Lamp	C	ner	1	1			0 1. 5	20220	Engine Mountly 177			
1021	991793	Frt Colle		18	1	9	3600	108	2 3	90952	Engine Mounting PU	-	+	7
1022	1861166	Tet Cattle Day		10	2	-	9400	109	0 / 2	30321	Engine Mounting Page	-	-	+
1023	771/991	ert Ceille Cl	_	ec	1	2		109	1 9	92234	Gear Box Mounting	-	+	+
			3	C	1	-	55	109	4 9	91320	Fit LH Chassis Mamber	-	+	-
1023	22201311	ort Suppose Dead			+	1		109	2. 1 9:	91520	Frt RH Charrie Mant	-	-	-
1020	222022	rt Support Per 17	DY	2	1	4	530	109	• 9:	1 82706	Frt Vertical Come No.	-	+	-
1027	992416 1	forn			1		91	109	1 3:	1002	PILLOWER Crose Man	. 00	5	
1028	9912771	Il Bruce De I	9		1		80	.109	1 3	2010	ritth Fender	BT		
1067 13	33317 (11	11 11 11						1098		5072	Frt LH Fender Inner Panel	DD		-
			CU	AI-	1		(42000	1099	7 33	314/.	Fit LH Fender I ama	100	+	\vdash
			- a	4-	7	1	37000		עב ו	314X II	Fet I LI Eandan P	- Cri	1>	<
	12000311	R R Side Lame		•		\neg		1101	1 33	1740 []	Frt I.H Fender Inner OUT 11	T	1-	\vdash
037 13	77024811	Onnet			1					211211	FILL I Mudflus	1	+-	-
034 -9	991328 B	unner Emble	B	0.		5	000	1103	99	4025	Frt LH Wheel Rim	CU	1	
033 3	2028/1B	onnet Look	-			-		1104	99	5065 1	Frt LH Rim Cover		1	\vdash
030 0	90285 B	onnet Inculator	30	1	/		1100	-1105	99	5071 6	rt RH Fender		\top	
03/19	19027 (IB	CONTRACT PET	un	7	1		14 G	1106	99	1739 F	rt RH Fender Inner Panel	Buc	/	
A20 3	YUZO I IB	Onnet Dames	BA	-15	X		190							
040 0	90303 B	onnet Rubber onnet Cable	- 67	-	+	3	100	1108	1 22	1752 IF	rt PLY Ennel P	-		/
041 9	90311 D	onnet Cable	_	+	╁	-	- 1	1102	1 33	1740 IF	IT RM Fender Invited Live	Cra		
042 9	90119 A	r Con Condenser	_	+-	╁	-	- 1		1 001	100411	II KIH MANGHIAN .		\vdash	
043 90	90122 A	r Con Fan Assy	. B+	1	1	0.0	-0	1111	992	087 F	rt RH Wheel Dim	-	-	_
044 99	90134 A	Con Pan Assy		-	-	1.	10.	1112	1 994	1025 IF	rt RH Rim Course	-	\vdash	
045 99	90118 AI	r Con Suction Pipe (Low Pressure) r Con Suction Hose	1	77	+-	-	L	1113	995	065 IF	rt RH Tyre	-	-	_
146 99	00133 A	Con Suction Flose	1	+	\vdash	-		1114	992	093 Fr	rt Windsorenn Ol-	-	-	-
147 99	00114 Ai	r Con Discharge Pipe (High Pressure) Con Discharge Hose		7	-	┨.	1	1112	992	117 Fr	t Windson D. II	-	+	-
48 99	0140 AL	Con Discharge Hose	-	1	1	1	-		377	108 IFr	Windscreen Mould's	1	+	-
77 1 77	OTHER LAST	C	nec	/		90			112	039 ILL	Windscreen Cantant	1-	+	-
				1	-	10	-	1110	271	11916	P Denokat		-	-
						1	1	120	002	140 ER	Unit Unit		+	
14 1 773	3074 IRm	inter	-		-	1		121	9921	42 Fr	Wiper Arm		1	
3 992	2738 Rad	inta-Cl II	CIA	1			50	122	9950	45 W	Wiper Blade			
1 222	6/42 [[697]	in hor E- 4	Br			213	_	_	9911	26 121	per Panel Garnish ewall Panel			
9 1 222	14911691	into- F							9907	53 D	shboard Assy			
M 1 77/2	A D& IRud	ning IV. on					Ti	125	9922	82 01	ove Box Cover			
1 222	15 / Radi	alor Moco Patte					Ti	126	0022	81 61	ve Box Cover			
0 2772	741 [ICadi	ator Evnancia. 15. 1					Ti	127	0011	02 010	ove Box Compartment		-	
					-		1.	121	9944	83 Ste	erine Wheel Aleban		+	-
0 9900	070 Air (Yanna 1	cra	1	1	91	20 1	20	2344	02 12 (C)	ering Wheel Airban Com		-	-
1 3300	036 Air C	Innone II.	多℃	1		350	() 	-	201	47 Das	nooard Airbae		1	-1
9900	089 Air C	leaner Paramet							2000	DU Das	hboard Airbag Sensor		-	-
2211	121111 6	Viouet Manife LL				1	1	21 1 3	77002	29 I Airt	ong Control (tale		1-	-
13311	13 Frt F	Viguet Mr. 1011 a	ΔI	1	*	7/16	6 11	33 0	0105	n ral	Driver Seat		1	
	A TELL	Climitet Name of the transfer	_V1	M	7	Y	11	34 9	0100	o Frt I	RH Seat Belt Assy	-	-	1
9917	14 Front	Exhaust Pipe		1		Λ	111	35 0	9189	y Frt F	Passenger Sent		+	1
9902	19 Batter	and the		1	V	/	\ 	36 0	2218	Z Frt L	H Seat Belt Assy.		1-	-
9902	24 Batter	y Cover					1	1	3024	7 Stick	cer ·		1	1
9902.	23 Batter	v Bracket					10	-			n lave		Ţ.:-	7
99023	29 Batter	v Trav		1	del	20	W			The	velarc		1	1
		THE STATE OF THE PARTY AND THE	3	43	11	(-			-			1-	1
			2	-	7	١.	l-			1			1	1

(01)Bont (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Seratched (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

(1)Replace (√) (2)Repnir (X) (1)Check (?) (4)Not Consistent (NC)

(12)Miss	man William	m (14)Unconfirmed (15)Not Working			
	rcarriage				
NAC		Item	CON	٨C	Qfy
1372		Frt LH Shock Absorber	Bt	/	
1373		Frt LH Shock Absorber Mounting			
1374		Frt LH Coil Spring			
1375		Frt LH Knuckle Arm	8+	R	/
1376	995199	Frt LH Knuckle Arm Bearing	NEE	/	-
1377		Frt LH Lower Arm	8+	/	
1378	995169	Frt LH Upper Arm	-		
1379	995183	Frt LH Tie Rod			/
1380	995143	Frt LH Drive Shaft	Br	1	
1381	990661	Frt LH Control Arm			4
1382	992062	Frt LH Trailing Arm	A.	2	3
1383		Frt LH Leaf Spring	1	-	1
1384	991293	Frt LH Brake Disc Rotor			+
1385	991281	Frt LH Brake Caliper			V
1386	991292	Frt LH Brake Pipe	-		
1387	991287	Frt LH Brake Hose		10	Jos.
1388	991295	Frt LH Brake Sensor Wire	7	1	4
1389		Frt Stay Bar Bracket		1	1
		Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392		Frt Sub Frame			
		Frt Sub Frame Mounting	-	_	-
1394	991217	Frt Anti Roll Bar	-		-
		Frt Anti Roll Bar Linkage	_	-	_
1396	990887	Engine Block	_	-	_
		Engine Block Gasket	-	-	-
1398	990972	Engine Oil Sump		-	_
1399		Engine Oil	_	-	-
1400		Gear Box Assy		-	-
1401		Gear Box Gasket	_		_
1402		Gear Box Oil Sump	_		-
1403		Gear Oil		_	-
The state of the s		Centre Exhaust Pipe Assy		-	-
1294	990532	Centre Exhaust Mounting	-	-	-
1404	001134	Floor Panel			_
		Rear LH Shock Absorber			_
1406	003723	Rear LH Shock Absorber Mounting		_	
	003170	Rear LH Coil Spring		_	_
1408	993550	Rear LH Knuckle Arm	-	-	-
1409	993551	Rear LH Knuckle Arm Bearing		-	_
1410	993597	Rear LH Lower Arm			
1411		Rear LH Upper Arm		-	
1412	995161	Rear LE Drive Shaft		-	
1413		Rear LH Control Arm		-	_
1414		Rear LH Trailing Arm	-		-
		Rear LH Leaf Spring		-	_
1416	002041	Rear LH Brake Disc Rotor			
1417					
1417	990434	Rear LH Brake Caliper Assy Rear LH Brake Pipe			
		Rear LH Brake Pipe		_	
		Rear Sub Frame	-		
1421		Rear Sub Frame Mounting			_
-		Rear Anti Roll Bar			
		Rear Anti Roll Bar Rear Anti Roll Bar Linkage			
		Axle Beam	-		
_		With the County of the County			
1425		Rear Axle Panhard Rod			
1426		Differential Assy			
1427	972/06	Propeller Shaft			

		Vehicle No: SMW 15011			
NAC		Item	CON	٨C	Qty
1428		Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
		Frt RH Knuckle Arm		- 10	
0432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
		Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
		Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring		-	
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose		77	
		Frt RH Brake Sensor Wire			
		Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			-
		Rear RH Control Arm			
		Rear RH Trailing Arm		5.5	
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
		Rear RH Brake Hose	-		
			1		
			1	_	-
- 1			-	_	-
			-	_	-
			+		-
					-
		•			
				_	
			1-		-
			+		-
			1		-
			1	_	_
			1	_	-
			-	_	_
			-		_
	7		-		
			-		

No of Items:	Assessor:
--------------	-----------

$...\mathsf{CLAIM}\ \mathbf{SUBFOLDER}...(\mathsf{Pending}\ \mathsf{for}\ \mathsf{Survey}\ \mathsf{Report})$

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted		Ins Auth'ed	5	Status	
Main	11 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Es	timates	S\$0	.00 ew Rpt			Pending for Report Cancel Case	Survey
	Main	R	eference		laim Det	ails		Document	s		Show All
CLAIM S	UBFOLDER DE	TAILS					[Created	by adjuster]			
insured:	WONG A	HLUI, ID: S0327	7338E								
Main Claimant:	AH HWEE	LEE, ID: S770	3487H								
Vehicle Re No.:	Reg. SMN1501L Date of Loss: 09/09/2019 16:00 - :59 [1 Months and 14 Days From LTA Reg Date (N					lan Yr)]					
Claim Typ	pe: TP / 3423980221SG Policy/Cover Note No.:										
Vehicle Re No. (Insured):	SMA4975	В			Policy No (Claimar						
					Excess:						
Repairer:	M.s Pane	Beating Works	nop (HQ) 2 KAKI B	UKIT AVE 6	, # 02 . 1	AUT	ОНИВ @ КА	KI BUKIT, 41792	1 Kak	Bukit - Tel:	
Handling Insurer:	AIG Asia WZ.Tan@a		e Pte. Ltd. (Expre	ss) - Tel: 6	5-6419-30	000	. [Handled b	y Tan, Bennie-V	VZ - 6	419 1718] B	ennie-
Adjuster:	23/09/2		Ltd (HQ) - Tel: 62	256-3561	[Handled	by P	ARASURAM	1 SHANMUGAM]	[F	inal Rpt d	ue
ASSOCIA	ATED MAIL RE	CEIVED						Vi	ew All	Compos	e Case Mail
• AIG_S	G (13/09/2019)	: Request To Up	load TP GIA Repor	rt							
ALL ASS	OCIATED TAS	SKS⊟				,	View All	Search Tasks	Create	New Task	Complete
Due Da	te Priority	Type Task	Group Subject	ct Hand	lor A		ed By	Completed On		Created On	Done

Merimen e-Claims Page 1 of 5

Claim Documents

Pho	otos/Images		3 per p	age 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	25/09/19 09:59	General View	0	Load JPG	V
2	25/09/19 09:59	General View	0	Load JPG	V
3	25/09/19 09:59	General View	0	Load JPG	V
4	25/09/19 09:59	General View	6	Load JPG	V
5	25/09/19 09:59	General View	0	Load JPG	V
6	25/09/19 09:59	General View	6	Load JPG	V
7	25/09/19 09:59	General View	6	Load JPG	V
8	25/09/19 09:59	General View	0	Load JPG	V
9	25/09/19 09:59	General View	0	Load JPG	V
10	25/09/19 09:59	General View	0	Load JPG	V
11	25/09/19 09:59	General View	0	Load JPG	V
12	25/09/19 09:59	General View	0	Load JPG	V
13	25/09/19 09:59	General View	0	Load JPG	V
14	25/09/19 09:59	General View	0	Load JPG	V
15	25/09/19 09:59	General View	0	Load JPG	V
16	25/09/19 09:59	General View	0	Load JPG	V
17	25/09/19 09:59	General View	0	Load JPG	V
18	25/09/19 09:59	General View	0	Load JPG	V
19	25/09/19 09:59	General View	0	Load JPG	V
20	25/09/19 09:59	General View	0	Load JPG	V
21	25/09/19 09:59	General View	0	Load JPG	V
22	25/09/19 09:59	General View	0	Load JPG	<u>Z</u>
23	25/09/19 09:59	General View	0	Load JPG	V
24	25/09/19 09:59	General View	0	Load JPG	N N
25	25/09/19 09:59	General View	0	Load JPG	Ø.
26	problem upon de sinare.	General View			V
	25/09/19 09:59		0	Load JPG	
27	25/09/19 09:59	General View	0	Load JPG	V
28	25/09/19 09:59	General View	0	Load JPG	
29	25/09/19 09:59	General View	0	Load JPG	
30	25/09/19 09:59	General View	0	Load JPG	V
31	25/09/19 09:59	General View	0	Load JPG	V
32	25/09/19 09:59	General View	0	Load JPG	Z
33	25/09/19 09:59	General View	0	Load JPG	M
34	25/09/19 09:59	General View		Load JPG	V
35	25/09/19 09:59	General View	0	Load JPG	V
36	25/09/19 09:59	General View	6	Load JPG	Z
37	25/09/19 09:59	General View	0	Load JPG	V
38	25/09/19 09:59	General View	0	Load JPG	Ø
39	25/09/19 09:59	General View	0	Load JPG	V
40	25/09/19 09:59	General View	0	Load JPG	V
41	25/09/19 09:59	General View	0	Load JPG	V
42	25/09/19 09:59	General View	0	Load JPG	V
43	25/09/19 09:59	General View	0	Load JPG	V

			- I - I		V
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Thumbnail Load JPG	_
14	25/09/19 09:59	General View		Vi Vivide	
15	25/09/19 09:59	General View	0	Load JPG	V
6	25/09/19 09:59	General View	0	Load JPG	V
7	25/09/19 09:59	General View	0	Load JPG	V
8	25/09/19 09:59	General View	0	Load JPG	V
19	25/09/19 09:59	General View	0	Load JPG	V
0	25/09/19 09:59	General View	0	Load JPG	V
1	25/09/19 09:59	General View	0	Load JPG	V
52	25/09/19 09:59	General View	0	Load JPG	2
3	25/09/19 09:59	General View	6	Load JPG	V
54	25/09/19 09:59	General View	0	Load JPG	V
55	25/09/19 09:59	General View	6	Load JPG	V
56	25/09/19 09:59	General View	0	Load JPG	V
57	25/09/19 09:59	General View	0	Load JPG	V
58	25/09/19 09:59	General View	0	Load JPG	V
59		General View	0	Load JPG	V
	25/09/19 09:59	Vaccinia (Calada (Cala	0	Load JPG	Z
50	25/09/19 09:59	General View	0	Load JPG	<u> </u>
51	25/09/19 09:59	General View		Post Name (<u>N</u>
52	25/09/19 09:59	General View	0	Load JPG	<u> </u>
53	25/09/19 09:59	General View	0	Load JPG	-
54	25/09/19 09:59	General View	0	Load JPG	5
55	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	₽
56	25/09/19 10:00	Photographs of Damaged Parts	6	Load JPG	₽
57	25/09/19 10:00	Photographs of Damaged Parts	63	Load JPG	2
58	25/09/19 10:00	Photographs of Damaged Parts	•	Load JPG	V
59	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
70	25/09/19 10:00	Photographs of Damaged Parts	©	Load JPG	V
71	25/09/19 10:00	Photographs of Damaged Parts	63	Load JPG	2
72	25/09/19 10:00	Photographs of Damaged Parts	6	Load JPG	2
73	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
74	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
75	25/09/19 10:00	Photographs of Damaged Parts	6	Load JPG	V
76	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
77	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
		Photographs of Damaged Parts	0	Load JPG	2
78	25/09/19 10:00	Control of the Contro	0	Load JPG	2
79	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	Z
80	25/09/19 10:00	Photographs of Damaged Parts			<u>~</u>
81	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	-
82	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	_ E
83	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
84	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
85	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	<u> </u>
86	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	<u> </u>
87	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	E
88	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
89	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	8
90	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	2
91	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	5
92	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
93	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
94	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
_	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
95			0	Load JPG	6
96	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6
97	25/09/19 10:00	Photographs of Damaged Parts		100000000000000000000000000000000000000	_
98	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	6

Pho	tos/Images		3 per page		V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbi		rin
100	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji	-	V
101	25/09/19 10:00	Photographs of Damaged Parts	1 Load 3	-	V
102	25/09/19 10:00	Photographs of Damaged Parts	61 Load Ji	G E	Y
103	25/09/19 10:00	Photographs of Damaged Parts	€ Load Ji	G E	V
104	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	G E	V
105	25/09/19 10:00	Photographs of Damaged Parts	■ Load Ji	PG F	V
106	25/09/19 10:00	Photographs of Damaged Parts	■ Load Ji	G F	V
107	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	G F	V
108	25/09/19 10:00	Photographs of Damaged Parts	Load J	PG F	V
109	25/09/19 10:00	Photographs of Damaged Parts	Load Ji	PG F	V
110	25/09/19 10:00	Photographs of Damaged Parts	■ Load JI		V
111	25/09/19 10:00	Photographs of Damaged Parts	■ Load J	PG [V
112	25/09/19 10:00	Photographs of Damaged Parts	■ Load 3		V
113	25/09/19 10:00	Photographs of Damaged Parts	① Load Ji		V
114	25/09/19 10:00	Photographs of Damaged Parts	① Load Ji		V
					V
115	25/09/19 10:00	Photographs of Damaged Parts			
116	25/09/19 10:00	Photographs of Damaged Parts	① Load J	_	V
117	25/09/19 10:00	Photographs of Damaged Parts	① Load J		V
118	25/09/19 10:00	Photographs of Damaged Parts	1 Load J		V
119	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji	_	V
120	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG	V
121	25/09/19 10:00	Photographs of Damaged Parts	■ Load J	PG	V
122	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG	V
23	25/09/19 10:00	Photographs of Damaged Parts	■ Load JI	PG F	V
124	25/09/19 10:00	Photographs of Damaged Parts	6 Load J	PG F	V
125	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG F	V
126	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG F	V
127	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG F	V
128	25/09/19 10:00	Photographs of Damaged Parts	€ Load J	PG F	V
129	25/09/19 10:00	Photographs of Damaged Parts	€ Load J		V
130	25/09/19 10:00	Photographs of Damaged Parts	① Load J		V
131	25/09/19 10:00	Photographs of Damaged Parts	① Load Ji		V
132	25/09/19 10:00	Photographs of Damaged Parts	① Load Ji	_	V
133	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji	-	V
				_	_
134	25/09/19 10:00	Photographs of Damaged Parts	① Load 3		2
135	25/09/19 10:00	Photographs of Damaged Parts	1 Load J		V
136	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji		V
137	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	_	V
138	25/09/19 10:00	Photographs of Damaged Parts	■ Load Ji	_	V
39	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji		V
40	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji		V
41	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	G F	¥
142	25/09/19 10:00	Photographs of Damaged Parts	€ Load Ji	PG	V
143	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	G F	V
144	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG F	V
145	25/09/19 10:00	Photographs of Damaged Parts	€ Load J	PG F	V
146	25/09/19 10:00	Photographs of Damaged Parts	Load 3	_	V
147	25/09/19 10:00	Photographs of Damaged Parts	■ Load J	-	V
48	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji		V
49	25/09/19 10:00	Photographs of Damaged Parts	1 Load Ji	_	V
50	500 000 000 000 000	Photographs of Damaged Parts Photographs of Damaged Parts	1 Load 3		V
			1 Load J		V
51	25/09/19 10:00	Photographs of Damaged Parts			_
152		Photographs of Damaged Parts	① Load J		V
153		Photographs of Damaged Parts	① Load Ji		V
154	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	_	V
155	25/09/19 10:00	Photographs of Damaged Parts	1 Load J	PG	¥

	tos/Images	LVV Auto Consultante Dto Ltd (HO)	3 per page	⊻ا ail P	Pri
56	Relabel/Reorder 25/09/19 10:00	LKK Auto Consultants Pte Ltd (HQ) Photographs of Damaged Parts	Load JP	_	V
57	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	V
	The state of the s	THE AVERAGE AND A STATE OF THE PROPERTY OF THE	1 Load JP	-	V
58	25/09/19 10:00	Photographs of Damaged Parts		1000	2
59	25/09/19 10:00	Photographs of Damaged Parts	€ Load JP		
60	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	-	2
61	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	2
62	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	2
63	25/09/19 10:00	Photographs of Damaged Parts	Load JP	G	-
64	25/09/19 10:00	Photographs of Damaged Parts	Load JP	G	5
65	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	5
66	25/09/19 10:00	Photographs of Damaged Parts	63 Load JP	G	E
67	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	5
68	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	5
69	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
70	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
71	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	-	5
72	25/09/19 10:00	Photographs of Damaged Parts Photographs of Damaged Parts	1 Load JP	-	6
	USVESSO SE	TOTAL OF THE STATE		-	-
73	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	-	E
74	25/09/19 10:00	Photographs of Damaged Parts	① Load JP		E
75	25/09/19 10:00	Photographs of Damaged Parts	€ Load JP	5.0	-
76	25/09/19 10:00	Photographs of Damaged Parts	€3 Load JP	G	E
77	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	E
78	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
79	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	E
30	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	Ę
31	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
82	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	[
33	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP		E
84	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	-	E
			1 Load JP	-	E
85	25/09/19 10:00	Photographs of Damaged Parts			_
86	25/09/19 10:00	Photographs of Damaged Parts	6 Load JP		-
87	25/09/19 10:00	Photographs of Damaged Parts	Load JP		E
88	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	E
89	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
90	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
91	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
92	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	[
3	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	I
94	25/09/19 10:00	Photographs of Damaged Parts	Load JP	G	E
5	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP		1
6	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP		-
7	25/09/19 10:00	Photographs of Damaged Parts Photographs of Damaged Parts	1 Load JP	93	1
				-	-
8	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP		-
99	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	10	- [
00	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	_	-
)1	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	-
)2	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	1
3	25/09/19 10:00	Photographs of Damaged Parts	El Load JP	G	-
4	25/09/19 10:00	Photographs of Damaged Parts	1 Load JP	G	I
)5	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	E
16	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP	G	Į
7	25/09/19 10:00	Photographs of Damaged Parts	Load JP	G	1
18	25/09/19 10:00	Photographs of Damaged Parts	■ Load JP		-
		Photographs of Damaged Parts	1 Load JP	_	-
9	25/09/19 10:00	1 205 1150 750 - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The second secon		-
10	25/09/19 10:00	Photographs of Damaged Parts	Load JP		

Pho	tos/Images		3 per p	page 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
212	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
213	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
214	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
215	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
216	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
217	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
218	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
219	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	\mathbf{V}
220	25/09/19 10:00	Photographs of Damaged Parts	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/09/19 16:03	OI GIA REPORT	6	Load PDF	

Documents Checklist

	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19016196/FCD3E2

Date:

07/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Insured Vehicle No: SMA4975B

Vehicle No: Date of Loss:

SMN1501L 09/09/2019

Nature of Claim:

TP

Claim No: 3423980221SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMN1501L

Make & Model:

HONDA VEZEL, 1.5 (A) 26/07/2019 (Man. Year: 2019) Engine No:

L15B5570741

Reg. Date: Colour:

Purple

Chassis No: Odometer:

RU11320729 596 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side:

Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

12/09/2019

Date Inspected:

12/09/2019 Inspected At:

M.s Panel Beating Workshop (HQ) 2 KAKI BUKIT AVE 6, # 02 . 17

AUTOHUB @ KAKI BUKIT

Singapore 417921

Estimated Period of Repair:

6.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommend	led	l Par	ts
-----------	-----	-------	----

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
ĺ	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*-
	1		*FRT BUMPER	Buckled	0.00 F	*-
	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-
	1		*FRT BUMPER SIDE RETAINER	Cracked	0.00 F	*-
ì	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*-
	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*-
3	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*-
)	1		*FRT BUMPER SENSOR	Short Circuit	0.00 F	*-
0	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*-
1	1		*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*-
2	1		*FRT LH BUMPER FOG LAMP	Cracked	0.00 F	*-
3	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*_
4	1		*FRT GRILLE	Cracked	0.00 F	*-
5	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-
6	1		*FRT GRILLE CHROME MOULDING	Scratched	0.00 F	*-
7	1		*FRT SUPPORT PANEL	Dented	0.00 F	*-
8	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*-
9	1		*HORN	Short Circuit	0.00 F	*-
0	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*-
1	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*-
2	1		*BONNET	Buckled	0.00 F	*-
3	1		*BONNET LOCK	Short Circuit	0.00 F	*-
4	1		*BONNET INSULATOR	Cracked	0.00 F	*-
5	1		*BONNET HINGE	Bent	0.00 F	*-1
6	1		*BONNET DAMPER	Bent	0.00 F	*-
7	1		*AIR CON CONDENSER	Bent	0.00 F	*-1
8	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	* Check	0.00 F	*-
9	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	* Check	0.00 F	*-
0	1		*AIR CON LIQUID PIPE	* Check	0.00 F	*-
1	1		*RADIATOR	Cut	0.00 F	*-1
2	1		*RADIATOR COWLING	Broken	0.00 F	*-1
3	1		*AIR DUCT	Cracked	0.00 F	*-1
4	1		*AIR CLEANER ASSY	Broken	0.00 F	*-
5	1		*FRT LOWER CROSS MEMBER	Dented	0.00 F	*-1
6	1		*FRT LH FENDER	Bent	0.00 F	*- F
7	1		*FRT LH FENDER INNER PANEL	Dented	0.00 F	*- F
8	1		*FRT LH FENDER PROTECTOR	Cracked	0.00 F	*- F
9	1		*FRT LH WHEEL RIM	Cut	0.00 F	*-
0	1		*FRT RH FENDER	Buckled	0.00 F	*-1
1	1		*FRT RH FENDER PROTECTOR	Cracked		*-1
2	1		*FRT LH SHOCK ABSORBER	Bent	0.00 F	*- F
3			The state of the s		0.00 F	
3 4	1		*FRT LH KNUCKLE ARM	Repair	0.00 F	*- F
1275	1		*FRT LH KNUCKLE ARM BEARING	Necessary	0.00 F	*-F
5	1		*FRT LH DOWER ARM	Bent	0.00 F	*-1
6 -Em	nobles	nort	*FRT LH DRIVE SHAFT	Broken	0.00 F	*-1
-rra	nchise	рап.		Total Parts (S\$)	0.00	0.00

 $https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster\&fuseaction=g...\ \ 7/10/2019$

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >