

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE





SCENE





SCENE



SCENE



SCENE



SCENE



# Sau Hock Motor Services

Blk. 10, Ang Mo Kio Industrial Park 2A, AMK Autopoint, #02 -14, Singapore 568047

Fax : 6555 - 4006 / Email : sauhock@live.com

Date :- 6 / 5 / 2019

**COPY**

Motor Claims Department

India Int'l Ins Pte Ltd

BY FAX :-

Dear Sir,

6224 - 4174



**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION  
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF  
PRE-ACTION PROTOCOL FOR NIMA CASES**

**BY HAND**

We have been appointed by the Owner to repair his/her motor vehicle

No. SJT 69515 on 4-5-19 with another vehicle

No. SHA 78324 along B109, Bkt Purnei car-park

Please be informed that the said vehicle can be inspected at:-

**Contact**

**Workshop : Sau Hock Motor Services**

Blk. 10, AMK Industrial Park 2A (Ave, 5)

#02-14, AMK Autopoint, Singapore 568047

**Fax : 6555 - 4006**

**Contact**

**Person : Mr. Robert / 9109 - 8638**

**Email : sauhock@live.com**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Holiday. We will commence repairs thereafter without further reference to you.

Yours faithfully,

**Wu LLC - Law Firm - Tony Gn**

11.11.19

**CASH SALE/WORK ORDER**

**YS TOWING PTE LTD**

BLK 4015 ANG MO KIO INDUSTRIAL PARK A #01-502, SINGAPORE 569631

TEL: 6788 2233 / 6458 8480 FAX: 6288 8480

Company Registration No. 201628973E

24 hours Hotline : 9765 2992

No 20792

Date,

4/5/19

寶號

Messrs:

0214

車號

Vehicle No:

SST 67515

車型

Model No:

Hyundai

由

From:

PT Merah

到

To:

W/S

時間(日/夜)

Time (day/night):

其他

Others:

CASH \$:

50/

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed, ERP Fees, Car park fees, Cancellation of job and other miscellaneous charges incurred while performing the services shall be borne by the customer.

經手人

Authorised by:




收貨人

Received by:



## Repair for all kinds of Motor Vehicle

 **Cheque Payment Send To:** Blk 661C Edgedale Plains #03-648 Singapore 823661

**HP: 9109 8638 Fax: 6555 4006**

Date 24/05/19

Vehicle No. SD 1 69515

Goods sold are not returnable  
Goods received in good order and condition.

**TOTAL S\$**





# PAR Automotive Consultancy

Regn No: 53986974L

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel : 645 31173, Fax : 645 36131

Report No: 0278-19-SHM

24 May 2019

Tan Yao Guang  
Blk 440C Bukit Batok West Ave 8 #08-739  
Singapore 653440

**INVOICE No.** 0278-19-SHM

Vehicle No. SJT6951S

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$754.00
<b>Total amount payable</b>		<b><u>\$754.00</u></b>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



# PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173. Fax : 645 36131.

Regn No: 529869741.

Report No: 0278-19-SHM

24 May 2019

## ACCIDENT VEHICLE SURVEY REPORT

Tan Yao Guang  
Blk 440C Bukit Batok West Ave 8 #08-739  
Singapore 653440

### VEHICLE INFORMATION:

Vehicle Reg No.:	SJT6951S	Odometer:	138788km
Make & Model:	Hyundai Avante 1.6 AT	Colour:	Silver
Chassis number:	KMH DU41MAU896401	Date of accident:	04/05/2019
Year of Regn.:	27/10/2009	Date inspected:	05/05/2019
Repairer at:	Sau Hock Motor Services	Date inspected (After Repair):	13/05/2019
	Blk 10 Ang Mo Kio Ind Park 2A #02-14		
	AMK AutoPoint		
	Singapore 568047		

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Yokohama	5mm/Yokohama	195/60R15
Rear:	5mm/Yokohama	5mm/Yokohama	195/60R15

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## Parts and Labour Assessment

Report No: 0278-19-SHM

Vehicle No: SJT6951S

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Bonnet	1	repair	1,017.00	0.00 X SVC
Front bumper	1	squashed	432.00	432.00 /
Front bumper side retainer RH/LH	2	necessary	52.00	26 52.00 /
Front windscreen	1	cracked	650.00	650.00 X AN
Front windscreen moulding	1	necessary	60.00	60.00 X M
Front ABS sensor	1	reuse	227.00	0.00 N#
Front drive shaft assy	1	bent	936.00	936.00 X SVC
Front fender LH	1	buckled	402.00	402.00 /
Front fender bracket LH	1	bent	35.00	35.00 /
Front fender inner panel	1	repair	493.00	0.00
Front fender inner sponge	1	necessary	51.00	51.00 X SVC
Front headlamp LH	1	fractured	480.00	480.00 /
Front headlamp clip LH	3	necessary	19.50	19.50 /
Front headlamp lower bracket	1	bent	37.00	37.00 /
Front knuckle arm	1	distorted	363.00	363.00 /
Front knuckle arm bearing	1	dislodged	113.00	113.00 /
Front lower arm	1	bent	282.00	282.00 /
Front lower ball joint	1	dislodged	77.00	77.00 X SVC
Front power steering rack and pinion	1	bent	913.00	913.00 X SVC
Front power steering rack end	1	dislodged	112.00	112.00
Front power steering tie rod	1	bent	65.00	65.00
Front shock absorber	1	bent	194.00	194.00 X SVC
Front shock absorber top mounting	1	necessary	96.00	96.00 X SVC
Front stabilizer bar link	1	bent	69.00	69.00
Front fender "VVT" LH	1	necessary	20.00	20.00 /
Front fender inner shield LH	1	fractured	57.00	57.00 /
Front cross member assy	1	bent	1,510.80	1,510.80 X SVC
Subtotal before discount			8,763.30	7,026.30
Percentage discount 0% and 20%			0.00	1,405.26
Sub-total 1			8,763.30	5,621.04

2512.50  
20%  
2010

# PAR Automotive Consultancy

Annex A: Page 2  
Report No: 0278-19-SHM-SJT6951S

Front bumper clip - set	1	necessary	30.00	30.00
Front number plate c/w holder	1	necessary	50.00	40.00
Front sport rim	1	abraded	650.00	300 650.00
Front tyre	1	cut	450.00	450.00 1962
Front fender inner shield clip LH - set	1	necessary	30.00	30.00
Subtotal before discount			1,210.00	1,200.00
Percentage discount	0%	and 0%	0.00	0.00

596  
Sub-total 2 1,210.00 1,200.00  
Parts-total 9,973.30 6,821.04

## LABOUR

1. To straighten and panel beating bonnet, front door LH and front members. To remove and refit above parts.	1,000.00	500.00 400
2. To putty, re-spray painting and polish affected areas.	1,200.00	800.00 400
3. To check and rectify wiring system.	80.00	50.00 30
4. To remove and refit front suspension and steering system.	500.00	400.00 200
5. To conduct electronic wheel alignment.	200.00	150.00 60
6. To remove and refit front windscreen.	150.00	120.00 X 111
7. To rust proof affected areas.	120.00	60.00 40
Labour total	3,250.00	2,080.00
Parts & Labour total	13,223.30	8,901.04

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : \$7,100.00  
and the recommended number of working days for the repairs is : 6

B J Loi (I Eng. MIMI, AIRTE)  
Automotive Appraiser

3793.2  
20% : 3000  
5 Days

2010.00  
596.00  
1180.00  
3736.00  
202  
2988.80  
415-31000

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19008020/R1td3s2-1

64 CECIL STREET

#05-02 IOB BUILDING SINGAPORE 049711

Date : 20-09-2019



Code : III2

**1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)**

Insured Veh.	SHA 7832U	Veh. Inspected	SJT 6951S
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19050075	Excess (\$)	0.00
Assign From	MANIVEL PRIYADARSHINI	Assign Date	09/09/2019

**2. Vehicle Particulars & Condition**

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KMH DU41BMAU896401	Colour	SILVER
Odometer	138788	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	5 mm

**4. Description of Damages**

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

**5. General Information**

Accident Date	04/05/2019	Inspection Date	13/09/2019
Survey held at	SAU HOCK MOTOR SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5) #02-14 AMK AUTOPOINT SINGAPORE 568047.		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 6951S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BONNET	SERVICEABLE	1,017.00	-
1	FRONT BUMPER	REPLACED	432.00	432.00
2	FRONT BUMPER SIDE RETAINER RH/LH	REPLACED	52.00	26.00
1	FRONT WINDSCREEN	NOT NECESSARY	650.00	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	FRONT ABS SENSOR	NOT CHANGED	227.00	-
1	FRONT DRIVE SHAFT ASSY	SERVICEABLE	936.00	-
1	FRONT FENDER LH	REPLACED	402.00	402.00
1	FRONT FENDER BRACKET LH	REPLACED	35.00	35.00
1	FRONT FENDER INNER PANEL	REPAIRED SEE LABOUR	493.00	-
1	FRONT FENDER INNER SPONGE	SERVICEABLE	51.00	-
1	FRONT HEADLAMP LH	REPLACED	480.00	480.00
3	FRONT HEADLAMP CLIP LH	REPLACED	19.50	19.50
1	FRONT HEADLAMP LOWER BRACKET	REPLACED	37.00	37.00
1	FRONT KNUCKLE ARM	REPLACED	363.00	363.00
1	FRONT KNUCKLE ARM BEARING	REPLACED	113.00	113.00
1	FRONT LOWER ARM	REPLACED	282.00	282.00
1	FRONT LOWER BALL JOINT	SERVICEABLE	77.00	-
1	FRONT POWER STEERING RACK AND PINION	SERVICEABLE	913.00	-
1	FRONT POWER STEERING RACK END	REPLACED	112.00	112.00
1	FRONT POWER STEERING TIE ROD	REPLACED	65.00	65.00
1	FRONT SHOCK ABSORBER	SERVICEABLE	194.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	96.00	-
1	FRONT STABILIZER BAR LINK	REPLACED	69.00	69.00
1	FRONT FENDER "VVT" LH	REPLACED	20.00	20.00
1	FRONT FENDER INNER SHIELD LH	REPLACED	57.00	57.00
1	FRONT CROSS MEMBER ASSY	SERVICEABLE	1,510.80	-
	LESS 20% DISCOUNT		-	-502.50
			8,763.30	2,010.00

Report Ref No. CS3/III19008020/R1td3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	REPLACED	30.00	30.00
1	FRONT NUMBER PLATE C/W HOLDER (SN)	REPLACED	50.00	40.00
1	FRONT SPORT RIM (SN)	REPLACED	650.00	300.00
1	FRONT TYRE (SN)	REPLACED	450.00	196.00
1	SET FRONT FENDER INNER SHIELD CLIP LH (SN)	REPLACED	30.00	30.00
			1,210.00	596.00
	<b><u>LABOUR</u></b>			
	TO STRAIGHTEN AND PANEL BEATING BONNET, FRONT DOOR LH AND FRONT MEMBERS. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER PANEL.		1,000.00	400.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,200.00	400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO REMOVE AND REFIT FRONT SUSPENSION AND STEERING SYSTEM.		500.00	200.00
	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT.		200.00	60.00
	TO REMOVE AND REFIT FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	TO RUST PROOF AFFECTED AREAS.		120.00	40.00
			3,250.00	1,130.00
	<b>GRAND TOTAL</b>		<b>13,223.30</b>	<b>3,736.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PE-ACCIDENT CONDITION)</b>			<b>3,000.00</b>

Report Ref No. CS3/III19008020/R1td3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.