

ASS. REC. BY:

REF: CS/MSG 19016219/00f3

n2

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Irene Tan CK Ing of MSG Date/Time: 13.9.19 8.37a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 6759H

Insured:

SLN 9682G

at Workshop m/s

Autolub n Industrial

Tel:

67038691

of 19 Ubi Road 4

Policy No:

Claim No:

604724

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 13.9.19 8.57a.m

Person Contacted:

Elmur

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 6759H - X

SLN 9682G - X

16/9/19

Send preli revised via merimen

ISS. REC. BY:

REF: MS19

ASSIGNMENT

From:

Date:

13.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 6759H

at Workshop m/s Autolukon

of 19 ubi road 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2.30pm Owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mupl

Vehicle: IN / OUT

Date:

Person Contacted:

SLA 37950

Veh No:

SLA 6759H

Yr Regn:

3, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

LA /

Make:

Nissan Qashqai c.c 1197

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

90 689

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEAJ1141583549

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

2.5/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/9/19

D.O.A.

13/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

rear bumper black surface returned can't spray
Zeilung als crackle n/c

27/12/19

1189.02 confirmed with Elmer (Ref 3775.06, 769)

RECEIVED 27 DEC 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 27/12 - typist

Rep. Form:

merimen

Lump Sum / F.P. / C:

1189.02

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Wheel end (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

150

11

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 16 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLN9682G	Accident Date	: 01/09/2019
TP Vehicle No	: SLA6759H	Assignment Date	: 13/09/2019
Make	: NISSAN QASHQAI	Est. Duration of Repair	: 2
Date of Inspection	: 13/9/2019		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,964.08
Revised Amount	:S\$	1,251.60
Check Items (Estimated)	:S\$	378.16
Total	:S\$	1,629.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019		13 Sep 2019 08:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LIM MENG KEONG , ID: S7024886G, Tel: +6598365994, Email: NOEMAIL			[Created by insurer]
Main Claimant:	CHOO SENG YONG , ID: S6807766D			
Vehicle Reg. No.:	SLA6759H	Date of Loss:	01/09/2019 14:00 - :59 [41 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 604724	Policy/Cover Note No.:	80469640 (Comprehensive) Coverage: 23/05/2019 - 22/05/2020	
Vehicle Reg. No. (Insured):	SLN9682G	Policy No. (Claimant):		
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:			Excess:
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/09/2019]			
Driver/Custodian (Insured):	LIM MENG KEONG (49 / Male), NRIC: S7024886G, Tel: +6598365994 Email: NOEMAIL			
Adj Asg. Remarks:	Survey appt 13/09/19, 2.30pm. Owner waiting. on WP. Please contact us ASAP if you cannot attend this assignment. Liab: 100%. Contact: Elmer Alfonso @ 6703 8691.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	766D
Vehicle Details	
Vehicle No.:	SLA6759H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	HRA2233385A
Chassis No.:	SJNFEAJ11U1583549
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,454.00
Original Registration Date:	11 Mar 2016
First Registration Date:	11 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$13,454.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2026
PARF Rebate Amount:	\$10,090.00
Intended COE Rebate Details	
COE Expiry Date:	10 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$27,860.00
Total Rebate Amount:	\$37,950.00

The information contained herein is correct as at 16 Sep 2019

OK

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9565 FAX: 6346 7422

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0463/19

DATE : 02-SEP-2019

MS16 INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY

#24-01 HONG LEOH BUILDING

S(40561)

TEL : 68277660

FAX : 62257402

ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : CHOO SENG YONG

ADDRESS : BLK 233 COMPASSVALE WALK

#05-474

S(540233)

TELEPHONE NO : 97720261

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : D19MTPV01003510

VEHICLE NO : SLA6759H

MODEL CODE : FRLA8ZJ11UEA-A--

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2233385A

CHASSIS NO : SJNFEAJ11U1683549

MILEAGE : 90123 KM

DATE IN : 02/09/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/09/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Not Arthur
16/9/19
Take the responsibility -
2 day -
13/9/19

- 9645 0084 elmer@tanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA6759H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1. 22/001	LABOR CHARGES TO REPAIR RR END PANEL & BOTH REAR RENDER, RENEW RR BUMPER	1960.00	250
2. 22/002	CHARGES TO SPRAY PAINTING SAME	1200.00	200
3. 22/003	RENEW REVERSE SENSOR	110.00	✓
4. 22/004	SUPPLY RR LICENSE PLATE		
5. 22/005	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	✓
	TOTAL LABOUR CHARGES	3318.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA6759N

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	LH REFLECTOR RR BUMPER	26565-JJ90A 11	61.90	X
2	RH REFLECTOR RR BUMPER	26560-JJ90A 11	61.90	X
3	ORNAMENT-BACK DOOR DASHQAT	90892-4EA0A 11	94.40	X
4	EMBLEM-REAR NISSAN	90890-4EA0A 11	64.90	X
5	TOW HOOK COVER RR BUMPER	85071-4EA0A 11	18.80	X
6	LH STAY RR BUMPER	H5211-4EAMA 11	141.00	X
7	RH STAY RR BUMPER	H5210-4EAMA 11	141.00	X
8	ENERGY ABSORBER RR BUMPER	85090-4EA0B 11	141.40	X
9	LH SIDE BRACKET RR BUMPER	85221-4EA0A 11	38.90	X
10	RH SIDE BRACKET RR BUMPER	85220-4EA0A 11	38.90	X
11	CLIP RR BUMPER @ SGD \$-1.30 EACH	01553-05933 11	7.90	/
12	REAR BUMPER	85022-4EA0B 11	796.70	/
13	SENSOR-REVERSE	SENSOR 11	260.00	X
14	REAR LICENCE PLATE	RLP 11	60.00	X
15	SUNDRIES	11	50.00	X
SUB TOTAL			1607.60	0.00 360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-100%)			321.52	0.00 0.00
GRAND TOTAL			1286.08	0.00 360.00
OVERALL TOTAL			1646.08	

LEGEND: REMARKS(X) = APPROVED, REMARKS(/) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA6759H

TOTAL LABOUR CHARGES	3318.00
TOTAL SPARE PARTS CHARGES	1646.08

GRAND TOTAL	4964.08 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : [NS/IC/EA/0463/19]
DATE : 02-SEP-2019

SURVEYOR MARCUS

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LECNG BUILDING
S(048581)
TEL : 68277660
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

2 DAYS

OWNER'S NAME : CHOO SENG-KONG
ADDRESS : BLK 233 COMPASSVALE WALK
#05-474
S(540223)
TELEPHONE NO : 97720261

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 019MTPV01003510
VEHICLE NO : SLA6759H
MODEL CODE : FRLAR8ZJ11U5A--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2233365A
CHASSIS NO : SJNFEA/J11U1583549
MILEAGE : 92032 KM
DATE IN : 02/09/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 01/09/2019

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA6759H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO RENEW RR BUMPER	1960.00	250.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	1200.00	200.00
3 ZZ/003	RENEW REVERSE SENSOR	110.00	110.00
4 ZZ/004	SUPPLY RR LICENSE PLATE		
5 ZZ/005	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	48.00
	TOTAL LABOUR CHARGES	3318.00	608.00
	ADDITIONAL DISCOUNT(5.00%)		30.40
	FINAL LABOUR CHARGES		577.60

MATERIAL LIST FOR ACCIDENT VEHICLE (REGN NO SLA6799H)

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	LH REFLECTOR RR BUMPER	26565-JJ90A	61.90		X
2	RH REFLECTOR RR BUMPER	26460-JJ90A	61.90		X
3	ORNAMENT-BACK DOOR DASHOAT	90892-4EADA	94.40		X
4	EMBLEM-REAR-NISSAN	90890-4EADA	64.90		X
5	TOW HOOK COVER RR BUMPER	85071-4EADA	18.80		X
6	LH STAY RR BUMPER	H5211-4EAMA	141.00		X
7	RH STAY RR BUMPER	H5210-4EAMA	141.00		X
8	ENERGY ABSORBER RR BUMPER	85090-4EAOB	141.40		X
9	LH SIDE BRACKET RR BUMPER	85221-4EADA	38.90		X
10	RH SIDE BRACKET RR BUMPER	85220-4EADA	38.90		X
11	CLIP RR BUMPER @ SGD \$ 1.30 EACH	01553-05933	7.80		OK
12	REAR BUMPER	85022-4EADH	796.70		OK
13	SENSOR-REVERSE	SENSOR			250.00 X
14	REAR LICENCE PLATE	RLP			60.00 X
15	SUNDRIES	NPN			50.00 X
SUB TOTAL			804.50	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			160.90	0.00	0.00
GRAND TOTAL			643.60	0.00	0.00
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-5.00%)			32.18	0.00	0.00
OVERALL TOTAL			611.42		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLA6759H

NETT ITEM	804.50
LESS 20.00%	-160.90
NETT AMOUNT	643.60
ADDITIONAL DISCOUNT (5.00%)	-32.18
FINAL AMOUNT	611.42

LIST ITEM	0.00
LESS 20.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	0.00
LESS 20.00%	0.00
SPECIAL NETT AMOUNT	0.00

TOTAL LABOUR CHARGES	577.60
TOTAL SPARE PARTS CHARGES	611.42

TOTAL CHARGES	1189.02
ADD 7 % GST	83.23

GRAND TOTAL	1272.25
-------------	---------

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016219/UVF3N2
 Date: 02/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80469640

Claimant Vehicle No : SLA6759H

Insured Vehicle No : SLN9682G

Date of Loss: 01/09/2019

Nature of Claim: TP Claim No: 604724

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA6759H
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2233385A
 Reg. Date: 11/03/2016 (Man. Year: 2015) Chassis No: SJNFEAJ11U1583549
 Colour: Grey Odometer: 90689 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,646.08	611.42	1,034.66	62.86
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	3,318.00	577.60	2,740.40	82.59
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,964.08	1,189.02	3,775.06	76.05
+ GST 7.00/7.00% (S\$)	347.49	83.23	264.26	76.05
Nett Amount (S\$)	5,311.57	1,272.25	4,039.32	76.05

INSPECTION

Date of Assignment: 13/09/2019

Date Inspected: 13/09/2019

Inspected At:

Autolution Industrial Pte Ltd (Ubi)
 19 Ubi Road 4
 Singapore 408623

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2020)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA6759H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REFLECTOR RR BUMPER	Not Necessary	61.90 FN	*- FN
2	1		*RH REFLECTOR RR BUMPER	Not Necessary	61.90 FN	*- FN
3	1		*ORNAMENT-BACK DOOR QASHQAI	Not Necessary	94.40 FN	*- FN
4	1		*EMBLEM-REAR NISSAN	Not Necessary	64.90 FN	*- FN
5	1		*TOW HOOK COVER RR BUMPER	Not Necessary	18.80 FN	*- FN
6	1		*LH STAY RR BUMPER	Not Necessary	141.00 FN	*- FN
7	1		*RH STAY RR BUMPER	Not Necessary	141.00 FN	*- FN
8	1		*ENERGY ABSORBER RR BUMPER	Not Necessary	141.40 FN	*- FN
9	1		*LH SIDE BRACKET RR BUMPER	Not Necessary	38.90 FN	*- FN
10	1		*RH SIDE BRACKET RR BUMPER	Not Necessary	38.90 FN	*- FN
11	6		*CLIP RR BUMPER	Necessary	7.80 FN	*7.80 FN
12	1		*REAR BUMPER	Grazed/Deformed	796.70 FN	*796.70 FN
13	1		*SENSOR-REVERSE	Serviceable	250.00 FS	*- FS
14	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS
15	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (\$\$)	1,967.60	804.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	321.52	160.90
- Add. Disc. on L,N Items 0.00/5.00% (\$\$)	0.00	32.18
Total Parts (\$\$)	1,646.08	611.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR CHARGES TO REPAIR RR END PANEL & BOTH REAR FENDER,RENEW RR BUMPER	New	1,960.00	250.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,200.00	200.00
3	REFIX REVERSE SENSOR	New	110.00	110.00
4	SUPPLY RR LICENSE PLATE (NPA)	New	0.00	0.00
5	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	New	48.00	48.00
Gross Labour Cost (\$\$)			3,318.00	608.00
- 0.00/5.00% Labour Discount (\$\$)			0.00	30.40
Gross Labour after Discount (\$\$)			3,318.00	577.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >