

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986**Our File No:** CC3/FWD19016226/GSF3E2**Date:** 23/09/2019REFERENCE

Insured/Claimant:	BEH KUM WEE	Policy No:	PNPV2018-00016985
Date of Loss:	11/09/2019	Nature of Claim:	OD
		Claim No:	1201900027133

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKX8693R</b>	Engine No:	A14NET152560190
Make & Model:	CHEVROLET ORLANDO, 1.4 (A)	Chassis No:	KL1YA7589GK316591
Reg. Date:	30/12/2015 (Man. Year: 2015)	Odometer:	77540 km
Colour:	White		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,901.00	6,852.00	13,049.00	65.57
Miscellaneous Items	280.00	84.00	196.00	70.00
Labour	2,145.00	1,070.00	1,075.00	50.12
Paintwork Labour	1,250.00	900.00	350.00	28.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,576.00</b>	<b>8,906.00</b>	<b>14,670.00</b>	<b>62.22</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>500.00</b>	<b>-500.00</b>	
<b>(S\$)</b>	<b>23,576.00</b>	<b>8,406.00</b>	<b>15,170.00</b>	<b>64.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,650.32</b>	<b>588.42</b>	<b>1,061.90</b>	<b>64.35</b>
<b>Nett Amount (S\$)</b>	<b>25,226.32</b>	<b>8,994.42</b>	<b>16,231.90</b>	<b>64.35</b>

INSPECTION

Date of Assignment:	13/09/2019	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	13/09/2019	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	7.0 days		

**Adjuster:** XING GUO QIANG**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(EXCLUDE CHECK ITEMS S\$10,789.00 NETT)

**TOTAL LOSS ASPECT**

Market Value :	\$ 58,000.00
OMV :	\$ 16,447.00
PARF Rebate (1) :	\$ 12,335.00
Quota Premium Paid :	\$ 60,003.00
COE Rebate (2) :	\$ 37,774.00
Total Rebate (1) + (2) = :	\$ 50,109.00

The total amount incurred will be Market Value \$ 58,000.00 minus Total Rebate \$ 50,109.00 = \$ 7,891.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

Reference		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2019)
<b>Parts:</b>	M1-MPV	CHEVROLET ORLANDO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX8693R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Cracked	650.00 F	*650.00 F
2	10	NA	*FRONT BUMPER CLIPS	Necessary	15.00 F	*15.00 F
3	2	NA	*FRONT BUMPER SIDE HOLDER - LH; RH	Deformed	60.00 F	*60.00 F
4	2	NA	*FRONT BUMPER SIDE RETAINER - LH; RH	Deformed	20.00 F	*20.00 F
5	1	NA	*FRONT BUMPER CHEVROLET LOGO	Necessary	105.00 F	*105.00 F
6	1	NA	*FRONT BUMPER LOWER; BLACK	Cut	250.00 F	*250.00 F
7	1	NA	*FRONT FENDER - RH	Buckled	580.00 F	*580.00 F
8	1	NA	*FRONT FENDER COWLING - RH	Deformed	85.00 F	*85.00 F
9	10	NA	*FRONT FENDER COWLING CLIPS - RH	Necessary	15.00 F	*15.00 F
10	1	NA	*FRONT FENDER OUTER WHEEL ARCH GARNISH - RH	Cut	55.00 F	*55.00 F
11	1	NA	*FRONT DOOR - RH	Bent	850.00 F	*850.00 F
12	2	NA	*FRONT DOOR RUBBER - RH	Not Necessary	160.00 F	*- F
13	1	NA	*FRONT DOOR OUTER CHANNEL MOULDING - RH	Not Necessary	70.00 F	*- F
14	1	NA	*FRONT DOOR OUTER PROTECTOR; LOWER - RH	Necessary	35.00 F	*35.00 F
15	1	NA	*FRONT DOOR STICKER - RH	Necessary	55.00 F	*55.00 F
16	1	NA	*FRONT DOOR OUTER HANDLE; BIG - RH	Cut	80.00 F	*80.00 F
17	1	NA	*FRONT DOOR OUTER HANDLE; SMALL - RH	Cut	20.00 F	*20.00 F
18	1	NA	*REAR DOOR - RH	Repair	850.00 F	*- F
19	1	NA	*REAR DOOR RUBBER - RH	Not Necessary	65.00 F	*- F
20	1	NA	*REAR DOOR OUTER CHANNEL MOULDING - RH	Not Necessary	80.00 F	*- F
21	1	NA	*REAR DOOR OUTER PROTECTOR; LOWER - RH	Necessary	35.00 F	*35.00 F
22	2	NA	*REAR DOOR STICKER - RH	Not Necessary	110.00 F	*- F
23	1	NA	*REAR DOOR OUTER HANDLE; BIG - RH	Cut	80.00 F	*80.00 F
24	1	NA	*REAR DOOR OUTER HANDLE; SMALL - RH	Not Necessary	20.00 F	*- F
25	1	NA	*REAR FENDER OUTER WHEEL ARCH GARNISH - RH	Cut	55.00 F	*55.00 F
26	1	NA	*REAR BUMPER	Not Necessary	650.00 F	*- F
27	10	NA	*REAR BUMPER CLIPS	Not Necessary	15.00 F	*- F
28	2	NA	*REAR BUMPER SIDE HOLDER - LH; RH	Not Necessary	30.00 F	*- F
29	2	NA	*REAR BUMPER SIDE RETAINER - LH; RH	Not Necessary	40.00 F	*- F
30	1	NA	*REAR BUMPER LOWER; BLACK	Not Necessary	170.00 F	*- F
31	1	NA	*ROCKER PANEL OUTER GARNISH - RH	Cut	650.00 F	*650.00 F
32	1	NA	*SIDE MIRROR ASSY - RH	Cracked	580.00 F	*580.00 F
33	1	NA	*SIDE MIRROR OUTER LOWER COVER - RH	Missing	30.00 F	*30.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
34	1	NA	*FRONT DRIVE SHAFT - RH	* Check	1,028.00 F	*- F	
35	1	NA	*FRONT TYRE RIM - RH	Cut	1,482.00 F	*1,482.00 F	
36	1	NA	*FRONT ABSORBER - RH	* Check	315.00 F	*- F	
37	1	NA	*FRONT ABSORBER TOP MOUNTING - RH	* Check	55.00 F	*- F	
38	1	NA	*FRONT LOWER ARM - RH	Bent	365.00 F	*365.00 F	
39	1	NA	*FRONT KNUCKLE ARM - RH	Bent	280.00 F	*280.00 F	
40	1	NA	*FRONT KNUCKLE ARM BEARING W / WHEEL HUP - RH	Necessary	380.00 F	*380.00 F	
41	1	NA	*FRONT STAY LINK - RH	Bent	40.00 F	*40.00 F	
42	1	NA	*FRONT STEERING CROSSMEMBER	* Check	2,220.00 F	*- F	
43	1	NA	*FRONT POWER STEERING RACK	* Check	6,896.00 F	*- F	
44	1	NA	*FRONT POWER STEERING RACK TIE END - RH	* Check	75.00 F	*- F	
45	1	NA	*FRONT POWER STEERING RACK TIE ROD END - RH	* Check	200.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>19,901.00</b>	<b>6,852.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	FRONT TYRE - RH (Scratched)(30%)	280.00	84.00
			<b>Sub Total (S\$)</b>	<b>84.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,250.00	900.00
<b>Labour Items</b>				
2	TO KNOCK OUT DENTS; RH FRONT CENTRE DOOR PILLAR; RH FRONT FENDER INNER PANEL; LH REAR FENDER; REMOVE; REPLACE ACCIDENT PARTS	New	1,400.00	660.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO 4 WHEEL ALIGNMENT	New	70.00	70.00
5	TO REMOVE; REPLACE RH FRONT TYRE RIM AND BALANCING	New	45.00	40.00
6	TO REMOVE; REPLACE RH FRONT UNDERCARRIAGE; FRONT CROSSMEMBER; STEERING RACK AND RELATED PARTS	New	450.00	200.00
7	TO TRANSFER 2 DOORS AND DOOR FITTING	New	160.00	80.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >