

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19016231/KGA3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKX252H	<b>Insured Vehicle No :</b>	SH7102B
Date of Loss: 08/09/2019	Nature of Claim: TP	Claim No: MCT19090178

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKX252H</b>		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2603266
Reg. Date:	22/06/2006 (Man. Year: 2006)	Chassis No:	ZNE100311955
Colour:	Metallic Silver	Odometer:	201283 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,512.87	1,966.48	3,546.39	64.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,800.00	1,640.00	47.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,952.87</b>	<b>3,766.48</b>	<b>5,186.39</b>	<b>57.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>		
<b>(S\$)</b>	8,952.87	2,650.00	6,302.87	70.40
<b>+ GST 7.00/7.00% (S\$)</b>	626.70	185.50	441.20	70.40
<b>Nett Amount (S\$)</b>	<b>9,579.57</b>	<b>2,835.50</b>	<b>6,744.07</b>	<b>70.40</b>
<b>+ Car Rental (4.0 x S\$180.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,562.95</b>		

### INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	16/09/2019 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2020)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX252H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,492.30 FL	*1,492.30 FL
2	1		*TAILGATE WEATHERSTRIP	Serviceable	352.30 FL	*- FL
3	1		*TAILGATE STOPPER LH	Serviceable	15.60 FL	*- FL
4	1		*TAILGATE STOPPER RH	Serviceable	15.60 FL	*- FL
5	1		*TAILGATE HINGE LH	Repair	88.75 FL	*- FL
6	1		*TAILGATE HINGE RH	Repair	88.75 FL	*- FL
7	1		*TAILGATE LOCK ASSY	Repair	470.40 FL	*- FL
8	1		*TAILGATE LOCK STRIKER	Repair	45.17 FL	*- FL
9	1		*TAILGATE HANDLE CHROME MOULDING	Serviceable	291.45 FL	*- FL
10	1		*SET REAR WINDSCREEN MOULDING	Necessary	70.20 FL	*70.20 FL
11	1		*REAR WIPER MOTOR	Serviceable	699.60 FL	*- FL
12	1		*REAR TAIL LAMP ASSY RH	Serviceable	574.90 FL	*- FL
13	2		*REAR TAIL LAMP CLIP	Not Necessary	8.44 FL	*- FL
14	1		*REAR BUMPER	Cracked	525.30 FL	*525.30 FL
15	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	67.80 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER RH	Distorted	67.80 FL	*67.80 FL
17	12		*REAR BUMPER CLIP	Necessary	46.68 FL	*46.68 FL
18	1		*REAR BUMPER REFLECTOR RH	Cracked	59.70 FL	*59.70 FL
19	1		*REAR END PANEL	Repair	522.60 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	295.40 FL	*- FL
21	1		*REAR EXHAUST SILENCER ASSY	Repair	780.15 FL	*- FL
22	2		*REAR EXHAUST SILENCER MOUNTING	Serviceable	91.60 FL	*- FL
23	2		*ANTI-RUST COATING	Not Necessary	160.00 FS	*30.00 FS
24	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*SET REAR BUMPER SENSOR	Missing	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,180.49</b>	<b>2,531.98</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,667.62	565.50
<b>Total Parts (\$\$)</b>	<b>5,512.87</b>	<b>1,966.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,250.00	950.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,250.00	600.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
4	REMOVE AND INSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM ,GARNISH ,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
5	DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW /FACILITATE REPAIR	New	100.00	60.00
6	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
7	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS	New	60.00	50.00
8	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE EXHAUST PIPE/SYSTEM TO FACILITATE REPAIR	New	120.00	0.00
9	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH	New	250.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>3,440.00</b>	<b>1,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >