

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

DEAR SIR / MADAM :

*Not Authorized  
11 Sep @ 2650h  
Resony After Point  
4-141*

ACCIDENT REPAIR ON: SKX252H

MODEL : TOYOTA WISH 1.8A

POLICY NO : MPC19A00111900

CHASSIS NO : ZNE100311955

YEAR OF MANUFACTURE : 2006

DATE / TIME OF ACCIDENT: 08/09/2019 Time: 1225Hrs at ALONG YISHUN AVE 11 &

THIRD PARTY VEHICLE NO: SH7102B

Date: 13/09/2019

Page : 1 of 2

YISHUN RING ROAD.

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

## Replacement Of Parts

| S/N                               | Quantity | Unit Price | Condition   | Amount          |
|-----------------------------------|----------|------------|-------------|-----------------|
|                                   |          | S\$        |             | S\$             |
| 1 Tailgate                        | 1        | 1,492.30   | Dented      | 1,492.30 ✓      |
| 2 Tailgate weatherstrip           | 1        | 352.30     | Torn        | 352.30 x        |
| 3 Tailgate stopper LH             | 1        | 15.60      | Necessary   | 15.60 x         |
| 4 Tailgate stopper RH             | 1        | 15.60      | Necessary   | 15.60 x         |
| 5 Tailgate hinge LH               | 1        | 88.75      | Bented      | 88.75 x         |
| 6 Tailgate hinge RH               | 1        | 88.75      | Bented      | 88.75 x         |
| 7 Tailgate lock assy              | 1        | 470.40     | Cracked     | 470.40 x        |
| 8 Tailgate lock striker           | 1        | 45.17      | Bented      | 45.17 x         |
| 9 Tailgate handle chrome moulding | 1        | 291.45     | To Check    | 291.45 x        |
| 10 Rear windscreen moulding set   | 1        | 70.20      | Necessary   | 70.20 ✓         |
| 11 Rear wiper motor               | 1        | 699.60     | Malfunction | 699.60 x        |
| 12 Rear tail lamp assy RH         | 1        | 574.90     | Cracked     | 574.90 x        |
| 13 Rear tail lamp clip            | 2        | 4.22       | Necessary   | 8.44 x          |
| 14 Rear bumper                    | 1        | 525.30     | Torn        | 525.30 ✓        |
| 15 Rear bumper side retainer LH   | 1        | 67.80      | Necessary   | 67.80 x         |
| 16 Rear bumper side retainer RH   | 1        | 67.80      | Necessary   | 67.80 ✓         |
| 17 Rear bumper clip               | 12       | 3.89       | Necessary   | 46.68 ✓         |
| 18 Rear bumper reflector RH       | 1        | 59.70      | Cracked     | 59.70 ✓         |
| 19 Rear end panel                 | 1        | 522.60     | Dented      | 522.60 x repair |
| 20 Rear end panel top garnish     | 1        | 295.40     | Kinked      | 295.40 x        |
| 21 Rear exhaust silencer assy     | 1        | 780.15     | Bented      | 780.15 x        |
| 22 Rear exhaust silencer mounting | 2        | 45.80      | Necessary   | 91.60 x         |

\$ 2261.98 - 25%

= \$ 1696.48

Sub-Total: 6,670.49

Less: 25% discount - 1,667.62

Total Parts after 25% discount: 5,002.87

## Special Nett Items

|                          |   |        |                 |
|--------------------------|---|--------|-----------------|
| 1 Anti-rust coating      | 2 | 80.00  | na 160.00 301   |
| 2 Windscreen sealant     | 1 | 100.00 | na 100.00 405n  |
| 3 Rear bumper sensor set | 1 | 250.00 | na 250.00 2005n |
|                          |   |        | 510.00          |

\$ 270.00

Total Parts: 5,512.87

Labour Charges For Rear RH Portion

|   |                                                                                                                                            |          |         |
|---|--------------------------------------------------------------------------------------------------------------------------------------------|----------|---------|
| 1 | Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. | 1,250.00 | 950 300 |
| 2 | Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities             | 1,250.00 | 600     |
| 3 | Provide skill labour to disconnect and check electrical wiring                                                                             | 60.00    | 201     |
| 4 | Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs                   | 150.00   | 7       |
| 5 | Dismantle and transfer tailgate fittings and mechanism to new/facilitate repair                                                            | 100.00   | 601     |
| 6 | Provide skill labour to remove and refit rear windscreen                                                                                   | 200.00   | 1201    |
| 7 | Provide skill labour to remove and replace bumper sensors                                                                                  | 60.00    | 501     |
| 8 | Provide skill labour to remove and replace exhaust pipe/system to facilitate repair                                                        | 120.00   | x       |
| 9 | Provide skill labour to mount vehicle onto chassis alignment bench                                                                         | 250.00   | x       |

Total Labour:

\$1800.00

Total Parts & Labour:

3,440.00

GST 7%

8,952.87

Grand Total:

626.70

9,579.57

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SKX252H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth  
Company : LKK  
Date : 16/9/19  
Time : 11.45am  
Contact No : 96910663  
Email :

Part: \$1696.48

S/N: \$270.00

Labour: \$1800.00

Total: \$3766.48 - 20%

= \$3013.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: