

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016239/KBA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SME9172Y

Insured Vehicle No : GBC3811S

Date of Loss: 11/09/2019

Nature of Claim: TP

Claim No: 8693065194SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME9172Y**

Make & Model: TOYOTA PRIUS HYBRID, 1.5 (A)

Engine No: 2ZR0C01002

Reg. Date: 22/10/2018 (Man. Year: 2018)

Chassis No: ZVW400030063

Colour: Metallic Silver

Odometer: 98588 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Roadstone 8 mm

Rear Left Side:

Roadstone 7 mm

Front Right Side: Roadstone 8 mm

Rear Right Side:

Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,778.73	4,630.10	3,148.63	40.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,690.00	2,460.00	59.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,928.73	6,320.10	5,608.63	47.02
+ GST 7.00/7.00% (S\$)	835.01	442.41	392.60	47.02
Nett Amount (S\$)	12,763.74	6,762.51	6,001.23	47.02
+ Car Rental (8.0 x S\$88.00/day) (S\$)		704.00		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		7,473.99		
Global Sum Settlement (S\$)		7,470.00		

INSPECTION

Date of Assignment: 12/09/2019

Date Inspected: 13/09/2019 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,473.80 FL	*1,473.80 FL
2	1		*REAR WINDSCREEN SOLAR FIRM	Necessary	450.00 FS	*200.00 FS
3	1		*PRIVATE HIRER STICKER	Necessary	20.00 FS	*20.00 FS
4	1		*REAR WINDSCREEN MOULDING	Necessary	70.20 FL	*70.20 FL
5	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
6	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
7	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
8	1		*REAR BUMPER	Bent	459.20 FL	*459.20 FL
9	1		*REAR BUMPER CLIP	Necessary	38.90 FL	*38.90 FL
10	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	121.70 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER RH	Distorted	121.70 FL	*121.70 FL
12	1		*REAR BUMPER REFLECTOR LH	Serviceable	58.70 FL	*- FL
13	1		*REAR BUMPER REFLECTOR RH	Serviceable	58.70 FL	*- FL
14	1		*TAIL DOOR	Bent	1,022.50 FL	*1,022.50 FL
15	1		*TAIL DOOR LOCK	Repair	391.60 FL	*- FL
16	1		*TAIL DOOR PLATE GARNISH	Warped	498.30 FL	*498.30 FL
17	1		*TAIL DOOR EMBLEM	Necessary	67.10 FL	*67.10 FL
18	1		*WORDING PRIUSCX	Necessary	72.66 FL	*72.66 FL
19	1		*WORDING HYBRID SYNERGY	Necessary	48.57 FL	*48.57 FL
20	1		*TAIL DOOR TRIM	Serviceable	577.85 FL	*- FL
21	10		*TAIL DOOR TRIM CLIP	Not fitted	42.10 FL	*- FL
22	1		*TAIL END PANEL	Bent	678.10 FL	*678.10 FL
23	1		*TAIL END PANEL GARNISH	Distorted	154.60 FL	*154.60 FL
24	10		*TAIL END PANEL GARNISH CLIP	Necessary	39.20 FL	*39.20 FL
25	1		*BOOT WEATHERSTRIP	Serviceable	342.70 FL	*- FL
26	1		*TAIL LAMP LH	Serviceable	653.20 FL	*- FL
27	1		*TAIL LAMP RH	Cracked	653.20 FL	*653.20 FL
28	10		*TAIL LAMP CLIP	Necessary	42.10 FL	*42.10 FL
29	1		*REAR CAMERA	Serviceable	680.00 FS	*- FS
30	1		*SPARE TYRE BOARD	Serviceable	698.30 FL	*- FL
31	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
					Sub Total (\$\$)	9,874.98
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,096.25
					Total Parts (\$\$)	4,630.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER ,RHR FENDER,FRONT BUMPER)	New	1,600.00	600.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER ,RHR FENDER,FRONT BUMPER)	New	1,600.00	660.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	60.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO TUFF COAT	New	150.00	60.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
10	TO ARRANGE EXPRESS SERVICE TO DO PRIVATE HIRER STICKER	New	120.00	40.00
Gross Labour Cost (\$\$)			4,150.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >