

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SM SPRAY PAINTING A 167

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SKQ7897M	Excess.	NIL
Policy No.		Coverage.	
Claiming Against.	SDP3838Z		
Insured Under.	NTUC INCOME		

Vehicle Particulars & Condition

Make & Model	HONDA JAZZ 1.5
Engine No.	L15B31000248
Chassis No.	JHMGK5850FX201899
Odometer	
Engine CC.	1500
Year Of Reg.	2014
Colour.	RED
Parf/COE Rebate.	\$ 39,666.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

FRONT / REAR PORTION

General Information

Accident Date. 11/9/2019
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

SM SPRAY PAINTING

Not Authorized
date
13/9/19
TOTAL 1955?

Qty.	Description Of Parts	Pricing
1	REAR TAILGATE	body m \$ 814.20 ✓
1	REAR TAILGATE HINGE LH	17 \$ 40.30x
1	REAR TAILGATE HINGE RH	17 \$ 40.30x
1	REAR TAILGATE LOCK	DD/ym \$ 157.20 ✓
1	REAR TAILGATE LOCK CABLE	ym \$ 110.00 ✓
1	REAR TAILGATE INNER TRIM	Dis \$ 98.20 ✓
1	REAR TAILGATE WIPER MOTOR	ym \$ 178.20 ✓
1	REAR TAILGATE WIPER ARM	set \$ 59.20 ✓
1	REAR TAILGATE OUTER CENTRE GARNISH	cm \$ 195.20 ✓
1	REAR NUMBER PLATE LAMP	\$ 32.80 ?
1	REAR TAILGATE LOGO	rec \$ 20.70 ✓
1	REAR TAILGATE JAZZ EMBLEM	rec \$ 35.40 ✓
1	REAR TAILGATE LOCK OUTER HANDLE	\$ 175.20 ?
1	REAR FENDER LH	body m/sec \$ 659.20 ✓
1	REAR FENDER RH	body m/sec \$ 659.20 ✓
1	REAR FENDER INNER TRIM LH	Dis \$ 165.20 ✓
1	REAR FENDER INNER TRIM RH	\$ 165.20 ?
1	REAR TAILLAMP LH	smo \$ 287.20 ✓
1	REAR TAILLAMP RH	cm \$ 287.20 ✓
1	REAR BUMPER	Dis \$ 456.20 ✓
1	REAR BUMPER BRACKET LH	set \$ 90.00 ✓
1	REAR BUMPER BRACKET RH	set \$ 90.00 ✓
1	REAR BUMPER AIR COVER LH	tin \$ 48.20 ✓
1	REAR BUMPER AIR COVER RH	\$ 48.20 ?
1	REAR BUMPER SIDE RETAINER LH	set \$ 23.50 ✓
1	REAR BUMPER SIDE RETAINER RH	body \$ 23.50 ✓
1	REAR WINDSCREEN GLASS	shop/d \$ 855.20 ✓
1	REAR WINDSCREEN MOULDING	del \$ 149.20 ✓
1	REAR TAILGATE RUBBER	twi \$ 92.30 ✓
1	REAR FENDER INNER SHIELD LH	tin \$ 83.70 ✓
1	REAR FENDER INNER SHIELD RH	17 \$ 83.70x
1	REAR DOOR LH	n RPR x
1	REAR DOOR RH	n RPR x
1	ROOF PANEL	n RPR
1	REAR TAILLAMP PANEL LH	set \$ 85.30 ✓
1	REAR TAILLAMP PANEL RH	\$ 85.30 ?
1	REAR LUGGAUGE COMPARTMENT TOP COVER	\$ 198.20 ?
1	REAR END PANEL	body m \$ 390.20 ✓
1	REAR END PANEL TOP GARNISH	Dis \$ 120.40 ✓
1	REAR SPARE TYRE PANEL	crumpled/sec \$ 897.20 ✓
1	REAR SPARE TYRE PANEL TOP COVER	\$ 550.87 ?

7/3/20

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	REAR SPARE TYRE	\$ 280.00 ⁹
1	REAR SPARE TYRE COMPARTMENT	\$ 127.20 ⁷
	List items	\$ 8,958.47
	Less 20%	\$ 447.92
	Sub Total	\$ 8,510.55
1	REAR TAILGATE INNER TRIM CLIPS	<i>ur</i> \$ 30.00 ✓
1	REAR TAILGATE WIPER BLADE	<i>Surf</i> \$ 26.00 ✓
1	REAR NUMBER PLATE	<i>Surf</i> \$ 45.00 40
1	REAR BUMPER CLIP	<i>rey</i> \$ 30.00 ✓
1	REAR REVERSE SENSOR	<i>Shind</i> \$ 200.00 ✓
1	REAR WINDSCREEN SEALANT	<i>ree</i> \$ 60.00 40
2	REAR FENDER INNER SHIELD CLIPS	<i>11</i> \$ 120.00 X
2	REAR FENDER GLASS SEALANT	<i>ree</i> \$ 120.00 60
4	REAR TAILLAMP CLIP	<i>11</i> \$ 8.00 X
	Nett Items	\$ 639.00
		<i>426</i>

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panel for rust protection.	\$ 80.00 ✓
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 80.00 30
	To Carry-Out Body Cavity Preservation.	Repaint \$ 60.00 X
	TO REMOVE & REFIT REAR FENDER GLASS	\$ 200.00 160
	Computer wheel alignment	\$ 100.00 60
	TO DISMANTTLE & REFIT REAR WINDSCREEN GLASS	\$ 100.00 ✓
	TO TRANSFER REAR TAILGATE	\$ 120.00 60
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 2,000.00 ✓
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,700.00 1400
	LABOUR	\$ 4,440.00 3890
	Sub Total.	\$ 12,950.55
	7% GST	\$ 906.54
	Grand Total	\$ 13,857.08

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12245.78

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2019 Edit Reg		13 Sep 2019 00:00 Edit Adj Rpt	S\$10,020.96 Edit Estimates	S\$10,020.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHONG KWONG ONN JOEL , ID: S8424890H, Tel: +6598765432								
Main Claimant:	FOO CHER BOON , ID: S8328113H								
Vehicle Reg. No.:	SKQ7897M	Date of Loss:	11/09/2019 17:00 - :59 [56 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7870513903SG	Policy/Cover Note No.:	1800102003 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDP3838Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Sm Spray Panting (HQ) 1 Kaki Bukit Avenue 6, #01-13 Autobay, 417883 Kaki Bukit - Tel: 98228346								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (17/09/2019): NO TP GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKQ7897M (7870513903SG)**
[SDP3838Z]





































TP

FOO CHER BOON

Sep 11 2019 5:00PM

[CHONG KWONG ONN JOEL]

Sm Spray Panting

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/19 09:23	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/09/19 09:24	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
38	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
39	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
40	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
42	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
43	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
44	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
45	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
46	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
47	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
48	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
49	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
50	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
51	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
52	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
53	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
54	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
55	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
56	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
57	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
58	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
59	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
60	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
61	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
62	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
63	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
64	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
65	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
66	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
67	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
68	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
69	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
70	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
71	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
72	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
73	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
74	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
75	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
76	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
77	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
78	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
79	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
80	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
81	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
82	14/09/19 09:24	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/19 14:51	GIA REPORT	Load PDF	
2	20/09/19 10:17	LTA REBATE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/09/19 15:02	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19016247/UYD3S2
Date: 20/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800102003
Claimant Vehicle No : SKQ7897M **Insured Vehicle No :** SDP3838Z
 Date of Loss: 11/09/2019 Nature of Claim: TP Claim No: 7870513903SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ7897M**
 Make & Model: HONDA JAZZ, 1.5 VTIR (A) Engine No: L15B31000248
 Reg. Date: 26/12/2014 (Man. Year: 2014) Chassis No: JHMGK5850FX201899
 Colour: Red Odometer: 103784 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,805.78	6,130.96	1,674.82	21.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	3,890.00	550.00	12.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,245.78	10,020.96	2,224.82	18.17
+ GST 7.00/7.00% (S\$)	857.20	701.47	155.73	18.17
Nett Amount (S\$)	13,102.98	10,722.43	2,380.55	18.17

INSPECTION

Date of Assignment: 13/09/2019
 Date Inspected: 13/09/2019 Inspected At: SM Spray Painting
 NO. 25 KAKI BUKIT ROAD 4
 #08-30 SYNERGY @ KAKI BUKIT
 SINGAPORE 417800
 Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$48,000.00

OMV : \$15,051.00

PARF Rebate (1) : \$3,788.00

Quota Premium Paid : \$67,889.00

COE Rebate (2) : \$35,805.00

Total Rebate (1) + (2) = \$39,593.00

THE TOTAL AMOUNT INCURRED WILL BE MARKET VALUE \$48,000.00 MINUS TOTAL REBATE \$39,593.00 =
\$8,407.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

(AMOUNT AGREED AND ACCEPTED BY REPAIRER)

(EXCLUDE CHECK ITEMS S\$1,330.37 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	814.20 FL	*814.20 FL
2	1		*REAR TAILGATE HINGE LH	Not Necessary	40.30 FL	*- FL
3	1		*REAR TAILGATE HINGE RH	Not Necessary	40.30 FL	*- FL
4	1		*REAR TAILGATE LOCK	Dented / Jammed	157.20 FL	*157.20 FL
5	1		*REAR TAILGATE LOCK CABLE	Jammed	110.00 FL	*110.00 FL
6	1		*REAR TAILGATE INNER TRIM	Distorted	98.20 FL	*98.20 FL
7	1		*REAR TAILGATE WIPER MOTOR	Jammed	178.20 FL	*178.20 FL
8	1		*REAR TAILGATE WIPER ARM	Bent	59.20 FL	*59.20 FL
9	1		*REAR TAILGATE OUTER CENTRE GARNISH	Cracked	195.20 FL	*195.20 FL
10	1		*REAR NUMBER PLATE LAMP	*Check	32.80 FL	*- FL
11	1		*REAR TAILGATE LOGO	Necessary	20.70 FL	*20.70 FL
12	1		*REAR TAILGATE JAZZ EMBLEM	Necessary	35.40 FL	*35.40 FL
13	1		*REAR TAILGATE LOCK OUTER HANDLE	*Check	175.20 FL	*- FL
14	1		*REAR FENDER LH	Badly Dented / Buckled	659.20 FL	*659.20 FL
15	1		*REAR FENDER RH	Badly Dented / Buckled	659.20 FL	*659.20 FL
16	1		*REAR FENDER INNER TRIM LH	Distorted	165.20 FL	*165.20 FL
17	1		*REAR FENDER INNER TRIM RH	*Check	165.20 FL	*- FL
18	1		*REAR TAILLAMP LH	Broken	287.20 FL	*287.20 FL
19	1		*REAR TAILLAMP RH	Cracked	287.20 FL	*287.20 FL
20	1		*REAR BUMPER	Distorted	456.20 FL	*456.20 FL
21	1		*REAR BUMPER BRACKET LH	Bent	90.00 FL	*90.00 FL
22	1		*REAR BUMPER BRACKET RH	Bent	90.00 FL	*90.00 FL
23	1		*REAR BUMPER AIR COVER LH	Torn	48.20 FL	*48.20 FL
24	1		*REAR BUMPER AIR COVER RH	*Check	48.20 FL	*- FL
25	1		*REAR BUMPER SIDE RETAINER LH	Bent	23.50 FL	*23.50 FL
26	1		*REAR BUMPER SIDE RETAINER RH	Bent	23.50 FL	*23.50 FL
27	1		*REAR WINDSCREEN GLASS	Shattered	855.20 FL	*855.20 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	149.20 FL	*149.20 FL
29	1		*REAR TAILGATE RUBBER	Twisted	92.30 FL	*92.30 FL
30	1		*REAR FENDER INNER SHIELD LH	Torn	83.70 FL	*83.70 FL
31	1		*REAR FENDER INNER SHIELD RH	Not Necessary	83.70 FL	*- FL
32	1		*REAR DOOR LH (NPA)	Repair	0.00 FL	*- FL
33	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
34	1		*ROOF PANEL (NPA)	Repair	0.00 FL	*- FL
35	1		*REAR TAILLAMP PANEL LH	Bent	85.30 FL	*85.30 FL
36	1		*REAR TAILLAMP PANEL RH	*Check	85.30 FL	*- FL
37	1		*REAR LUGGAGE COMPARTMENT TOP COVER	*Check	198.20 FL	*- FL
38	1		*REAR END PANEL	Badly Dented	390.20 FL	*390.20 FL
39	1		*REAR END PANEL TOP GARNISH	Distorted	120.40 FL	*120.40 FL
40	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	897.20 FL	*897.20 FL
41	1		*REAR SPARE TYRE PANEL TOP COVER	*Check	550.87 FL	*- FL
42	1		*REAR SPARE TYRE	*Check	280.00 FL	*- FL
43	1		*REAR SPARE TYRE COMPARTMENT	*Check	127.20 FL	*- FL
44	1		*REAR TAILGATE INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*REAR TAILGATE WIPER BLADE	Bent	26.00 FS	*26.00 FS
46	1		*REAR NUMBER PLATE	Bent	45.00 FS	*40.00 FS
47	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
48	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
49	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
50	2		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	120.00 FS	*- FS
51	2		*REAR FENDER GLASS SEALANT	Necessary	120.00 FS	*60.00 FS
52	4		*REAR TAILLAMP CLIP	Not Necessary	8.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,597.47** **7,557.20**
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,791.69 1,426.24

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	7,805.78
						6,130.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANEL FOR RUST PROTECTION.	New	80.00	80.00
2	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGES PARTS.	New	80.00	30.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	60.00	0.00
4	TO REMOVE & REFIT REAR FENDER GLASS.	New	200.00	160.00
5	COMPUTER WHEEL ALIGNMENT.	New	100.00	60.00
6	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS.	New	100.00	100.00
7	TO TRANSFER REAR TAILGATE.	New	120.00	60.00
8	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	2,000.00	2,000.00
9	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE.	New	1,700.00	1,400.00
Gross Labour Cost (\$\$)			4,440.00	3,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >