



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBB 6166G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	BUCKLED	777.90	777.90
6	REAR BUMPER CLIPS @\$3.50 (CONSISTENT)	NECESSARY	21.00	21.00
1	REAR TAILGATE (CONSISTENT)	BENT	1,100.90	1,100.90
1	TAILGATE EMBLEM 'VEZEL' (CONSISTENT)	NECESSARY	45.60	45.60
1	TAILGATE EMBLEM 'HYBRID' (CONSISTENT)	NECESSARY	75.50	75.50
1	TAILGATE INNER LOCK (CONSISTENT)	DENTED	181.60	181.60
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	151.80	151.80
	LESS 20% DISCOUNT		-470.86	-470.86
			1,883.44	1,883.44
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
1	ROLL REAR WINDSCREEN GLASS GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			240.00	240.00
<u>LABOUR</u>				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE & REFIX TAILGATE ASSY ,REAR BUMPER ,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME.		650.00	450.00
	PUTTY & RESPRAY ON REAR PANEL ,TAILGATE ,REAR BUMPER.		750.00	650.00
	REMOVE & REFIX REVERSE CAMERA.		50.00	50.00
	RUSTPROOFING.		60.00	30.00
			1,630.00	1,300.00
GRAND TOTAL			3,753.44	3,423.44
RECOMMENDED COST OF REPAIRS				3,423.44

Report Ref No. CC4/ASM19016282/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.