

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016299/UDS3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SFY9897S **Insured Vehicle No :** SME1830J

Date of Loss: 13/09/2019 **Nature of Claim:** TP **Claim No:** 4277483411SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFY9897S	Engine No:	2ARE752058
Make & Model:	LEXUS ES250, 2.5 (A)	Chassis No:	JTHBJ1GG902035704
Reg. Date:	31/12/2013 (Man. Year: 2013)	Odometer:	55617 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,312.90	20,332.02	26,980.88	57.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	3,410.00	2,220.00	39.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,942.90	23,742.02	29,200.88	55.16
Approved Total (Overridden) (S\$)		18,500.00		
(S\$)	52,942.90	18,500.00	34,442.90	65.06
+ GST 7.00/7.00% (S\$)	3,706.00	1,295.00	2,411.00	65.06
Nett Amount (S\$)	56,648.90	19,795.00	36,853.90	65.06
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,497.00		

INSPECTION

Date of Assignment: 16/09/2019

Date Inspected: 16/09/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,866.50 F	*1,466.20 FL
2	1		*BOOTLID REAR LOGO	Necessary	105.20 F	*105.20 FL
3	1		*BOOTLID LEXUS EMBLEM	Necessary	99.50 F	*99.50 FL
4	1		*BOOTLID ES250 EMBLEM	Necessary	92.80 F	*92.80 FL
5	1		*BOOTLID OUTER CHROME MOULDING	Bent / Cracked	644.20 F	*422.80 FL
6	1		*BOOTLID LOCK STRIKER	Not Necessary	89.90 F	*- FL
7	2		*BOOTLID REFLECTORS	Cracked	1,732.00 F	*1,070.20 FL
8	1		*BOOTLID INNER LOCK	Twisted / Jammed	509.10 F	*509.10 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	366.20 F	*366.20 FL
10	1		*BOOTLID INNER TRIM	Not Necessary	641.10 F	*- FL
11	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
12	2		*BOOTLID HINGES	Not Necessary	245.60 F	*- FL
13	1		*REAR BUMPER	Distorted	1,442.30 F	*988.10 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	811.20 F	*715.20 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	137.00 F	*- FL
17	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	204.60 F	*- FL
18	4		*REAR BUMPER PDC SENSORS	Cracked (2 PCS ONLY)	1,252.00 F	*626.00 FL
19	1		*REAR BUMPER LOWER TRAY	Not fitted	481.10 F	*- FL
20	1		*REAR BUMPER LOWER GARNISH	Not Necessary	422.50 F	*- FL
21	1		*REAR BUMPER SPONGE	Distorted	266.50 F	*215.30 FL
22	1		*REAR END PANEL	Badly Dented	988.20 F	*892.50 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	439.10 F	*439.10 FL
24	1		*REAR END PANEL LOCK SENSOR	Cracked	350.00 F	*350.00 FL
25	2		*TAILLAMP	Cracked	1,845.00 F	*1,570.40 FL
26	1		*TAILLAMP HOUSING PANELS	O/S Bent	777.00 F	*388.50 FL
27	2		*REAR FENDERS	Repair	2,410.00 F	*- FL
28	2		*REAR FENDER INNER TRIMS	Not Necessary	830.00 F	*- FL
29	1		*REAR FLOOR PANEL	Repair	1,429.30 F	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	682.30 F	*- FL
31	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	455.50 F	*- FL
32	1		*REAR EXHAUST	Repair	985.40 F	*- FL
33	2		*REAR EXHAUST MOUNTINGS	Not Necessary	120.00 F	*- FL
34	2		*TAILLAMP LOWER BRACKETS	Cracked	124.40 F	*124.40 FL
35	1		*BONNET	Repair	1,066.50 F	*- FL
36	1		*BONNET INSULATOR	Not Necessary	311.20 F	*- FL
37	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
38	2		*BONNET HINGES	Not Necessary	250.00 F	*- FL
39	1		*BONNET LOCK	Not Necessary	241.10 F	*- FL
40	1		*FRONT BUMPER	Dented / Deformed	1,385.20 F	*988.10 FL
41	1		*FRONT BUMPER SPONGE	Torn	312.50 F	*266.30 FL
42	1		*FRONT BUMPER REINFORCEMENT	Bent	892.30 F	*715.50 FL
43	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	210.00 F	*- FL
44	1		*FRONT BUMPER CENTRE GRILLE	Torn	205.00 F	*105.40 FL
45	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
46	1		*FRONT BUMPER FOG LAMPS	N/S Cracked	767.00 F	*383.50 FL
47	1		*FRONT BUMPER LICENCE PLATE GARNISH	Deformed / Torn	88.20 F	*88.20 FL
48	2		*FRONT BUMPER CENTRE CHROME MOULDING	Cracked	840.00 F	*630.00 FL
49	1		*FRONT GRILLE	Cracked	1,220.00 F	*681.30 FL
50	1		*FRONT GRILLE LOGO	Scratched	185.00 F	*145.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	2		*HEADLAMP ASSY	Cracked	7,200.00 F	*5,830.60 FL
52	1		*FRONT SUPPORT PANEL	Bent	619.00 F	*619.00 FL
53	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	429.30 F	*286.40 FL
54	2		*FRONT BUMPER PDC SENSORS	Shorted	626.00 F	*626.00 FL
55	2		*FRONT FENDERS	Repair	1,582.40 F	*- FL
56	1		*FRONT BRACE PANEL	Twisted	151.00 F	*151.00 FL
57	1		*AIR CON CONDENSER	Not Necessary	1,420.00 F	*- FL
58	1		*RADIATOR	Not Necessary	1,886.20 F	*- FL
59	1		*RADIATOR FAN ASSY	Not Necessary	1,299.50 F	*- FL
60	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
61	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
62	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
63	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
64	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
65	1		*REAR REVERSE CAMERA	Shorted	600.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 47,312.90 22,537.80
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 2,205.78

Total Parts (\$\$) 47,312.90 20,332.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR PDC SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	120.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
7	TO SPRAY RUST PROOFING	New	180.00	90.00
8	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,300.00
10	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (\$\$)			5,630.00	3,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >