

(08/11/13)

Surveyor: KalvinREF: CC3/TM19016349/klsf352**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 7555U Yr Regn: 13 Sep 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Zonig c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 177200 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851 CVK410750XGen. Cond: Good / Poor / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Parant

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 13/9/19 D.O.I. 16/9/19Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 7555U - CC3/CTI 19001085/veh352
	SQP 6829E - X
18/9/19	Label PIP \$2178.14 / 2 Pys. (\$524.88 Red - 19%)

Date/Time, File Pass to?

19/09/191) Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

P/P \$ 2,178.14

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305333382

OWNER

COMFORT TRANSPORTATION PTE LTD

IS 7010045

OWNER NO.

383 SIN MING DRIVE

LESS Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHA7555U

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

16.09.2019 08:00

YR OF MANU

13.09.2018

TARGET DATE

CHASSIS CODE

KMHC851CVKU107504

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 13.09.2019

NATURE: 3P 13.09.19

S/NO

LABOR CODE

DESCRIPTION



PACKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Settlement Slip

Exit Pass

No.:

SHA7555U

JU TOKIO LKK

Vehicle No.:

SHA7555U

Signature/Date

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/09/2019 16:19
Date Of Accident	13/09/2019 09:25
Exact Location Of Accident	TG KATONG RD SOUTH TOWARDS ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7555U
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TEE HOCK LEONG
NRIC No	S1175954H
Date Of Birth	08/01/1956
Occupation	OUTDOOR
Date Of Driving Pass	24/01/1994
Driving Experience	25 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82825717
Fax Number	
Contact Number	
EMail Address	HOCKLEONGT@GMAIL.COM

Address	140 05-03 UPPER BUKIT TIMAH ROAD
Postcode	588176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: -
	GENDER: MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

see attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGP6825E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

SKETCH PLAN

1. DATA #SSSU

B-EGP (825E)
(MCM0A)

Ar ✓

A hand-drawn diagram on a grid background. On the left, two squares are stacked vertically, labeled 'A' (top) and 'B' (bottom). To the right of these squares, a series of vertical lines represent lattice sites. Above the first five sites, there are arrows pointing to the right. Above the sixth site, there is an arrow pointing to the left. This represents a hopping process from site 6 to site 5.

TA KATONG, RD 20TH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement as per attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature: _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: Olivia Wendy
NRIC/FIN No: 13 SEP 2014

Describe Circumstances of the Accident.

On the 13/09/2019 @ about 09:25hrs, I was driving along Tg Katong Rd South towards ECP slip rd with 1 male passenger on board my taxi.


The front vehicle jammed braked so I slow down and stop as well. Then suddenly there's an impact from behind my taxi. I step out to checked and found out a vehicle of SGP6825E front portion had collided onto my rear portion of my taxi.

No injury at the point of accident.


Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature/Date &
Time






Driver's Signature(If driver is not the policyholder)/Date
& Time



Witnessed by Reporting
Centre Personnel

13 SEP 2019





TOKIO - JU
PLP

VEHICLE NO : SHA 7555U

DATE 13/9/2019 15:25

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper / ca			\$ 459.40
	Rear Bumper Reinforcement — ca			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) ✓ Reels	S	138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy — m			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy — m			\$ 47.50
	Rear Bumper Stay X sm			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) X sm	\$	33.10	\$ 66.20
	Rear Bumper Cover Clips — m			\$ 22.00
	Rear Bumper Reflector Lamp (LH/RH) X sm	\$	31.90	\$ 63.80
	SUB TOTAL			\$ 1,819.25
	LESS 20%			\$ 363.85
	DISCOUNTED TOTAL			\$ 1,455.40
	Rear No.Plade — ca shohd			\$ 25.00
	Rear Bumper Reserve Sensor — m			\$ 257.10
	Rear Bumper Rubber Mat — m			\$ 50.00
	TOTAL			\$ 332.10
	Labour Charge			
	Panel Beating Kalani 16/KC/CY			\$ 350.00 320
	Spray Painting Charge // 16/9/19 1050h			\$ 250.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Marian Fee 2 Days P.P.			\$ "
	Before Part photo			
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,537.50
				2703.02

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2592.62

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 17 Sep 2019)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA7555U/17/09/2019 17:40**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FOG LAMP <i>— cut</i>	20.00	0.00	*201.50 FL <i>A</i>
2	1		*REAR TOWING COVER <i>— cut</i>	20.00	0.00	*5.40 FL <i>A</i>
F=Franchise part L=ListItemDisc						
Sub Total (\$\$)						206.90
- List Item Discount on L Items (\$\$)						41.38
Total Parts (\$\$)						165.52

ComfortDelGro Engineering Pte Ltd/SHA7555U/17/09/2019 17:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

COMFORTDELGRO ENGINEERING

Our Job Ref No 305333382

Date : 17/09/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SHA7555U

Date of Accident : 13/09/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SGP6825E
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1617.14
 - (b) Labour Charges ### \$561.00
 - Total for Part-By-Part Repair Cost** \$2178.14
###
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : Kalvin

Date : 18/9/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.09.2019

REPAIR ESTIMATE

Time: 17:41:53

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305333382
 REGN NO : SHA7555U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 16.09.2019 08:00
 ACCIDENT DATE : 13.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2288-G	IONIQ BEAM-RR BUMPER	1	294.80	20.00	235.84
0003	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60
0005	04-01-0104-2370-G	IONIQ LAMP ASSY-REAR FOG	1	201.50	20.00	160.88
0006	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00	2.00-	50.00
0007	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.20	135.70
0008	FNPS	NO PLATE(S)	1	25.00	0.02-	25.00
0009	04-01-0104-3819-G	IONIQ STAY-RR BUMPER LH	1	138.10	20.00	110.48
0010	04-01-0104-3919-G	IONIQ STAY-RR BUMPER RH	1	138.10	20.00	110.48
0011	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	47.50	20.00	38.00
0012	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1	5.40	20.00	4.32

SUB-TOTAL : 1,600.98

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.09.2019

REPAIR ESTIMATE

Time: 17:41:53

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305333382
REGN NO : SHA7555U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 16.09.2019 08:00
ACCIDENT DATE : 13.09.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT CHARGE	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 L	MERIMEN	11.00

SUB-TOTAL : 561.00

TOTAL : 2,161.98

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING









Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019 Sendback Est	16 Sep 2019 10:31 S\$2,427.10	17 Sep 2019 09:56 Edit Adj Rpt	S\$2,178.14 Edit Estimates	S\$2,178.14 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Sep 2019 17:38	17 Sep 2019 17:40 S\$165.52	17 Sep 2019 17:40			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: PHUA HUIZHAN , ID: S7303862F									
Main Claimant: CTPL									
Vehicle Reg. No.:	SHA7555U	Date of Loss:	13/09/2019 00:00 - :59 [12 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1907223	Policy/Cover Note No.:	MZ000374 (TP, Fire & Theft) Coverage: 22/12/2018 - 21/12/2019						
Vehicle Reg. No. (Insured):	SGP6825E	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ho Teng Boon Eliza]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 26/09/2019]									
Adj Asg. Remarks: OI HAS NOT RPT THE ACCDT									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA7555U (M1907223)
[SGP6825E]
TP
CTPL
Sep 13 2019 12:00AM
[PHUA HUIZHAN]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/09/19 10:31	Repairer Estimates	 Load HTM	<input checked="" type="checkbox"/>
2	17/09/19 17:40	Repairer Estimates Suppl. #1	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/09/19 07:51	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/09/19 07:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	18/09/19 07:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	18/09/19 07:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	18/09/19 07:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	18/09/19 07:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	18/09/19 07:55	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	18/09/19 07:55	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	18/09/19 07:55	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
37	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
38	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
39	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
40	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
41	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
42	18/09/19 07:55	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/09/19 10:32	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/09/19 09:31	SUPPLEMENTARY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19016349/K1SF3S2
 Date: 20/09/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MZ000374
 Claimant Vehicle No: SHA7555U Insured Vehicle No: SGP6825E
 Date of Loss: 13/09/2019 Nature of Claim: TP Claim No: M1907223

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA7555U
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU081764
 Reg. Date: 13/09/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU107504
 Colour: Blue Odometer: 177700 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Davanti 9 mm Rear Left Side: Davanti 9 mm
 Front Right Side: Davanti 9 mm Rear Right Side: Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,831.62	1,617.14	214.48	11.71
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	550.00	200.00	26.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,592.62	2,178.14	414.48	15.99
+ GST 7.00/7.00% (S\$)	181.49	152.47	29.02	15.99
Nett Amount (S\$)	2,774.11	2,330.61	443.50	15.99

INSPECTION

Date of Assignment: 17/09/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 16/09/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 Estimated Period of Repair: 2.0 days 59 Loyang Drive
 Singapore 508969

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7555U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Buckled	138.10 FL	*138.10 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Buckled	138.10 FL	*138.10 FL
5	1		*REAR BUMPER STAY	Serviceable	138.10 FL	*- FL
6	1		*REAR BUMPER CENTRE MLDG	Cracked	451.25 FL	*451.25 FL
7	1		*REAR BUMPER LOWER CENTRE MLDG	Cracked	47.50 FL	*47.50 FL
8	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	33.10 FL	*- FL
9	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	33.10 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Serviceable	63.80 FL	*- FL
12	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FS
13	1		*REVERSE SENSOR	Shorted	135.70 F	*135.70 FS
14	1		*REAR NUMBER PLATE	Cracked	25.00 F	*25.00 FS
Supplementary #1						
15	1		*REAR FOG LAMP	Cut	201.50 FL	*201.50 FL
16	1		*REAR TOWING COVER	Cut	5.40 FL	*5.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,236.85	1,968.75
- List Item Discount on L Items 20.00/20.00% (\$\$)	405.23	351.61
Total Parts (\$\$)	1,831.62	1,617.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT	New	250.00	200.00
3	WIRING	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	100.00	30.00
Gross Labour Cost (S\$)			750.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >