

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG19016350/R1SD3E2

Date: 23/12/2020

REFERENCE

Insured/Claimant: HOWE WEN LEE CHRISTOPHER MARK
Date of Loss: 11/09/2019

Policy No:
Nature of Claim: OD Claim No: 2467172466SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG733C	Engine No:	CVK068759
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF48JA232124
Reg. Date:	30/11/2018 (Man. Year: 2018)	Odometer:	10176 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$133,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,066.00	18,749.92	12,316.08	39.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	38,364.00	20,072.00	18,292.00	47.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	69,430.00	38,821.92	30,608.08	44.08
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	67,830.00	37,221.92	30,608.08	45.12
+ GST 7.00/7.00% (S\$)	4,748.10	2,605.53	2,142.57	45.12
Nett Amount (S\$)	72,578.10	39,827.45	32,750.65	45.12

INSPECTION

Date of Assignment: 16/09/2019

Date Inspected: 16/09/2019 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd (UBI)

Estimated Period of Repair: 28.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER-RH	Bent	700.00 FS	*559.60 FS
2	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
3	1	*FRONT FENDER CLOSING ELEMENT-RH	Serviceable	45.00 FS	*- FS
4	1	*FRONT FENDER BRACKET-RH	Serviceable	32.00 FS	*- FS
5	1	*FRONT FENDER DEFORMATION ELEMENT BRACKET-RH	Serviceable	45.00 FS	*- FS
6	1	*FRONT FENDER BRACKET	Serviceable	29.00 FS	*- FS
7	1	*FRONT FENDER BRACE-RH	Serviceable	107.00 FS	*- FS
8	1	*FRONT FENDER CLOSING ELEMENT-RH	Serviceable	30.00 FS	*- FS
9	1	*WHEEL HOUSING LINER-RH	Serviceable	220.00 FS	*- FS
10	1	*WHEEL HOUSING LINER ATTACHMENT PARTS-FRONT AND REAR	Serviceable	82.00 FS	*- FS
11	1	*FRONT FENDER END PLATE-RH	Serviceable	33.00 FS	*- FS
12	1	*STONE CHIP GUARD-RH	Cut	46.00 FS	*36.64 FS
13	1	*FENDER LEDGE COVER-RH INNER	Serviceable	28.00 FS	*- FS
14	1	*FENDER TOP LEDGE COVER - RH OUTER	Serviceable	21.00 FS	*- FS
15	1	*FRONT DOOR - RH	Bent	2,152.00 FS	*1,721.60 FS
16	1	*OUTER DOOR SEAL - RH	Necessary	185.00 FS	*147.60 FS
17	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
18	1	*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
19	1	*FRONT DOOR - LH	Bent	2,152.00 FS	*1,721.60 FS
20	1	*FRONT DOOR OUTER SEAL - LH	Necessary	185.00 FS	*147.60 FS
21	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
22	1	*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
23	2	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	975.00 FS	*- FS
24	2	*FRONT DOOR CATCH	Serviceable	191.00 FS	*- FS
25	1	*DOOR HANDLE TRIM PLATE - DRIVER DOOR	Serviceable	80.00 FS	*- FS
26	1	*DOOR HANDLE SENSOR - RH	Serviceable	208.00 FS	*- FS
27	1	*FRONT PERIPHERAL LIGHT - RH	Serviceable	66.00 FS	*- FS
28	1	*EXTERIOR DOOR HANDLE - RH	Cracked	35.00 FS	*27.52 FS
29	1	*FRONT DOOR - LOCK CYLINDER	Serviceable	492.00 FS	*- FS
30	1	*FRONT DOOR MOUNTING BAR - DRIVER DOOR	Serviceable	149.00 FS	*- FS
31	1	*EXTERIOR MIRROR MOUNTING - LH	Cracked	999.00 FS	*799.20 FS
32	1	*MIRROR CAP - LH	Cracked	220.00 FS	*175.60 FS
33	1	*MIRROR GLASS - LH	Cracked	1,132.00 FS	*905.60 FS
34	2	*FRONT DOOR CORNER TRIM - LH / RH	Serviceable	82.00 FS	*- FS
35	2	*WINDOW GUIDE TRIM STRIP - LH / RH	Serviceable	470.00 FS	*- FS
36	2	*WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH	Serviceable	560.00 FS	*- FS
37	1	*FRONT DOOR WINDOW - LH	Serviceable	265.00 FS	*- FS
38	1	*REAR DOOR - LH	Bent	2,152.00 FS	*1,721.60 FS
39	1	*REAR DOOR OUTER SEAL - LH	Necessary	185.00 FS	*147.60 FS
40	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
41	1	*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
42	1	*FRONT DOOR SEALING STRIP	Serviceable	15.00 FS	*- FS
43	1	*REAR DOOR - RH	Bent	2,152.00 FS	*1,721.60 FS
44	1	*REAR OUTER DOOR SEAL - RH	Necessary	185.00 FS	*147.60 FS
45	1	*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
46	1	*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
47	1	*REAR DOOR SEALING STRIP	Serviceable	15.00 FS	*- FS
48	2	*REAR DOOR ATTACHMENT PARTS	Not Necessary	1,030.00 FS	*- FS
49	2	*REAR DOOR CATCH	Serviceable	218.00 FS	*- FS
50	2	*REAR FENDER SIDE PANEL - LH / RH	Bent	4,886.00 FS	*3,908.80 FS
51	1	*REAR WINDOW	Necessary	1,049.00 FS	*839.20 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*PRIMER	Necessary	19.00 FS	*14.88 FS
53	2	*SIDE WINDOW - LH / RH	Necessary	1,122.00 FS	*896.80 FS
54	2	*WHEEL HOUSING LINER - LH / RH	Serviceable	446.00 FS	*- FS
55	2	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	164.00 FS	*- FS
56	1	*C-PILLAR REINFORCEMENT - RH LOWER	Serviceable	183.00 FS	*- FS
57	2	*WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH	Serviceable	670.00 FS	*- FS
58	2	*B-PILLAR TRIM - LH / RH	Serviceable	254.00 FS	*- FS
59	1	*FRONT RIM - RH	Scratched	200.00 FS	*200.00 FS
60	1	*REAR RIM - RH	Scratched	200.00 FS	*200.00 FS
61	1	*TYRE PRESSURE DATA PLATE	Necessary	35.00 FS	*27.36 FS
62	1	*ACRYLIC SEALANT	Necessary	360.00 FS	*360.00 FS
63	1	*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
64	1	*STONE CHIP	Necessary	360.00 FS	*360.00 FS
65	1	*METAL FILLER POWDER	Necessary	560.00 FS	*560.00 FS
66	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
67	2	*BOTH 1/4 GLASS SEALANT	Necessary	200.00 FS	*200.00 FS
68	1	*SUNDRIES	Necessary	800.00 FS	*137.36 FS
69	1	*DOOR LOCK RHS FRONT	Cut	487.00 FS	*389.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 31,066.00 18,749.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
3	TO RENEW REAR WINDSCREEN AND BOTH 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	900.00	900.00
4	TO INSTALL REAR WINDSCREEN FILM	New	400.00	400.00
5	TO REMOVE AND TRANSFER BOTH RHS FRONT AND REAR DOOR AND BOTH LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	1,120.00	1,120.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENTS	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
8	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, LHS FRONT DOOR, LHS REAR DOOR, REAR BUMPER AND LID. CUT OUT AND WELD BOTH REAR FENDER AND RHS SIDE INNER PANEL. RENEW RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, LHS FRONT DOOR, LHS REAR DOOR AND LHS WING MIRROR ASSY. TO REPAIR FRONT BUMPER, LHS FRONT FENDER, BONNET AND REAR BUMPER. }	New	16,800.00	8,000.00
9	RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED }	New	0.00	0.00
10	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH FRONT DOORS, BOTH REAR DOORS, LHS WING MIRROR COVER, DOOR HANDLES, BOTH REAR FENDERS, REAR BUMPER, RHS REAR SIDE INNER PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	14,800.00	5,500.00
11	TO RENEW RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
12	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	192.00
Gross Labour Cost (\$\$)			38,364.00	20,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >