

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016367/BKA3Q2

Date: 06/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900080568

Claimant
Vehicle No : SLA9669P **Insured Vehicle No :** SMJ9419K

Date of Loss: 15/09/2019 Nature of Claim: TP Claim No: 8777310919SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9669P		
Make & Model:	TOYOTA HARRIER, 2.0 PREMIUM CVT (A)	Engine No:	3ZRB718946
Reg. Date:	29/02/2016 (Man. Year: 2016)	Chassis No:	ZSU600070953
Colour:	Black	Odometer:	120681 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,732.12	5,390.80	10,341.32	65.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	2,280.00	2,890.00	55.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	20,902.12	7,670.80	13,231.32	63.30
Approved Total (Overridden) (\$)		6,100.00		
Nett Amount (\$)	20,902.12	6,100.00	14,802.12	70.82
+ Car Rental (7.0 x \$120.00/day) (\$)		840.00		
+ Doc/Search Fee (\$)		36.45		
Nett Liability (\$)		6,976.45		

INSPECTION

Date of Assignment: 16/09/2019

Date Inspected: 16/09/2019 Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd (KAKI BUKIT)

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,381.50 FL	*1,343.20 FL
2	1		*REAR BUMPER DIFFUSER	Broken	419.65 FL	*397.60 FL
3	1		*REAR BUMPER REFLECTOR	Not Damaged	193.60 FL	*- FL
4	1		*REAR BUMPER SPONGE	Not Damaged	160.20 FL	*- FL
5	2		*REAR BRACKET BRACKET	Not Damaged	137.00 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINERS	Necessary	202.40 FL	*164.00 FL
7	1		*REAR SMART KEYLESS SENSOR	Not Damaged	230.50 FL	*- FL
8	1		*TAILGATE	Repair	1,585.60 FL	*- FL
9	1		*TAILGATE LAMP LH	Not Damaged	454.20 FL	*- FL
10	1		*TAILGATE OUTER GARNISH	Not Damaged	490.50 FL	*- FL
11	1		*TAILGATE EMBLEM HARRIER	Necessary	102.50 FL	*72.10 FL
12	1		*TAILGATE WEATHERSTRIP	Not Damaged	348.00 FL	*- FL
13	1		*TAILLAMP LH	Broken	567.00 FL	*480.60 FL
14	1		*REAR FENDER LH	Dented	968.70 FL	*968.70 FL
15	1		*REAR FENDER INNER SHIELD	Not Damaged	456.00 FL	*- FL
16	1		*AIR VENT	Not Damaged	86.90 FL	*- FL
17	1		*FUEL COVER	Not Damaged	86.50 FL	*- FL
18	1		*REAR WHEEL HUB LH	Not Damaged	314.40 FL	*- FL
19	1		*REAR LOWER ARM LH	Not Damaged	506.00 FL	*- FL
20	1		*REAR UPPER ARM LH	Bent	397.80 FL	*331.00 FL
21	1		*REAR KNUCKLE ARM LH	Not Damaged	635.00 FL	*- FL
22	1		*REAR KNUCKLE ARM BEARING LH	Dented	198.00 FL	*198.00 FL
23	1		*REAR ABSORBER LH	Not Damaged	525.00 FL	*- FL
24	1		*REAR AXLE	Not Damaged	687.50 FL	*- FL
25	1		*REAR DOOR LH	Dented	1,376.50 FL	*1,318.10 FL
26	1		*REAR DOOR OUTER MOULDING LH	Necessary	158.00 FL	*158.00 FL
27	1		*REAR DOOR OUTER HANDLE LH	Not Damaged	158.00 FL	*- FL
28	1		*REAR DOOR WEATHERSTRIP	Cut	95.80 FL	*95.80 FL
29	1		*REAR DOOR CHROME GARNISH	Bent	189.00 FL	*121.10 FL
30	1		*REAR DOOR PANEL GARNISH (BODY) LH	Not Damaged	133.40 FL	*- FL
31	1		*REAR DOOR HINGE LH	Not Damaged	75.00 FL	*- FL
32	1		*REAR DOOR REGULATOR ASSY LH	Not Damaged	529.50 FL	*- FL
33	1		*REAR DOOR LOCK ASSY LH	Jammed	486.20 FL	*486.20 FL
34	1		*REAR DOOR TRIM LH	Not Damaged	315.60 FL	*- FL
35	1		*REAR DOOR CHECKER	Not Damaged	68.00 FL	*- FL
36	1		*REAR SIDE BODY FLOOR PANEL	Not Damaged	473.20 FL	*- FL
37	1		*FRONT DOOR LH	Repair	1,376.50 FL	*- FL
38	1		*FRONT DOOR OUTER MOULDING LH	Necessary	158.00 FL	*158.00 FL
39	1		*FRONT DOOR OUTER HANDLE LH	Not Damaged	158.00 FL	*- FL
40	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	95.80 FL	*- FL
41	1		*FRONT DOOR CHROME GARNISH	Bent	189.00 FL	*121.10 FL
42	1		*FRONT DOOR PANEL GARNISH (BODY) LH	Not Damaged	133.40 FL	*- FL
43	1		*FRONT DOOR HINGE LH	Not Damaged	75.00 FL	*- FL
44	1		*FRONT DOOR REGULATOR ASSY LH	Not Damaged	529.50 FL	*- FL
45	1		*FRONT DOOR LOCK ASSY LH	Not Damaged	486.20 FL	*- FL
46	1		*FRONT DOOR TRIM LH	Not Damaged	315.60 FL	*- FL
47	1		*FRONT DOOR CHECKER	Not Damaged	68.00 FL	*- FL
48	4		*REAR REVERSE SENSOR WITH MODULE	Shorted	400.00 FS	*200.00 FS
49	2		*QUARTER GLASS MOULDING	Not Damaged	60.00 FS	*- FS
50	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
51	1		*REAR FENDER INNER SHIELD CLIP	Not Damaged	60.00 FS	*- FS
52	1		*REAR TAILLAMP SEALANT	Not Damaged	50.00 FS	*- FS
53	2		*DOOR INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	19,487.65	6,673.50
				- List Item Discount on L Items 20.00/20.00% (S\$)	3,755.53	1,282.70
				Total Parts (S\$)	15,732.12	5,390.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R TAILGATE COMPONENTS	New	120.00	0.00
2	TO R&R SIDE GLASS AND	New	100.00	50.00
3	RUST PROOFING	New	200.00	80.00
4	REPAIR /CHECK WIRING	New	200.00	80.00
5	WHEEL ALIGNMENT	New	120.00	60.00
6	PANEL BEAT AND STRAIGHTEN ACCIDENT AREA	New	1,800.00	800.00
7	SPRAY AND PUTTY ACCIDENT AFFECTED AREAS	New	1,800.00	1,000.00
8	TO R&R UNDERCARRIAGE COMPONENT (BRAKEPAD,CALLIPER ETC)	New	150.00	0.00
9	TO R&R DOOR MECHANISM AND COMPONENT	New	300.00	100.00
10	TO R&R REAR UNDERCARRIAGE WORKS (LOWER ARM ,DRIVESHAFT ,ABSORBER)	New	150.00	80.00
11	TO R&R REAR AXLE	New	150.00	0.00
12	TO RESPRAY REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			5,170.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >