

ASS. REC. BY:

REF: CS/CT1 19016376/kyf3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irwin Tan Hui Ping of CT1

Date/Time: 16.9.19 17.18pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GU 7494T

Insured: GBJ 417U

at Workshop n/s K. Kim Hin Auto

Tel: 64527018

of B1C 34 Sin Ming Drive #01-114

97172631

Policy No: DMCRSV19157419000

Claim No: SNM 190204331002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.9.19 9.50a.m

Person Contacted: Jamad

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 160 Sin Ming Drive #02-20
	GU 7494T - X
	GBJ 417U - X
18/9	61Rp 82400 Car firm (Red \$4416-72, 64%)

ASS. REC. BY:

REF: 672/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s KKH

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 516,800

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 6/21 Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

1 File post toVehicle: GU 74947 Yr Regn: 06, 01
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Model: Toyota Liteace DX cc 2184Colour: White AC: Insured / Std / NI / NASp. Rating: 436604 T/Radio: Insured / Std / NI / NA

Engine: _____

Chassis: CR42 - 0018241Gen. Cond: Good / Fair / Poor / BurntSteer: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orHood: Nil / S/Rim / STD A/Rim orType: F / R 185R12X8

BS / DMS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYOTA OKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 7 mmL/Bal: 6 mm L/Bal: 7 mmD.O.I. 11/9/19 D.O.I. 17/9/19

Survey made at _____

Date of Damages: Nil / Rear / O/S / N/S / U/C / Rooftop orAcc N/S & R

Eng. / Chassis frame / Body Structure affected due to collision.

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

☐ : Prell. ReportDays Off Repair: 6Resurvey No. of Trip: 2

Survey Fee:

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/2/20 Typist

Add Fee:

☐ Shop Insp (\$☐ Shop Insp (\$☐ Shop Insp (\$☐ Shop Insp (\$

Transportation:

) S - RS, SI

) Fuel

) Others

Report Format:

Lump Sum / L.B.I. (\$

\$2900/-

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inrs Auth'd	Status
Main	16 Sep 2019		16 Sep 2019 17:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:		NG KOK HUA							
Vehicle Reg. No.:		GU7494T	Date of Loss:	11/09/2019 11:00 - :59					
Claim Type:		TP / SNM19D204331C02	Policy/Cover Note No.:	DMCVSN19157419000					
Vehicle Reg. No. (Insured):		GBJ4117U	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		K.kim Hin Auto Pte Ltd (HQ) BLK 34 SIN MING DRIVE, #01-114, 575708 Sin Ming - Tel: 64527018							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2019]							
Adj Asg. Remarks:		PLEASE SURVEY & REVERT							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 639B

Vehicle Details

Vehicle No.: GU7494T
Vehicle to be Exported: No
Intended Deregistration Date: 13 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: LITEACE MNL
Primary Colour: White
Manufacturing Year: 2001
Engine No.: 3C3911245
Chassis No.: CR420019241
Maximum Power Output: -
Open Market Value: \$19,650.00
Original Registration Date: 02 Jun 2001
First Registration Date: 02 Jun 2001
Transfer Count: 1
Actual ARF Paid: \$983.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 01 Jun 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$22,326.00
COE Rebate Amount: \$7,670.00
Total Rebate Amount: \$7,670.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Sep 2019

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30734

Vehicle Insured : GBJ 4117 U
Accident Date : 11-Sep-2019

Limit \$2400/-

Date : 14-Sep-2019

Our Ref : 190543 (CHINA) / LAVENDER

PAGE : 1

NG KOK HUA (MR)
Singapore

*Not Notified
61 Day @ 2400
Repair After Paint 6 days*

ESTIMATED COST OF REPAIR FOR TOYOTA LITEACE (2184cc)(2001) GU7494T

1 pc rear bumper		R 550.00	✓
2 pcs rear bumper side bracket (LH/RH)	@ S\$ 58.00	R 116.00	✓
1 pc n/s rear bumper reflector		CM 95.00	✓
1 pc tailgate		R 1,050.00	✓
1 pc tailgate lock		2m 229.00	✓
1 pc tailgate weatherstrip		R 445.00	✓
1 pc tailgate logo sticker		R 55.00	✓
1 pc tailgate 'Liteace' sticker		R 95.00	✓
1 pc tailgate glass moulding		R 95.00	✓
1 pc front bumper		R 335.10	✓
2 pcs front bumper side bracket	@ S\$ 48.00	R 96.00	✓
1 pc front bumper reinforcement		229.50	✓
10 pcs front bumper clips	@ S\$ 5.00	R 50.00	✓
1 pc front grille		CM 290.00	✓
1 pc front grille logo		R 65.00	✓
1 pc air con condenser		R 1,575.00	✓
1 pc air con fan assy		R 491.70	X

5,862.30

Less 25% : -1,465.58

4,396.72

1 pc tailgate '70km/h' sticker		R 25.00	sn
1 pc tailgate 'DX' sticker		R 20.00	sn
1 pc tailgate '750kg' sticker		R 80.00	sn
1 pc tailgate inner aluminium plate		R 340.00	sn
1 pc tailgate 'Diesel' sticker		R 60.00	sn
1 pc front number plate		R 35.00	sn
1 pc tailgate glass sealant		R 40.00	sn

*15sn
✓
40sn
R
20sn
20sn
✓*

L&K Auto Consultants hereby notify the Reparer of the following:

- To ensure better after sales service
- To display damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is via "Witness Preparation" form
- No illegal modification is allowed
- Supplementary items must be approved and be subject to final approval from Insurance Company

Accepted by Reparer
Signature:
Date:

Con't Page 2 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBJ 4117 U
Our Ref : 190543

Page : 2
No. : 30734

1 pc tailgate glass damping seal

20.00 sn ✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 600

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To transfer tailgate's fittings

80.00 60

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

120.00 100

To putty and respray on affected
portions.

680.00 400

Total : S\$ 6,816.72
=====

Singapore Dollars Six Thousand Eight Hundred
and Sixteen and Cents Seventy Two Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016376/KYF3N2

Date: 21/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19157419000
Claimant Vehicle No :	GU7494T	Insured Vehicle No :	GBJ4117U
Date of Loss:	11/09/2019	Nature of Claim:	TP
		Claim No:	SNM19D204331C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GU7494T	Engine No:	3C3911245
Make & Model:	TOYOTA LITEACE, 2.2 D MNL (M)	Chassis No:	CR420019241
Reg. Date:	02/06/2001 (Man. Year: 2001)	Odometer:	436604 km
Colour:	White		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R12X8	Rear Tyre Size:	165 R12X8
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,016.72	3,574.07	1,442.65	28.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,280.00	520.00	28.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,816.72	4,854.07	1,962.65	28.79
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	6,816.72	2,400.00	4,416.72	64.79
+ GST 7.00/7.00% (S\$)	477.17	168.00	309.17	64.79
Nett Amount (S\$)	7,293.89	2,568.00	4,725.89	64.79

INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	17/09/2019	Inspected At: 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722 REPAIRER: K.KIM HIN AUTO PTE LTD
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Feb 2020)	
Parts:	N/A	TOYOTA LITEACE 2.2 D MNL (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GU7494T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	550.00 FL	*550.00 FL
2	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Repair	116.00 FL	*- FL
3	1		*N/S REAR BUMPER REFLECTOR	Cracked	95.00 FL	*95.00 FL
4	1		*TAILGATE	Bent	1,050.00 FL	*1,050.00 FL
5	1		*TAILGATE LOCK	Jammed	229.00 FL	*229.00 FL
6	1		*TAILGATE WEATHERSTRIP	Serviceable	445.00 FL	*- FL
7	1		*TAILGATE LOGO STICKER	Necessary	55.00 FL	*55.00 FL
8	1		*TAILGATE LITEACE STICKER	Necessary	95.00 FL	*95.00 FL
9	1		*TAILGATE GLASS MOULDING	Necessary	95.00 FL	*95.00 FL
10	1		*FRONT BUMPER	Buckled	335.10 FL	*335.10 FL
11	1		*FRONT BUMPER SIDE BRACKET	N/s Distorted	96.00 FL	*48.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	229.50 FL	*- FL
13	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*FRONT GRILLE	Cracked	290.00 FL	*290.00 FL
15	1		*FRONT GRILLE LOGO	Necessary	65.00 FL	*65.00 FL
16	1		*AIR CON CONDENSER	Punctured	1,575.00 FL	*1,575.00 FL
17	1		*AIR CON FAN ASSY	Serviceable	491.70 FL	*- FL
18	1		*TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
19	1		*TAILGATE DX STICKER	Necessary	20.00 FS	*20.00 FS
20	1		*TAILGATE 750KG STICKER	Necessary	80.00 FS	*40.00 FS
21	1		*TAILGATE INNER ALUMINIUM PLATE	Serviceable	340.00 FS	*- FS
22	1		*TAILGATE DIESEL STICKER	Necessary	60.00 FS	*20.00 FS
23	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*20.00 FS
24	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*TAILGATE GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,482.30	4,707.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,465.58	1,133.03
Total Parts (\$\$)	5,016.72	3,574.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	800.00	600.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
3	TO TRANSFER TAILGATES FITTINGS	New	80.00	60.00
4	TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS.VACCUM AND RECHARGE GAS	New	120.00	100.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	680.00	400.00
Gross Labour Cost (S\$)			1,800.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >