

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016393/BPA3Q2
Date: 28/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800118816
Claimant Vehicle No :	SBR90X	Insured Vehicle No :	SLS1946Y
Date of Loss:	28/08/2019	Nature of Claim:	TP
		Claim No:	6807960274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBR90X		
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Engine No:	2ARH546859
Reg. Date:	12/06/2015 (Man. Year: 2015)	Chassis No:	AGH300014648
Colour:	White	Odometer:	59117 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,969.67	1,236.00	12,733.67	91.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	650.00	2,600.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,219.67	1,886.00	15,333.67	89.05
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	17,219.67	1,500.00	15,719.67	91.29
+ GST 7.00/7.00% (S\$)	1,205.38	105.00	1,100.38	91.29
Nett Amount (S\$)	18,425.05	1,605.00	16,820.05	91.29
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/09/2019	
Date Inspected:	17/09/2019	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	3.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

3/28/2021

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,426.00 FL	*1,380.40 FL
2	1		*REAR BUMPER SIDE RETAINER	Necessary	187.60 FL	*187.60 FL
3	1		*REAR BUMPER REFLECTOR	Not Damaged	164.00 FL	*- FL
4	1		*REAR BUMPER TOWING COVER	Not Damaged	82.00 FL	*- FL
5	1		*REAR BUMPER LOWER COVER	Not Damaged	348.60 FL	*- FL
6	1		*REAR END PANEL OUTER	Not Damaged	840.70 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Damaged	267.00 FL	*- FL
8	1		*TAILLAMP LH	Not Damaged	564.80 FL	*- FL
9	1		*TAILLAMP LOWER GARNISH	Not Damaged	326.10 FL	*- FL
10	1		*REAR BUMPER OUTER GARNISH SKIRTING	Not Damaged	784.10 FL	*- FL
11	1		*REAR BUMPER OUTER GARNISH CHROME LH	Not Damaged	289.60 FL	*- FL
12	1		*REAR BUMPER LAMP	Not Damaged	356.80 FL	*- FL
13	1		*REAR BUMPER LAMP CHROME GARNISH	Not Damaged	156.80 FL	*- FL
14	1		*REAR FENDER LH	Not Damaged	491.20 FL	*- FL
15	1		*EXHAUST	Not Damaged	987.50 FL	*- FL
16	1		*FUEL COVER	Not Damaged	89.20 FL	*- FL
17	1		*SIDE DOOR UPPER RAILING	Not Damaged	315.30 FL	*- FL
18	1		*SIDE DOOR LOWER RAILING	Not Damaged	315.30 FL	*- FL
19	1		*SIDE DOOR RH	Not Damaged	1,885.00 FL	*- FL
20	2		*SIDE DOOR HINGE	Not Damaged	253.80 FL	*- FL
21	1		*SIDE DOOR LOWER CATCH MECHANISM	Not Damaged	198.00 FL	*- FL
22	1		*SIDE DOOR INNER LOCK	Not Damaged	389.50 FL	*- FL
23	1		*SIDE DOOR LOCK SENSOR	Not Damaged	156.20 FL	*- FL
24	2		*SIDE DOOR STRIKER	Not Damaged	115.20 FL	*- FL
25	1		*SIDE DOOR WEATHERSTRIP	Not Damaged	225.60 FL	*- FL
26	1		*SIDE DOOR STEP PANEL	Not Damaged	357.20 FL	*- FL
27	1		*SIDE DOOR STEP PANEL GARNISH	Not Damaged	146.00 FL	*- FL
28	1		*SIDE BODY INNER PANEL	Not Damaged	450.00 FL	*- FL
29	1		*SIDE BODY PANEL LH	Not Damaged	867.90 FL	*- FL
30	1		*REAR KNUCKLE ARM LH	Not Damaged	389.60 FL	*- FL
31	1		*REAR KNUCKLE ARM BEARING LH	Not Damaged	266.80 FL	*- FL
32	1		*REAR LOWER ARM LH	Not Damaged	356.90 FL	*- FL
33	1		*REAR SHOCK ABSORBER LH	Not Damaged	267.80 FL	*- FL
34	1		*SIDE WINDSCREEN MOULDING	Not Damaged	250.00 FL	*- FL
35	1		*EXHAUST MUFFLER TIP	Not Damaged	325.60 FL	*- FL
36	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	1		*REAR BUMPER LOWER COVER CLIPS	Necessary	60.00 FS	*30.00 FS
38	4		*REAR DISTANCE SENSOR	Not Damaged	1,590.40 FS	*- FS
39	1		*TAILLAMP CLIPS	Not Damaged	40.00 FS	*- FS
40	1		*REAR END PANEL TOP GARNISH CLIPS	Not Damaged	69.00 FS	*- FS
41	1		*TAILGATE SEALANT	Not Damaged	100.00 FS	*- FS
42	1		*REAR END PANEL SEALANT	Not Damaged	100.00 FS	*- FS
43	1		*TAILLAMP SEAL	Not Damaged	60.00 FS	*- FS
44	1		*SIDE WINDSCREEN SEALANT	Not Damaged	150.00 FS	*- FS
45	1		*SPORT RIM WITH COATING	Not Damaged	325.00 FS	*- FS
46	1		*TYRE	Not Damaged	225.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,693.10	1,628.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,723.43	392.00
Total Parts (\$\$)	13,969.67	1,236.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R UNDERCARRIAGE COMPONENT	New	300.00	0.00
2	TO R&R DOOR COMPONENT WITH CHECKING	New	300.00	0.00
3	TO CHECK WIRING AND RECONNECT ALL ELECTRICAL SYSTEM	New	150.00	0.00
4	TO APPLY RUST PROOFING ON ACCIDENT AFFECTED AREAS	New	150.00	0.00
5	TO PANEL BEAT AND STRAIGHTEN ACCIDENT AFFECTED AREAS	New	1,000.00	400.00
6	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREAS	New	1,000.00	200.00
7	TO REMOVE AND REFIT EXHAUST SYSTEM	New	200.00	0.00
8	TO SPRAY REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			3,250.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >