



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 5888L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,658.00	-
1	REAR BOOT LOGO	SERVICEABLE	79.00	-
1	REAR BOOT LOCK	SERVICEABLE	272.50	-
1	REAR END PANEL	DENTED	1,018.50	883.00
1	REAR BUMPER	DENTED	1,950.00	1,587.00
1	REAR BUMPER INNER FRAME GARNISH	BROKEN	335.00	335.00
1	REAR BUMPER LOWER DIFUSSER	DEFORMED	885.00	885.00
2	REAR BUMPER REFLECTORS	N/S BROKEN	230.00	115.00
1	REAR BUMPER REINFORCEMENT	DENTED	685.00	685.00
2	REAR BUMPER SIDE RETAINERS	BROKEN	279.90	279.90
4	REAR BUMPER PDC SENSORS	SHORTED 2PCS ONLY	1,436.00	400.00
1	CONTROL MODULE FOR PARK ASSISTANT KIT	SERVICEABLE	345.00	-
1	CONTROL UNIT FOR SMART OPENER	SERVICEABLE	365.00	-
1	REAR EXHAUST HEAD SHIELD	SERVICEABLE	150.00	-
	LESS 5% DISCOUNT		-484.44	-
	LESS 10% DISCOUNT		-	-516.99
			9,204.46	4,652.91
<b><u>LABOUR</u></b>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	30.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		1,000.00	700.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
			2,480.00	1,370.00
GRAND TOTAL			11,684.46	6,022.91
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CC4/LPC19016413/Eda3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.