

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016449/AKA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800133914
Claimant
Vehicle No : SGG1796K **Insured Vehicle No :** SGA2932J
 Date of Loss: 14/09/2019 Nature of Claim: TP Claim No: 8064536325SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG1796K**
 Make & Model: NISSAN SUNNY, 1.6 EX (A) Engine No: QG16410089
 Reg. Date: 03/05/2006 (Man. Year: 2006) Chassis No: JN1CFAN16Z0101089
 Colour: Gold Odometer: 151336 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 700.00 | 300.00 | 400.00 | 57.14 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 700.00 | 300.00 | 400.00 | 57.14 |
| + GST 7.00/7.00% (S\$) | 49.00 | 21.00 | 28.00 | 57.14 |
| Nett Amount (S\$) | 749.00 | 321.00 | 428.00 | 57.14 |
| + Loss of Use (2.0 x S\$60.00/day) (S\$) | | 120.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 443.00 | | |

INSPECTION

Date of Assignment: 23/09/2019
 Date Inspected: 23/09/2019 Inspected At: Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717
 Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TO KNOCKING & PULL OUT FRONT LH PORTION & RENEW ABOVE PARTS | New | 100.00 | 50.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS | New | 600.00 | 250.00 |
| Gross Labour Cost (\$\$) | | | 700.00 | 300.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >