

1-000000

ASS. REC. BY:

REF

003/INC/19010558

avd3-1

Special Instruction

5/11/19

ASSIGNMENT (Office)

From (Person):

Motor Income

of

INC

Date/Time:

16/9/19

Estimated Cost

Bill to

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SMA 13291

Insured

STU 8627K

at Workshop no/s

Precision Motorworks

Tel

87433247

of 68 Kaki Bukit Ave 6 #01-03

Policy No

Claim No

MT/1047842-002

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

3/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Factorization

Date/Time

11/6

Person Contacted

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

pending both parties GIA Report

SMA 13291-X

STU 8627K-X

Dismantle: 12/6/2019

After repair: 14/6/2019

7/10/19

IS \$2450, 4 Days.
Submit (Red 7950, 7690)

[Signature]
4/10/2019

RECEIVED 07 OCT 2019

200

PREL BY

PRS
62.

REF

INC

ASSIGNMENT

(-2022)

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SMA1329L

at Workshop m/s Precision Motor

of 63 Kaki Bukit Ave 6 #01-02 Acker KB

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value \$70k

IDAC Accident Report _____

Consistent? Yes or No

GIA / PR Seen _____

Consistent? Yes or No

Est. Repairs _____

4

days

Res: _____

Yes or No

Lum Sum _____

%

3 Val.

Yes or No

CA / REV / REP. / 24 HRS

Date _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$3000 - \$4000

Veh No

SMA1329L

(Regn)

24 May 2012

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 328i 2.0 cc 1997

Colour

white

A/C:

Insured / Std / NI / NA

Sp Reading

115961

T/Radio:

Insured / Std / NI / NA

Eng/No

C/No:

WBA 3A520X0F 253714

Gen. Cond.

Good / Fair / Poor / Burnt

Steering:

Insured / Jammed / Leaked / Burnt or

Brake:

Insured / Jammed / Leaked / Burnt or

Modi

Nil / Sharn / STD / A/P or

Tyre Size:

F:

255 / 35 ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

5

mm

R/Bal

5

mm

L/Bal

5

mm

L/Bal

5

mm

D.O.A

D.O.I

11-06-19

Survey held at

w/s

4:30pm

Des. of Damages

Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Meet eng (\$

Survey Fee

Transportation

2 x R6 \$

Printed

Checked

Noted

Report Format: PRS

Long: Sma / L.E. or

Nivitha (LKK Auto)

From: do_not_reply@income.com.sg
Sent: Monday, 16 September 2019 5:06 PM
To: assignments@lkkauto.com
Subject: MT/1047842-002 - Claim Involving SJU8627K / SMA1329L on 03 Jun 2019
Attachments: LOD2 2019-9-10.pdf.PDF; TP Survey Report .PDF;
EBGI-300002963-0000009815-1568623580170_EBAOGICLM_DLET_MT.pdf

Dear Sir / Madam,

We refer to the above claim.

Enclosed is the letter / document for your necessary attention.

Yours sincerely

Motor Insurance
Income

Note: This is a system generated email. Please do not reply to this email.

PAR Automotive Consultancy

Regn. No: 129869741

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0339-19-PM

24 June 2019

Sikiat Liong Hing Fong
164A Yung Kuang Road #12-50
Singapore 611184

INVOICE No. 0339-19-PM

Vehicle No. SMA1329L

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$885.00
Total amount payable		<u>\$885.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131

Report No: 0339-19-PM

24 June 2019

ACCIDENT VEHICLE SURVEY REPORT

Sikiat Liong Hing Fong
164A Yung Kuang Road #12-50
Singapore 611184

VEHICLE INFORMATION:

Vehicle Reg No.:	SMA1329L	Odometer:	115961km
Make & Model:	BMW 328	Colour:	White
Chassis number:	WBA3A520XOF253714	Date of accident:	03/06/2019
Year of Regn.:	04/05/2012	Date inspected:	10/06/2019
Repairer at:	Precision Motorworks	Date inspected (After Repair):	14/06/2019
	68 Kaki Bukit Ave 6 ARK @ KB #01-02		
	Singapore 417896		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	225/40ZR19
Rear:	5mm/Michelin	5mm/Michelin	255/35ZR19

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0339-19-PM

Vehicle No: SMA1329L

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear boot lid <i>Repair</i>	1	buckled	1,590.00	X 1,590.00
Rear boot lid logo "BMW"	1	necessary	78.10	/ 78.10
Rear boot lid damper RH/LH	2	reuse	230.00	0.00
Rear boot lid hinge RH/LH	2	repair	258.00	0.00
Rear boot lid inner trim board	1	deformed	186.00	X 186.00
Rear boot lid mechanism lock	1	bent	182.00	X 182.00
Rear number plate lamp RH/LH	2	fractured	84.00	X 84.00
Rear boot lid outer key lock	1	reuse	182.40	0.00
Rear boot lid outer lock & handle switch	1	reuse	64.20	0.00
Rear boot lid reflector lamp back rubber gasket RH/LH	2	necessary	70.00	X 70.00
Rear boot lid reflector lamp RH/LH	2	fractured	578.00	X 578.00
Rear boot lid weatherstrip	1	deformed	187.00	X 187.00
Rear bumper	1	squashed	1,259.00	/ 1,259.00
Rear bumper centre top retainer	1	deformed	45.00	X 45.00
Rear bumper lower lip	1	deformed	645.00	89 645.00
Rear bumper reinforcement	1	bent	653.00	457 653.00
Rear bumper reverse sensor	2	shorted	960.00	480 960.00
Rear bumper reverse sensor holder	4	necessary	280.00	X 280.00
Rear bumper reverse sensor rubber seal	4	necessary	42.80	X 42.80
Rear bumper reverse sensor wire harness - set	1	reuse	320.00	0.00
Rear bumper side retainer RH/LH <i>CH-RE RH X SVC</i>	2	necessary	171.20	85.6 171.20
Rear bumper tow hook cover	1	reuse	37.45	0.00
Rear end panel	1	repair	1,015.00	0.00
Rear end panel inner top garnish	1	fractured	213.00	X 213.00
Rear end panel inner top garnish clip	4	necessary	26.00	X 26.00
Rear end panel lock striker	1	repair	89.00	0.00
Rear exhaust aluminium hear shield	1	deformed	208.00	X 208.00
Rear exhaust end chrome pipe RH/LH	2	distorted	378.00	X 378.00
Rear exhaust gasket	1	necessary	37.45	X 37.45
Rear exhaust rubber mounting	3	distorted	120.00	X 120.00
Rear exhaust silencer box	1	bent	1,090.00	X 1,090.00
Rear tail lamp back rubber gasket RH/LH	2	necessary	79.18	X 79.18
Rear tail lamp clip RH/LH	8	necessary	52.00	X 52.00
Rear tail lamp inner panel RH/LH	2	repair	492.00	0.00
Rear tail lamp RH/LH <i>48.7</i>	2	fractured	1,536.00	X 1,536.00

5% = 2326.26

Rear tail lamp lower bracket RH/LH

2 bent

130.20

~~130.20~~ SVC

Subtotal before discount

13,568.98

10,880.93

Percentage discount 0% and 5%

0.00

544.05

Sub-total 1

13,568.98

10,336.88

Rear boot lid inner trim board clip - set

1 necessary

30.00

~~30.00~~ SVC

Rear number plate c/w holder

1 reuse

50.00

0.00

Rear bumper lower spoiler No such item

1 deformed

1,200.00

~~1,200.00~~

Rear bumper clip - set

1 necessary

30.00

~~30.00~~

Subtotal before discount

1,310.00

1,260.00

Percentage discount 0% and 0%

0.00

0.00

Sub-total 2

1,310.00

1,260.00

Parts-total

14,878.98

11,596.88

LABOUR

1 To straighten and panel beating rear end panel and rear frame members. To remove and refit above parts.

1,000.00

~~300 500.00~~

2 To putty, re-spray painting and polish affected areas

1,000.00

~~400 750.00~~

3 To check and rectify wiring system

80.00

~~40 50.00~~

4 To remove and refit rear exhaust pipe

180.00

~~140.00~~

5 To rust proof affected areas

90.00

~~30.00~~

Labour total

2,350.00

1,470.00

Parts & Labour total

17,228.98

13,066.88

Results of inspection of the accident vehicle are as shown above

We have taken into consideration the age and condition of the vehicle in our recommendation

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$10,400.00

4

B J LOH (Eng. MIML AIRTEL)
Automotive Appraiser

3096.26
20%: 2450
4 Days.

Your Ref: SMA1329L

Our Ref: MT/CA/TP/036/1047842-002/RD

16 Sep 2019

LKK AUTO CONSULTANTS PTE LTD
51 UBI AVENUE 1
#01-25 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408933

**WITHOUT PREJUDICE
SAVE AS TO COSTS
BY FAX & POST**

Dear Sir/Madam

**CLAIM NUMBER: MT/1047842-002
ACCIDENT INVOLVING SJU8627K / SMA1329L on 3 Jun 2019**

We refer to the claim.

Please let us have your complete PRS report/recommendation.

If you have any queries, please contact Rajeswary Doraisamy at 6430 7934 or email us at rajeswary.doraisamy@income.com.sg.

Yours sincerely



Jenny Pe
Deputy Vice President
Motor Insurance



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19010358/Gvd3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 07-10-2019

189556



Code : INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 8627K	Veh. Inspected	SMA 1329L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1047842-002	Excess (\$)	0.00
Assign From	MOTOR INSURANCE INCOME	Assign Date	16/09/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W 328I 2.0	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA3A520X0F253714	Colour	WHITE
Odometer	115961	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 ZR19	MICHELIN	5 mm
L/H Front Tyre	255/35 ZR19	MICHELIN	5 mm
R/H Rear Tyre	255/35 ZR19	MICHELIN	5 mm
L/H Rear Tyre	255/35 ZR19	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/06/2019	Inspection Date	11/06/2019
Survey held at	PRECISION MOTORWORKS PTE LTD 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB SINGAPORE 417896		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 1329L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,590.00	-
1	REAR BOOT LID LOGO "BMW"	NECESSARY	78.10	78.10
2	REAR BOOT LID DAMPER RH/LH	REUSE	230.00	-
2	REAR BOOT LID HINGE RH/LH	TO REPAIR SEE LABOUR	258.00	-
1	REAR BOOT LID INNER TRIM BOARD	SERVICEABLE	186.00	-
1	REAR BOOT LID MECHANISM LOCK	SERVICEABLE	182.00	-
2	REAR NUMBER PLATE LAMP RH/LH	SERVICEABLE	84.00	-
1	REAR BOOT LID OUTER KEY LOCK	SERVICEABLE	182.40	-
1	REAR BOOT LID OUTER LOCK & HANDLE SWITCH	SERVICEABLE	64.20	-
2	REAR BOOT LID REFLECTOR LAMP BACK RUBBER GASKET RH/LH	SERVICEABLE	70.00	-
2	REAR BOOT LID REFLECTOR LAMP RH/LH	SERVICEABLE	578.00	-
1	REAR BOOT LID WEATHERSTRIP	SERVICEABLE	187.00	-
1	REAR BUMPER	SQUASHED	1,259.00	1,259.00
1	REAR BUMPER CENTRE TP RETAINER	SERVICEABLE	45.00	-
1	REAR BUMPER LOWER LIP	DEFORMED	645.00	89.00
1	REAR BUMPER REINFORCEMENT	BENT	653.00	457.00
4	REAR BUMPER REVERSE SENSOR	SHORTED 2PCS ONLY	960.00	480.00
4	REAR BUMPER REVERSE SENSOR HOLDER	SERVICEABLE	280.00	-
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL	SERVICEABLE	42.80	-
1	SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	SERVICEABLE	320.00	-
2	REAR BUMPER SIDE RETAINER RH/LH	N/S DEFORMED / O/S SERVICEABLE	171.20	85.60
1	REAR BUMPER TOW HOOK COVER	REUSE	37.45	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,015.00	-
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	213.00	-
4	REAR END PANEL INNER TOP GARNISH CLIP	SERVICEABLE	26.00	-
1	REAR END PANEL LOCK STRIKER	SERVICEABLE	89.00	-
1	REAR EXHAUST ALUMINIUM HEAR SHIELD	SERVICEABLE	208.00	-
2	REAR EXHAUST END CHROME PIPE RH/LH	SERVICEABLE	378.00	-
1	REAR EXHAUST GASKET	SERVICEABLE	37.45	-
3	REAR EXHAUST RUBBER MOUNTING	SERVICEABLE	120.00	-

Report Ref No. CS3/INC19010358/Gvd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	1,090.00	-
2	REAR TAIL LAMP BACK RUBBER GASKET RH/LH	SERVICEABLE	79.18	-
8	REAR TAIL LAMP CLIP RH/LH	SERVICEABLE	52.00	-
2	REAR TAIL LAMP INNER PANEL RH/LH	SERVICEABLE	492.00	-
2	REAR TAIL LAMP RH/LH	SERVICEABLE	1,536.00	-
2	REAR TAIL LAMP LOWER BRACKET RH/LH	SERVICEABLE	130.20	-
	LESS 5% DISCOUNT		-	-122.43
			13,568.98	2,326.27
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BOOT LID INNER TRIM BOARD CLIP (SN)	SERVICEABLE	30.00	-
1	REAR NUMBER PLATE C/W HOLDER (SN)	REUSE	50.00	-
1	REAR BUMPER LOWER SPOILER (SN)	NO SUCH PARTS	1,200.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			1,310.00	30.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING REAR END PANEL AND REAR FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS. INCLUISVE OF THE REPAIR OF REAR BOOT LID, REAR BOOT LID HINGE RH/LH AND REAR END PANEL.		1,000.00	300.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,000.00	400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	40.00
	TO REMOVE AND REFIT REAR EXHAUST PIPE.	NOT NECESSARY	180.00	-
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	90.00	-
			2,350.00	740.00
	GRAND TOTAL		17,228.98	3,096.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS3/INC19010358/Gvd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.