

Report no: 395M0919.SH
Vehicle no: FBH6669R

A SPARE PARTS

Assessed Condition Qty

Description
Front fender
Front fender inner brace bracket
Front fork assy LH/RH
Headlamp assy
Handle bar
Handle bar end balancer set
Mirror set
Brake lever
Exhaust pipe chrome cover
(Special nett)
Front number plate
Rear box

1 abraded
1 twisted/distorted
2 bent
1 dented/scraped
1 bent
1 abraded
1 scraped
1 end abraded
1 dented/bent
Subtotal of the above
Discount 10%
Subtotal 1:
1 edge abraded
1 scraped
Subtotal 2:

Repaired's Amount	Revised Amount
110.00	110.00
35.00	35.00
560.00	560.00
280.00	280.00
85.00	85.00
40.00	40.00
90.00	90.00
25.00	25.00
55.00	55.00
1,280.00	1,280.00
128.00	128.00
1,152.00	1,152.00
10.00	10.00
220.00	220.00
230.00	230.00

Total cost of parts:

1,382.00	1,382.00
----------	----------

Total cost of labour:

670.00	480.00
--------	--------

Total cost of repair:

2,052.00	1,862.00
----------	----------

Labour charges.
Towing fee (2x)
Painting charges.

B LABOUR

70.00	60.00
450.00	300.00
150.00	120.00