

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





**CARSMITH PRIVATE LIMITED**  
25 TEBAN GARDEN ROAD #10-181  
SINGAPORE  
Singapore 600025  
+65 85580000  
carsmithpl@gmail.com

## Invoice

**INVOICE TO**  
SFW8616D

**INVOICE NO.** 1047  
**DATE** 05/08/2019  
**DUE DATE** 04/09/2019  
**TERMS** Net 30

DATE	SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
05/08/2019	<b>LUMP SUM REPAIR AS RECOMMENDED &amp; AGREED WITH SURVEYOR</b>		0	7,100.00	7,100.00

BALANCE DUE

**S\$7,100.00**

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Yeo Wang Ping  
C/o: Carsmith Private Limited  
13 Kaki Bukit Road 4, #01-20  
Bartley Biz Centre, Singapore 417807

Date : 31 July 2019  
Our ref : CSPL/07/1912/TP

Accident Date : 12 July 2019  
Inspection Date : 19 July 2019  
Repairer Name : Carsmith Private Limited  
13 Kaki Bukit Road 4, #01-20  
Bartley Biz Centre, Singapore 417807

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SFW 8616 D  
Make / Model : Volkswagen Passat  
Chassis No : WVVZZZ3CZJE193991  
Engine No : CJS279624

Year / Capacity : 2018 / 1798 cc  
Colour : White  
Mileage : 17292

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Pirelli	215/55 R17	5 mm	Sport
Front Offside	Pirelli	215/55 R17	5 mm	Sport
Rear Nearside	Pirelli	215/55 R17	5 mm	Sport
Rear Offside	Pirelli	215/55 R17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front o/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: **84** copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 7,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Vehicle Registration No: SFW 8616 D

Our Ref No: CSPL/07/1912/TP 2017

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Front o/s headlamp	Damage	\$ 2,090.00	\$ 2,090.00 <i>scr / \$1600</i>
1	Front o/s headlamp nozzle pen	Damage	\$ 165.00	\$ 165.00 <i>xnn</i>
1	Front o/s headlamp nozzle pen cover	Damage	\$ 48.00	\$ 48.00 <i>scr /</i>
1	Front grille with chrome assy	Damage	\$ 1,148.00	\$ 1,148.00 <i>cra / \$350</i>
1	Front grille logo	Necessary	\$ 165.00	\$ 165.00 <i>ncc / \$110</i>
1	Front bumper	Damage	\$ 1,364.00	\$ 1,364.00 <i>cut / \$1210</i>
1	Front bumper clip (1 set)	Necessary	\$ 135.00	\$ 135.00 <i>rel / \$50</i>
1	Front bumper inner sponge	Damage	\$ 138.60	\$ 138.60 <i>pr /</i>
1	Front bumper o/s fog lamp	Damage	\$ 244.20	\$ 244.20 <i>xnn</i>
1	Front bumper o/s fog lamp cover	Damage	\$ 127.60	\$ 127.60 <i>br /</i>
1	Front bumper lower grille	Damage	\$ 451.60	\$ 451.60 <i>br / \$330</i>
2	Front bumper PDC sensors	Damage	\$ 374.00	\$ 374.00 <i>scr /</i>
1	Front bumper reinforcement	Intact	\$ 644.60	
2	Front bumper side retainers	Necessary	\$ 79.20	\$ 79.20 <i>rel / \$60</i>
1	Front bumper undercover	Damage	\$ 246.00	\$ 246.00 <i>xnn</i>
1	Front bumper side chrome moulding	Damage	\$ 275.00	\$ 275.00 <i>cra /</i>
1	Front bumper centre chrome moulding	Damage	\$ 285.00	\$ 285.00 <i>scr /</i>
1	Front o/s fender	Damage	\$ 583.00	\$ 583.00 <i>br /</i>
1	Horn	Damage	\$ 89.00	\$ 89.00 <i>scr / \$78</i>
			<b>\$ 8,652.80</b>	<b>\$ 8,008.20</b> <i>\$5965.20</i>
			<i>Less 10%</i> \$ 865.28	\$ 800.82 <i>\$596.52</i>
<b>Total Cost - List Items</b>			<b>\$ 7,787.52</b>	<b>\$ 7,207.38</b> <i>\$5568.68</i>

**Total cost of parts**

**\$ 7,787.52 \$ 7,207.38**

Vehicle Registration No: SFW 8616 D

Our Ref No: CSPL/07/1912/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 7,787.52</b>	<b>\$ 7,207.38</b>

## LABOUR

- |   |  |             |                        |
|---|--|-------------|------------------------|
| 1 | To check wiring , lighting and resetting headlamps focussing.  | \$ 80.00    | \$ 50.00 <i>\$30</i>   |
| 2 | To remove and refit front sensor.  | \$ 150.00   | \$ 120.00 <i>\$50</i>  |
| 3 | To apply undercoating on repaired and replaced panel.  | \$ 100.00   | \$ 60.00 <i>\$50</i>   |
| 4 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,080.00 | \$ 750.00 <i>\$400</i> |
| 5 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.  | \$ 1,000.00 | \$ 660.00 <i>\$450</i> |

## **GRAND TOTAL**

*Labour : \$ 980*

<b>\$ 10,197.52</b>	<b>\$ 8,847.38</b>
---------------------	--------------------

List Item : \$5368.68  
 Labour : \$ 980  
 total : \$ \$6348.68  
 aft 1/52% : \$ 5050.00 \*

5245

Vehicle Registration No: SFW 8616 D

Our Ref No: CSPL/07/1912/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**



Cheong K. H  
Automotive Appraiser



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC19012718/Fqf3s2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 20-09-2019		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBF 4939K	Veh. Inspected	SFW 8616D	
Policy No.	Z18VC05001211	Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/022095	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	18/09/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN PASSAT	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WVWZZZ3CZJE193991	Colour	WHITE	
Odometer	17292	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	PIRELLI	6 mm	
L/H Front Tyre	215/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	215/55 R17	PIRELLI	5 mm	
L/H Rear Tyre	215/55 R17	PIRELLI	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/07/2019	Inspection Date	19/07/2019	
Survey held at	CARSMITH PTE LTD - 13 KAKI BUKIT RD 4 #01-20			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 8616D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT O/S HEADLAMP	SCRATCHED	2,090.00	1,600.00
1	FRONT O/S HEADLAMP NOZZLE PEN	NOT NECESSARY	165.00	-
1	FRONT O/S HEADLAMP NOZZLE PEN COVER	SCRATCHED	48.00	48.00
1	FRONT GRILLE WITH CHROME ASSY	CRACKED	1,148.00	880.00
1	FRONT GRILLE LOGO	NECESSARY	165.00	110.00
1	FRONT BUMPER	CUT	1,364.00	1,210.00
1	SET FRONT BUMPER CLIP	NECESSARY	135.00	50.00
1	FRONT BUMPER INNER SPONGE	BROKEN	138.60	138.60
1	FRONT BUMPER O/S FOG LAMP	NOT NECESSARY	244.20	-
1	FRONT BUMPER O/S FOG LAMP COVER	BROKEN	127.60	127.60
1	FRONT BUMPER LOWER GRILLE	BROKEN	451.60	330.00
2	FRONT BUMPER PDC SENSORS	SHORT CIRCUIT	374.00	374.00
1	FRONT BUMPER REINFORCEMENT	INTACT	644.60	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	79.20	60.00
1	FRONT BUMPER UNDERCOVER	NOT NECESSARY	246.00	-
1	FRONT BUMPER SIDE CHROME MOULDING	CRACKED	275.00	275.00
1	FRONT BUMPER CENTRE CHROME MOULDING	SCRATCHED	285.00	285.00
1	FRONT O/S FENDER	BUCKLED	583.00	583.00
1	HORN	SCRATCHED	89.00	78.00
	LESS 10% DISCOUNT		-865.28	-614.92
			7,787.52	5,534.28
<b>LABOUR</b>				
	TO CHECK WIRING, LIGHTING AND RESETTNG HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT FRONT SENSOR.		150.00	50.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	50.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,080.00	400.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED POSITIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	450.00
			2,410.00	980.00

Report Ref No. CS3/LPC19012718/Fqf3s2-1



GRAND TOTAL		10,197.52	6,514.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00

Report Ref No. CS3/LPC19012718/Fqf3s2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.