

ASS. REC. BY:

REF: es/INC19016484/Dxd3⁷²

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Annie Koh

of

INC

Date/Time: 9:29am @ 18/9/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 2038T

Insured:

SGB 5888D

at Workshop m/s

Chunni Motor

Tel:

GS425119

of

10 AMK Ind. Park 2A #01-05106

Policy No:

Claim No:

MT/1062709-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:21am @ 18/9/19

Person Contacted:

Lynn

Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SHC 2038T-CS / FC1/19016477/d3	
	SGB 5888D-X	

2019: 15/09/2019

ASSIGNMENT

CRB 2026 Oct

SHC 2038 T

Oct 2018

Veh No

(1 Regn)

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

c.c 1580

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

192040

T/Radio: Insured / Std / NI / NA

Eng/No:

G4LEJU112150

C/No:

KMHCB51CVK1105095

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195 / 65 R 15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dewanti

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A

15/18/09/2019

D.O.I

18/09/2019

Survey held at

Chunni AMK

10.34am

Des. of Damages (Fr) (Rear) O/S / N/S / U/C / Rooftop of

The U/C / Chassis frame / Body Structure affected due to collision

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

at Workshop no

of

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs: 12 ~~10~~ days

Res.: Yes or No

Lum Sum:

20

3 Val: Yes or No

CA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

NTUC SGB 5888 D

15/10/19

Invoice 2/15 20000/- 5.10 12 dgs of a
(Red 18,518.70, 4870)

RECEIVED 16 OCT 2019

Date/Time File Refs



Preli. Report

Date/Time File Refs



Final Report

Date/Time File Refs

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Site Insp

Interview

Tech. Insp

Welding

Add Fee:



Site Insp



Interview



Tech. Insp



Welding

16/10 - typist

TP

4/5 \$ 20,000p

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Wednesday, 18 September 2019 9:44 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Wednesday, 18 September 2019 9:29 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----	--------------------

1	Eng Huey Huey	MT/1060773-002	SLD8401K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188	SJA5936T	31/8/19	
2	Azhari	MT/1062866-001	SKX9109E	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728	SLB5957D	16/9/19	
3		PENDING ADVISE	YN6081G	SMRT AUTOMOTIVE SERVICES PTE LTD	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Mr. Tan YuWei / 98506093			
4	Wo Jessie	MT/1062709-002	SHC2038T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119	SGB5888D	15/9/19	Ms Irene at 6542 7162

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg





Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

MCD819122623 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 16/09/2019 15:11
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/09/2019 15:11
 Date Of Accident 15/09/2019 21:10
 Exact Location Of Accident AIRPORT BLVD TOWARDS TERMINAL 3
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC2038T
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model IONIQ HYBRID
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver TAN PENG HUAT
 NRIC No S1369829E
 Date Of Birth 01/01/1959
 Occupation OUTDOOR
 Date Of Driving Pass 26/04/1980
 Driving Experience 39 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90054654
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 514 JELAPANG ROAD
 #04-237
Postcode 670514
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1

NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] BUKIT PANJANG NPC
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20190916/2021

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGB5888D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver QISTINA ANGEL BINTE JAMIL
NRIC/Passport Number
Contact Number 82988241
Address
Postcode
Insurance Company Name

Nature Of Damage FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMA3836B
Vehicle Make/Model/Colour MAZDA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 98892394
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHB2991X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver NEVILLE JOHN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN(DRIVER)
Approximate Age
Injuries Sustain UNSURE
Injured person in which vehicle? SGB5888D
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name UNKNOWN(PAX)
Approximate Age
Injuries Sustain UNSURE
Injured person in which vehicle? SGB5888D
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R



Policyholder's Signature
Date & Time: 16.09.2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16.09.2019@15:15hrs

Lisa

Reporting Centre Personnel's Signature
Name: -
NRIC/FIN No.:

D-SHB 2991X (CCPL)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

T/20190916/2021

D-SHB 2991X Mr Neville John.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190916/2021

1 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20190916/2021

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/09/2019 10:33		Vide Report No.:		Station Diary No.: 29	
Informant's Particulars					
Name of Informant: TAN PENG HUAT			Address: APT BLK 514 JELAPANG ROAD #04-237 SINGAPORE 670514		
ID Type / ID No.: NRIC NO / S1369829E			Contact No.: Home/Office: Mobile: 90054654		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 08/02/1959	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/09/2019 21:10	Type of Location: Straight Road
Location: Along Road 1 AIRPORT BOULEVARD ECP Towards Changi.				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
B SGB5888D	Car				Seriously Damaged	2
D SHB2991X	Car				Slightly Damaged	1
A SHC2038T	Car	HYUNDAI	AE IONIQ HEV 1.6 DCT	Blue	Seriously Damaged	1
C SMA3836B	Car	MAZDA	MAZDA3 SEDAN 1.5 AT LED EU6		Slightly Damaged	1

**SINGAPORE
POLICE FORCE**

T/20190916/2021

2 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20190916/2021

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN PENG HUAT	ID No.	S1369829E
Related Vehicle	NIL	Contact No.	90054654
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 15/09/2019 at about 2110hrs, I was driving my taxi bearing the registration number SHC2038T, along ECP towards Changi, I was driving on the 4th lane of the road when I notice there was road works on the 5th lane of the road which I was traveling along. Since I was traveling the 4th lane I did not change lane and continue driving along the 4th lane. I notice the vehicle in front of me, bearing registration number SMA3836B, applying breaks as the breaking lights were on, hence I also started to apply my breaks to slow down and match the speed of the vehicle in front of me. All of a sudden, the vehicle came to a stop after breaking a slowing down. I manage to apply my breaks however, my vehicle happened to touch onto the vehicle in front of me.

A few moments after, I heard a loud bang coming from the back of my vehicle, and my vehicle jerked forward and pushed the front vehicle forward. Subsequently, I notice that there is another yellow taxi, which stop behind of the 3rd vehicle, possible due to the chain collision. We stopped our vehicle, got out and exchanged particulars. Subsequently, Traffic Police and ambulance arrived and conveyed driver of the 3rd vehicle in the chain collision, SGB5888D, to the nearest hospital. The 1st vehicle driver, myself and the 4th vehicle driver of the yellow taxi bearing SHB2991X, did not suffer any serious injuries.

The Traffic Police collected my in car camera footage and also the camera footage of the other drivers. I will be lodging a report with my taxi company myself.

Vide Report No. P/20190915/0076



**SINGAPORE
POLICE FORCE**



T/20190916/2021

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 3

Report No. T/20190916/2021

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

SC2 TAI HONG XUAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/09/2019 10:33

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MARIAH BINTE ZAKARIA

Contact No.: 65476433

Classification Of Case:

SN 117

Authentication Stamp

NP168



Signature:

Singapore Police Force

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2038T

DATE : 16.09.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Kind

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>broken</i>			\$ 1,227.50
	Speaker Assy- VESS <i>NH</i>			\$ 354.40
	Unit Assy-SMART CRU (Radar Sensor) <i>BT / money broken</i>			\$ 2,910.90
	Front Bumper Cover <i>broken</i>			\$ 418.30
	Front Bumper Sponge <i>broken</i>			\$ 86.90
	Front Bumper Reinforcement <i>BT</i>			\$ 1,075.10
	Front Bumper Bracket Top (LH/RH) <i>NH</i>		\$ 35.00	\$ 70.00
	Front Bumper Bracket (LH/RH) <i>NH</i>		\$ 28.00	\$ 56.00
	Front Bumper Clips 10 pcs <i>NH</i>			\$ 22.00
	Front Bumper Centre Moulding <i>broken</i>			\$ 188.00
	Headlamp Support Panel Assy <i>BT broken</i>			\$ 949.30
	Headlamp (LH/RH) <i>money broken</i>		\$ 1,198.80	\$ 2,397.60
	Radiator <i>BT</i>			\$ 510.50
	Radiator Shroud <i>NH</i>			\$ 275.50
	Radiator Air Guard (LH) <i>NH</i>			\$ 26.40
	Radiator Air Guard Up (LH) <i>NH</i>			\$ 27.50
	Horn Unit (LH/RH) <i>NH</i>		\$ 72.80	\$ 145.60
	Flap Assy Active Air Upper, LH <i>broken</i>			\$ 356.00
	Actuator Active Air, LH <i>broken socket</i>			\$ 257.10
	Aircon Condenser <i>BT</i>			\$ 663.60
	Electric Clutch Pump <i>NH</i>			\$ 4,130.00
			11062.80	
			8850.24	
	SUB TOTAL			\$ 16,148.20
	LESS 20%			\$ 3,229.64
	DISCOUNTED TOTAL			\$ 12,918.56
	Front Number Plate <i>Crack</i>			\$ 25.00
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00
			45.00	
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 90.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			1130.00	
	TOTAL LABOUR			\$ 2,270.00

SHC 2038T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Painted</i>			\$ 2,480.40
	Boot Lid Rubber <i>defunct</i>			\$ 127.40
	Boot Lid Hinge (LH/RH) <i>HN</i>	\$	31.30	\$ 62.60
	Boot Lid Lock Upper <i>Done</i>			\$ 224.00
	Boot Lid Lock Lower <i>Done</i>			\$ 225.00
	Boot Lid 'H' Emblem <i>HN</i>			\$ 28.00
	Emblem -Hybrid <i>HN</i>			\$ 24.30
	Emblem -Ioniq <i>HN</i>			\$ 31.30
	Antenna Assy-SMARTK <i>mainly broken</i>			\$ 689.50
	Wiring Harness BWS Ext <i>HN</i>			\$ 988.90
	Assy BSD Blind Spot Radar <i>Not o/s N/S Done</i>	\$	758.50	\$ 1,517.00
	Boot Lid Glass, Lower <i>HN</i>			\$ 384.90
	Boot Lid Lamp (LH/RH) <i>cut / scratched</i>	\$	794.40	\$ 1,588.80
	Licence Lamp (LH/RH) <i>o/s broken N/S HN</i>		30.20	\$ 60.40
	Boot Lid Trimboard <i>HN</i>			\$ 159.70
	Boot Lid Trimboard Clips (10pcs) <i>HN</i>			\$ 11.00
	Boot Lid Trimboard, Centre <i>HN</i>			\$ 69.60
	Rear Bumper <i>form</i>			\$ 459.40
	Rear Bumper Reinforcement <i>Painted</i>			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Painted</i>	\$	138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy <i>broken / dislodged</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>broken</i>			\$ 47.50
	Rear Bumper Stay <i>HN</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>HN</i>	\$	33.10	\$ 66.20
	Rear Bumper Cover Clips <i>HN</i>			\$ 22.00
	Rear Bumper Under Centre <i>dislodged / broken</i>			\$ 53.85
	Rear Bumper Side Under (LH/RH) <i>HN</i>	\$	27.50	\$ 55.00
	Rear Bumper Reflector Lamp (LH/RH) <i>broken / dislodged</i>	\$	31.90	\$ 63.80
	Rear Bumper Towing Cover <i>dislodged</i>			\$ 98.80
	Rear Bumper Reserve Light (Parking Brake Light) <i>mainly broken</i>			\$ 257.10
	Tail Lamp (LH/RH) <i>cut / scratched</i>	\$	870.40	\$ 1,740.80
	Tail Lamp Quarter Panel (LH/RH) <i>HN</i>	\$	208.90	\$ 417.80
	Rear Panel <i>Bnc</i>			\$ 532.00
	Rear Panel Garnish <i>defunct / Vst</i>			\$ 89.00
	Rear Panel Lower Panel <i>Bnc</i>	\$	39.40	\$ 78.80
	Spare Tyre Panel <i>Bnc</i>			\$ 892.50
	Rear Towing Hook <i>HN</i>			\$ 94.60
	Spare Tyre Flip Board <i>HN</i>			\$ 338.80
	Rear Centre Tray <i>broken</i>			\$ 189.90
	Exhaust Pipe Insulator <i>Vst</i>			\$ 35.00
	Exhaust Silencer <i>Vst</i>			\$ 943.50
	Exhaust Pipe Hanger <i>HN</i>			\$ 29.20
	Exhaust Pipe Centre <i>HN</i>			\$ 573.60
	Rear Fender (LH/RH) <i>Painted</i>	\$	1,768.30	\$ 3,536.60
	Rear Windscreen Glass <i>HN</i>			\$ 607.20
	Rear Windscreen Moulding <i>HN</i>			\$ 28.20
			16045.20	
			12836.16	
	SUB TOTAL			\$ 21,084.30
	LESS 20%			\$ 4,216.86
	DISCOUNTED TOTAL			\$ 16,867.44

SHC 2038T

Qty	Parts Description/Labour	Type	Unit Price	Amount
	Boot Lid Comfort Logo & Tel No. Sticker Nec			\$ 30.00 Nett ✓
	Rear No.Plake dislodged			\$ 25.00 Nett ✓
	Rear No.Plake Trim Cover dislodged			\$ 30.00 Nett ✓
	Rear Bumper Reverse Sensor Pann			\$ 135.70 Nett ✓
	Rear Bumper Advertisement Logo H&M NN			\$ 50.00 Nett mmm X
	Rear Bumper Rubber Mat Nec			\$ 50.00 Nett ✓
	Rear Windscreen Sealant Nec			\$ 46.00 Nett ✓
	Rear Camera Short And			\$ 900.00 Nett ✓
			1216.70	\$ 1,266.70
	Labour Charge			
	Panel Beating			\$ 2,000.00 1000/-
	Spray Painting Charge			\$ 1,500.00 900/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Rear Chassis Alignment Charge			\$ 400.00 4N
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Fuel Tank			\$ 150.00 4H
	Remove/Refix Exhaust Pipe			\$ 150.00 60/-
	TOTAL LABOUR			\$ 4,690.00
	ESTIMATE TOTAL			\$ 38,067.70
18 18/09/2019 E1000m NA Auction L/Sum 12 days.		Supp l/s	26308.10 <u>143.20</u> 26451.30 20 000/-	38,518.70
LKK Auto				
		<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>		
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 2038T (Supplementary)

DATE : 30.09.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate Garnish <i>Choke</i>			S 99.00	Nett ✓
	<i>Ign</i>		<i>20%</i>	<i>79.20</i>	
	<i>2kk Hand</i>				
	<i>8</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016484/Dvd3n2

73 BRAS BASAH ROAD

Date: 17-10-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: WO JESSIE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 5888D	Veh. Inspected	SHC 2038T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1062709-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	18/09/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU115095	Colour	BLUE
Odometer	192040 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/09/2019	Inspect Date / Time	18/09/2019 (10:34 AM)
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2038T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	BROKEN	1,227.50	1,227.50
1	SPEAKER ASSY-VESS	NOT NECESSARY	354.40	-
1	UNIT ASSY-SMART CRU (RADAR SENSOR)	MOUNTING BROKEN / BENT	2,910.90	2,910.90
1	FRONT BUMPER COVER	TORN	418.30	418.30
1	FRONT BUMPER SPONGE	TORN	86.90	86.90
1	FRONT BUMPER REINFORCEMENT	BENT	1,075.10	1,075.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	NOT NECESSARY	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	NOT NECESSARY	56.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER CENTRE MOULDING	BROKEN	188.00	188.00
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	949.30	949.30
2	HEADLAMP (LH/RH) @\$1198.00	MOUNTING BROKEN	2,397.60	2,397.60
1	RADIATOR	BENT	510.50	510.50
1	RADIATOR SHROUD	NOT NECESSARY	275.50	-
1	RADIATOR AIR GUARD (LH)	NOT NECESSARY	26.40	-
1	RADIATOR AIR GUARD UPR (LH)	NOT NECESSARY	27.50	-
2	HORN UNIT (LH/RH) @\$72.80	NOT NECESSARY	145.60	-
1	FLAP ASSY ACTIVE AIR UPPER,LH	BROKEN	356.00	356.00
1	ACTUATOR ACTIVE AIR,LH	SOCKET BROKEN	257.10	257.10
1	AIRCON CONDENSER	BENT	663.60	663.60
1	ELECTRIC CLUTCH PUMP	NOT NECESSARY	4,130.00	-
1	BOOT LID	DENTED	2,480.40	2,480.40
1	BOOT LID RUBBER	DEFORMED	127.40	127.40
2	BOOT LID HINGE (LH/RH) @\$31.30	NOT NECESSARY	62.60	-
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	225.00	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30

Report Ref No. CS/INC19016484/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ASSY-SMARTK	MOUNTING BROKEN	689.50	689.50
1	WIRING HARNESS BWS EXT	NOT NECESSARY	988.90	-
2	ASSY BSD BLIND SPOT RADAR @\$758.50	N/S DAMAGED / O/S NOT NECESSARY	1,517.00	758.50
1	BOOT LID GLASS,LOWER	NOT NECESSARY	384.90	-
2	BOOT LID LAMP (LH/RH) @\$794.40	CUT / SCRATCHED	1,588.80	1,588.80
2	LICENCE LAMP (LH/RH) @\$30.20	O/S BROKEN / N/S NOT NECESSARY	60.40	30.20
1	BOOT LID TRIMBOARD	NOT NECESSARY	159.70	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOT LID TRIMBOARD,CENTRE	NOT NECESSARY	69.60	-
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	DENTED	294.80	294.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$138.10	DENTED	276.20	276.20
1	REAR BUMPER CENTRE MOULDING ASSY	BROKEN / DISLODGE	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	BROKEN	47.50	47.50
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE BRACKET (LH/RH) @\$33.10	NOT NECESSARY	66.20	-
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	DISLODGE / BROKEN	53.85	53.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$27.50	NOT NECESSARY	55.00	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$31.90	BROKEN / DISLODGE	63.80	63.80
1	REAR BUMPER TOWING COVER	DISLODGE	98.80	98.80
1	REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	MOUNTING BROKEN	257.10	257.10
2	TAIL LAMP (LH/RH) @\$870.40	CUT / SCRATCHED	1,740.80	1,740.80
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$208.90	NOT NECESSARY	417.80	-
1	REAR PANEL	BUCKLED	532.00	532.00
1	REAR PANEL GARNISH	DEFORMED / BENT	89.00	89.00
2	REAR PANEL LOWER PANEL @\$39.40	BUCKLED	78.80	78.80

Report Ref No. CS/INC19016484/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL	BUCKLED	892.50	892.50
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-
1	SPARE TYRE FLIP BOARD	NOT NECESSARY	338.80	-
1	REAR CENTRE TRAY	BROKEN	189.90	189.90
1	EXHAUST PIPE INSULATOR	BENT	35.00	35.00
1	EXHAUST SILENCER	BENT	943.50	943.50
1	EXHAUST PIPE HANGER	NOT NECESSARY	29.20	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	573.60	-
2	REAR FENDER (LH/RH) @\$1768.30	DENTED	3,536.60	3,536.60
1	REAR WINDSCREEN GLASS	NOT NECESSARY	607.20	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	28.20	-
1	SPARE TYRE LOCK NUT (ADDITIONAL)	BENT	80.00	80.00
1	REAR TRAY (LH)(ADDITIONAL)	NOT NECESSARY	360.00	-
	LESS 20% DISCOUNT		-7,534.50	-5,437.60
			30,138.00	21,750.40
1	FRONT NUMBER PLATE GARNISH (ADDITIONAL)	CRACKED	99.00	99.00
	LESS 20% DISCOUNT		-	-19.80
			99.00	79.20
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE TRIM COVER (SN) }	BROKEN	30.00	45.00
1	FRONT NUMBER PLATE (SN) }	CRACKED	25.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO PLATE (SN)	DISLODGE	25.00	25.00
1	REAR NO PLATE TRIM COVER (SN)	DISLODGE	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR CAMERA (SN)	SHORTED	900.00	900.00
			1,321.70	1,261.70

Report Ref No. CS/INC19016484/Dvd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOT LID LOCK LOWER.		3,000.00	1,500.00
	SPRAY PAINTING CHARGE.		2,000.00	1,100.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		480.00	320.00
	TUFF KOTE.		50.00	40.00
	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX FUEL TANK.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
			6,960.00	3,360.00
	GRAND TOTAL		38,518.70	26,451.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)(CONFIRMED)				20,000.00

Report Ref No. CS/INC19016484/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)**BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.