

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016504/KGA3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKG4842T	Insured Vehicle No :	SHC1151E
Date of Loss: 13/09/2019	Nature of Claim: TP	Claim No: MCT19090293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG4842T		
Make & Model:	BMW 640I, 3.0 (A)	Engine No:	14517975N55B30A
Reg. Date:	10/09/2012 (Man. Year: 2011)	Chassis No:	WBALW32050C799084
Colour:	Grey	Odometer:	67341 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	295/30Z R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,576.50	15,193.20	18,383.30	54.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,985.00	1,385.00	1,600.00	53.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,561.50	16,578.20	19,983.30	54.66
Approved Total (Overridden) (S\$)		11,800.00		
(S\$)	36,561.50	11,800.00	24,761.50	67.73
+ GST 7.00/7.00% (S\$)	2,559.31	826.00	1,733.31	67.73
Nett Amount (S\$)	39,120.81	12,626.00	26,494.81	67.73
+ Car Rental (10.0 x S\$128.40/day) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		107.00		
Nett Liability (S\$)		14,024.45		
Global Sum Settlement (S\$)		14,000.00		

INSPECTION

Date of Assignment: 18/09/2019

Date Inspected: 18/09/2019 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 May 2020)
Parts:	143	BMW 640I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG4842T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEAD LAMP RH	Mtg Cracked	4,950.00 FL	*4,480.00 FL
2	1	*HEAD LAMP BRACKET RH	Necessary	150.00 FL	*150.00 FL
3	1	*FRONT BUMPER	Buckled / Mtg Distorted	2,100.00 FL	*1,955.00 FL
4	10	*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1	*FRONT BUMPER RH BRACKET	Repair	110.00 FL	*- FL
6	1	*FRONT FOG LAMP RH	Serviceable	455.00 FL	*- FL
7	1	*FRONT FOG LAMP COVER RH	Serviceable	85.00 FL	*- FL
8	1	*HEAD LAMP NOZZLE RH	Serviceable	230.00 FL	*- FL
9	1	*HEAD LAMP NOZZLE COVER RH	Serviceable	90.00 FL	*- FL
10	1	*FRONT RH FENDER	Repair	1,650.00 FL	*- FL
11	1	*FRONT RH FENDER INNER SHIELD	Distorted	220.00 FL	*220.00 FL
12	10	*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FL	*50.00 FL
13	1	*FRONT CROSS MEMBER	Serviceable	2,162.00 FL	*- FL
14	1	*FRONT RH SHOCK ABSORBER	Bent	1,755.00 FL	*1,571.00 FL
15	1	*FRONT RH UPPER ARM	Serviceable	628.00 FL	*- FL
16	1	*FRONT RH LOWER ARM	Distorted	680.00 FL	*580.00 FL
17	1	*FRONT RH THRUST ARM	Distorted	585.00 FL	*585.00 FL
18	1	*FRONT RH WHEEL HUB	Serviceable	563.00 FL	*- FL
19	1	*FRONT RH WHEEL HUB BEARING	Necessary	302.00 FL	*302.00 FL
20	1	*FRONT STABILIZER BAR RH	Bent	3,955.00 FL	*3,285.00 FL
21	1	*FRONT STABILIZER LINK RH	Distorted	210.00 FL	*125.00 FL
22	1	*FRONT RH TIE ROD	Bent	405.00 FL	*260.00 FL
23	1	*FRONT RH TIE ROD END	Bent	285.00 FL	*285.00 FL
24	1	*FRONT RH BRAKE DISC	Serviceable	305.00 FL	*- FL
25	1	*FRONT RH BRAKE DISC COVER	Serviceable	110.00 FL	*- FL
26	1	*SET FRONT BUMPER SENSOR	Serviceable	400.00 FS	*- FS
27	1	*TYRE	Serviceable	480.00 FS	*- FS
28	1	*RIM	Not Necessary	2,600.00 FS	*- FS
29	1	*WRAPPING STICKER	Not Necessary	1,800.00 FS	*- FS
30	4	*TYRE -MICHELIN 245/35ZR20 (80%)	Cut (1 PCS ONLY)	2,200.00 FS	*440.00 FS
31	4	*RIM -20 VOSSEN CAST RIMS	Necessary	5,300.00 FS	*1,325.00 FS
32	1	*WRAPPING STICKER	Necessary	920.00 FS	*920.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,785.00	16,583.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,208.50	1,389.80
Total Parts (\$\$)	33,576.50	15,193.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,400.00	400.00
2	TO REMOVE, REFIT/REPLACE UNDERCARRIAGE	New	350.00	240.00
3	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	120.00	80.00
4	TO REMOVE & REPLACE FRONT BUMPER SENSORS	New	100.00	50.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	20.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	500.00
7	TOWING	New	95.00	95.00
Gross Labour Cost (\$\$)			2,985.00	1,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >