

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19016529/QQF3S2**Date:** 22/01/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN19251719000
Claimant Vehicle No :	SGG9966J	Insured Vehicle No :	PC6956Y
Date of Loss:	10/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202945C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG9966J	Engine No:	200614210507204PT
Make & Model:	JAGUAR XJ, 2.0 TSS (A)	Chassis No:	SAJAC12M5FPV78114
Reg. Date:	31/03/2015 (Man. Year: 2015)	Odometer:	58284 km
Colour:	Silver		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	General 5 mm	Rear Left Side:	General 5 mm
Front Right Side:	General 5 mm	Rear Right Side:	General 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,130.48	9,790.68	14,339.80	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	2,010.00	2,780.00	58.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,920.48	11,800.68	17,119.80	59.20
Approved Total (Overridden) (\$\$)		9,450.00		
(\$\$)	28,920.48	9,450.00	19,470.48	67.32
+ GST 7.00/7.00% (\$\$)	2,024.43	661.50	1,362.93	67.32
Nett Amount (\$\$)	30,944.91	10,111.50	20,833.41	67.32

INSPECTION

Date of Assignment:	21/01/2020	
Date Inspected:	27/12/2019	Inspected At:
Estimated Period of Repair:	6.0 days	

Toh Painting (HQ)
BLK C3, WOODLANDS ROAD #391-C & G
YEW TEE INDUSTRIAL ESTATE
SINGAPORE 677966

Adjuster: OI SUN PIN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2020)
Parts:	143	JAGUAR XJ 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG9966J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Replaced	2,413.68 FL	*2,149.00 FL
2	1		*REAR BUMPER REFLECTOR LH	Replaced	116.36 FL	*116.36 FL
3	1		*REAR BUMPER RETAINER LH	Replaced	118.30 FL	*118.30 FL
4	1		*REAR BUMPER SIDE HOLDER LH	Replaced	45.36 FL	*45.36 FL
5	1		*REAR BUMPER REINFORCEMENT	Serviceable	1,282.28 FL	*- FL
6	1		*REAR FENDER LH	Replaced	2,977.03 FL	*2,977.03 FL
7	1		*REAR FENDER AIR VENT LH	Replaced	93.98 FL	*93.98 FL
8	1		*REAR FENDER AIR VENT SURROUND SPONGE LH	Serviceable	61.20 FL	*- FL
9	1		*REAR FENDER OUT SHIELD LH	Replaced	402.08 FL	*402.08 FL
10	1		*REAR FENDER QUARTER GLASS MOULDING LH	Replaced	1,648.40 FL	*100.00 FL
11	1		*REAR FENDER INNER TRIM BOARD LH	Serviceable	565.33 FL	*- FL
12	1		*REAR WINDSCREEN GLASS MOULDING	Replaced	1,574.12 FL	*156.40 FL
13	1		*REAR DOOR LH	Replaced	3,160.93 FL	*3,090.00 FL
14	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	254.80 FL	*- FL
15	1		*REAR DOOR GLASS CHANNEL LH	Serviceable	182.20 FL	*- FL
16	1		*REAR DOOR LOCK LH	Serviceable	552.88 FL	*- FL
17	1		*REAR DOOR INSULATOR PAD LH	Serviceable	161.20 FL	*- FL
18	1		*REAR RADAR SENSOR	Serviceable	305.12 FL	*- FL
19	1		*REAR SPORT RIM LH	Replaced	1,661.94 FL	*1,200.00 FL
20	1		*REAR SHOCK ABSORBER LH	Serviceable	2,575.60 FL	*- FL
21	1		*REAR TOP ARM LH	Serviceable	395.64 FL	*- FL
22	1		*REAR LOWER ARM LH	Serviceable	572.31 FL	*- FL
23	1		*REAR KNUCKLE ARM LH	Serviceable	1,029.33 FL	*- FL
24	1		*REAR KNUCKLE ARM BEARING LH	Replaced	124.74 FL	*124.74 FL
25	1		*REAR STABILIZER BAR	Serviceable	754.95 FL	*- FL
26	1		*REAR STABILIZER BAR LINK LH	Replaced	156.40 FL	*156.40 FL
27	1		*REAR DRIVE SHAFT LH	Serviceable	2,039.60 FL	*- FL
28	1		*REAR STAY BAR LH	Serviceable	585.88 FL	*- FL
29	1		*REAR TYRE LH	Serviceable	550.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Replaced	58.00 FS	*30.00 FS
31	1		*SET REAR FENDER OUTER SHIELD CLIP LH	Replaced	24.00 FS	*24.00 FS
32	1		*REAR FENDER QUARTER GLASS SEALANT LH	Replaced	80.00 FS	*40.00 FS
33	1		*SET REAR FENDER INNER TRIM BOARD CLIP LH	Serviceable	48.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Replaced	140.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,711.64	10,863.65
- List Item Discount on L Items 10.00/10.00% (\$)	2,581.16	1,072.97
Total Parts (\$)	24,130.48	9,790.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR & REPLACE DAMAGED PARTS.	New	1,500.00	800.00
2	SPRAY PAINT AFFECTED AREA.	New	1,400.00	600.00
3	REMOVE & REFIX REAR UNDERCARRIAGE LH.	New	360.00	150.00
4	REMOVE & REFIX REAR WINDSCREEN GLASS.	New	180.00	120.00
5	REMOVE & REFIX REAR FENDER QUARTER GLASS.	New	140.00	80.00
6	REMOVE & REFIX DOOR MECHANISM.	New	150.00	60.00
7	REMOVE & REFIX REAR TRIM BOARD & GARNISH.	New	120.00	40.00
8	CHECK WHEEL ALIGNMENT.	New	120.00	60.00
9	REMOVE & REFIX REAR PARKING SENSOR.	New	100.00	30.00
10	REMOVE & REFIX REAR SEAT & CARPET.	New	150.00	30.00
11	SPRAY ANTI RUST ON AFFECTED AREA.	New	120.00	40.00
12	DIAGNOSE & RESET SYSTEM AFTER REPAIR.	New	450.00	0.00
Gross Labour Cost (\$\$)			4,790.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >