

ASS. REC. BY:

REF: CS/SMD19016538/DYF372

Special Instruction:

photo ok

SUVAJOK: Bryan

## ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong of SMO Date/Time: 19.9.19 10.36a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 8334 Z Insured: SJT L285G

at Workshop m/s Chuan motor Tel: 65425119

of BIK 10 mm Industrial Park 2A #03-19

Policy No: DIB MPV01017003 Claim No: (MTD) 1904377

Sum Insured: Excess:

Make of Veh: D.O.A. 13.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 19.9.19 11.09a.m Person Contacted: Lynn Vehicle: IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SHC 8334 Z - CS/III 19009891/KVD202 DOA - 01/06/2019
	SJT 6285 G - CS/SMD 17014217/ A+bn2 DOA - 20/07/2017

# ASSIGNMENT

013 2023 Sept

Sept 2015

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No. \_\_\_\_\_  
 at Workshop No. \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 76 days Res.: Yes or No  
 Turn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 8334 2 (1 Regt) Sept 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / 120 / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 565250 T/Radio: Insured / Std / NI / NA  
 Eng/No: D4FDFU545676  
 C/No: KMHLB41UMGU078266

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal. S mm

R/Bal. S mm

L/Bal. S mm

L/Bal. S mm

D.O.A. 13/09/2019

D.O.I. 19/08/2019

Survey held at Chunni AMIC

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rent y Rv

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/9/19 Somro BJT 6285 G  
sent Preli by Merimen

23/10/19 prgpr 2/s 10400/- with 7 days prgpr (Red \$12,067-86, 53%)

RECEIVED 23-OCT-2019

Date Time File Path

☐

Preli. Report

☐

Final Report

Date Time File Path

23/10/19 Typist

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Mod. Insp \$

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation

S + RS \$

R/R

Other

Sub Total

Grand Total

450

11

461

Cump Sum \$10400/-

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 24 Sep 2019

**Preliminary Advice**

Insured Vehicle No	: SJT6285G	Accident Date	: 13/09/2019
TP Vehicle No	: SHC8334Z	Assignment Date	: 19/09/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 6.00
Date of Inspection	: 19/09/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages FRONT & REAR portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,467.86
Revised Amount	:S\$	12,510.34
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,510.34

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The survey was conducted on a "without" prejudice basis

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2019		19 Sep 2019 10:36 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:		YEO SHENG HEE, ID: S9419915H, Tel: +6596369467, Email: NOEMAIL [Created by insurer]							
Main Claimant:		COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R							
Vehicle Reg. No.:		SHC8334Z	Date of Loss:	13/09/2019 17:00 - :59					
Claim Type:		TP / CMTD1904377	Policy/Cover Note No.:	D18MTPV01017003 (Comprehensive)					
Vehicle Reg. No. (Insured):		SJT6285G	Policy No. (Claimant):						
			Excess:						
Address:		Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162							
Insurance Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]							
Insurer:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/09/2019]							
Owner/Custodian (Insured):		YEO SHENG HEE (25 / Male), NRIC: S9419915H, Tel: +6596369467 Email: NOEMAIL							
Asq. Remarks:		Please assign to Mr Mohd Rasul.							
<b>ASSOCIATED MAIL RECEIVED</b>									
No mail for this case.									
View All Compose Case Mail									
<b>ASSOCIATED TASKS</b>									
View All Search Tasks Create New Task Complete									
Case No	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

MCD619122259 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 16/09/2019 10:30  
 SUBMITTED BY: Huang XiaoYan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 16/09/2019 10:30  
 Date Of Accident 13/09/2019 17:30  
 Exact Location Of Accident CTE TWDS CITY B4 AMK AVE 1  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC8334Z  
**Insured/Policyholder**  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
**Vehicle Particulars**  
 Manufacturer HYUNDAI  
 Model I40  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
**Insurance Company**  
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number MCOM0015  
 Cover Note Number  
**Driver**  
 Name of Driver TAY CHER SENG  
 NRIC No S0120889F  
 Date Of Birth 23/02/1954  
 Occupation OUTDOOR  
 Date Of Driving Pass 15/08/1978  
 Driving Experience 41 YEARS AND 0 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-83479041  
 Fax Number  
 Contact Number  
 EMail Address NOEMAIL

Address BLK 133 JALAN BUKIT MERAH #07-1522  
 Postcode 160133  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons:  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJT6285G  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Nature Of Damage FRT  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SCQ348Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14.09.2019@1130hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13.09.2019 @ 1750hrs I was travelling along CTE twds City before AMK AVE 1 Exit with no passenger onboard.

As I was travelling straight suddenly veh(C) SCQ 348Y stopped and I followed. Suddenly veh(B) hit onto my rear and caused my vehicle to surge forward.

As it took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims.

No injury in this accident.

Veh(B) SJT 6285G - Male Driver

Veh(C) SCQ 348Y - Female Driver

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14.09.2019@1130hrs

Reporting Centre Personnel's Signature  
Name:


NRIC/FIN No.: June

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille NN			\$ 1,110.10 X
	Radiator Grille H Emblem NN			\$ 39.50 X
	Front Bumper Cover distorted / wandy crack			\$ 1,052.20 ✓
	Front Bumper Sponge NN			\$ 99.20 X
	Front Bumper Reinforcement NN			\$ 402.10 X
	Front Bumper Bracket Top (LH/RH) NN	S	22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) NN	S	24.60	\$ 49.20 X
	Headlamp Support Top Cover NN			\$ 222.60 X
	Headlamp Support Panel Assy NA crack			\$ 907.40 ✗✓
	Headlamp (LH/RH) wandy crack	S	1,388.00	\$ 2,776.00 ✓
	Radiator NN			\$ 698.30 X
	Radiator Fan Blade,Cowling,Motor Assy NN			\$ 792.95 X
	Radiator Bracket (RH/LH) NN	S	6.50	\$ 13.00 X
	Radiator Guard NN	S	20.00	\$ 40.00 X
	Horn Unit (LH/RH) NN	S	73.80	\$ 147.60 X
	Aircon Condenser NN			\$ 927.50 X
	Inter Cooler NN			\$ 1,032.50 X
	Inter Cooler Mounting (2 PCS) NN			\$ 25.90 X
	<b>SUB TOTAL</b>		4735.60	\$ 10,380.85
	<b>LESS 20%</b>			\$ 2,076.17
	<b>DISCOUNTED TOTAL</b>		3788.48	\$ 8,304.68
	Front Number Plate NN			\$ 25.00 Nett ✗
	Front No Plate Trim Cover NN			\$ 30.00 Nett ✗
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 300/-
	Spray Painting Charge			\$ 500.00 200/-
	Wiring Charge			\$ 50.00 30/-
	Towing Charge			\$ 50.00 IN
	Remove/Refix Aircon & Refill Gas			\$ 150.00 IN
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 NN
	<b>TOTAL LABOUR</b>		260.00 530.00	\$ 2,230.00

SHC 8334Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <del>ST</del>			\$ 2,174.90	✓
	Boot Lid Rubber <del>distorted</del>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <del>NH</del>	S	142.30	\$ 284.60	X
	Boot Lid Lock Upper <del>Dem</del>			\$ 102.60	✓
	Boot Lid Lock Lower <del>NH</del>			\$ 31.70	X
	Boot Lid 'H' Emblem <del>Nec</del>			\$ 28.70	✓
	Boot Lid CRDI Plate <del>Nec</del>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <del>chuck</del>	S	565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <del>NH</del>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <del>NH</del>			\$ 11.00	X
	Bootlid Moulding <del>NH</del>			\$ 85.00	X
	Bootlid i40 Emblem <del>NH</del>			\$ 27.90	X
	Bootlid Lower Garnish <del>NH</del>			\$ 227.90	X
	Rear Bumper <del>distorted</del>			\$ 553.00	✓
	Rear Bumper Reinforcement <del>NH</del> <del>SVC</del>			\$ 428.40	X
	Rear Bumper Reinforcement Bracket (LH/RH) <del>NH</del>	S	80.30	\$ 160.60	X
	Rear Bumper Clip 10 pcs <del>Nec</del>			\$ 22.00	✓
	Rear Bumper Bracket <del>NH</del>	S	35.60	\$ 71.20	X
	Rear Bumper Sponge <del>NH</del> <del>SVC</del>			\$ 118.40	X
	Rear Bumper Under Cover <del>distorted</del>			\$ 228.00	✓
	Tail Lamp (LH/RH) <del>N/S</del> <del>newly</del> <del>chuck</del> <del>O/S</del> <del>NH</del> <del>chuck</del>	S	697.80	\$ 1,395.60	✓
	Rear Panel <del>Distorted</del>			\$ 526.70	✓
	Rear Panel Garnish <del>NH</del>			\$ 57.70	X
	Rear Panel Lower Panel <del>NH</del> <del>Nec</del>			\$ 495.50	X
	Exhaust Pipe Insulator <del>NH</del>	S	58.55	\$ 117.10	X
	Exhaust Silencer <del>NH</del> <del>1st</del>	S	967.70	\$ 1,935.40	X
	Exhaust Pipe Hanger <del>NH</del>	S	58.55	\$ 117.10	X
	Exhaust Pipe Centre <del>NH</del>			\$ 730.10	X
			8718.00		
			6974.40		
	SUB TOTAL			\$ 11,303.10	
	LESS 20%			\$ 2,260.62	
	DISCOUNTED TOTAL			\$ 9,042.48	
	Boot Lid Comfort Logo & Tel No. Sticker <del>Nec</del>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <del>Nec</del>			\$ 100.00	Nett ✓
	Rear Bumper Reverse Sensor <del>Dem</del>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <del>Nec</del>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <del>Nec</del>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <del>Nec</del>	S	100.00	\$ 200.00	Nett ✓
			565.70	\$ 565.70	

SHC 8334Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			S 1,000.00 600/-
	Panel Beating			S 750.00 500/-
	Spray Painting Charge			S 50.00 30/-
	Wiring Charge			S 50.00 40/-
	Tuff Kote		1210.00	S 120.00 40/-
	Remove/Refix Reverse Sensor			S 300.00 24
	Remove/Refix Exhaust Pipe			
	TOTAL LABOUR			S 2,270.00
	ESTIMATE TOTAL			S 22,467.86
	19/09/2019 e 1700hrs		13068.58	
	NA Antirigel	4/5	10400/-	
	2/sum 67 days.			
	<u>Yan</u>			
	2KK Auto			
				
	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul>Acknowledged by Repairer Signature: Date:</div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19016538/DYF3N2

Date: 30/10/2019

### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01017003
Claimant Vehicle No :	SHC8334Z	Insured Vehicle No :	SJT6285G
Date of Loss:	13/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904377

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8334Z	Engine No:	D4FDFU545676
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU078266
Reg. Date:	10/09/2015 (Man. Year: 2015)	Odometer:	565250 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,967.86	11,328.58	6,639.28	36.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,740.00	2,760.00	61.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>22,467.86</b>	<b>13,068.58</b>	<b>9,399.28</b>	<b>41.83</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>10,400.00</b>		
<b>(\$\$)</b>	22,467.86	10,400.00	12,067.86	53.71
<b>+ GST 7.00/7.00% (\$\$)</b>	1,572.75	728.00	844.75	53.71
<b>Nett Amount (\$\$)</b>	<b>24,040.61</b>	<b>11,128.00</b>	<b>12,912.61</b>	<b>53.71</b>

### INSPECTION

Date of Assignment:	19/09/2019
Date Inspected:	19/09/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A,  
#03-19 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: YVONNE WONG YIN CHENG

## Adjuster Report

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC8334Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Not Necessary	1,110.10 FL	*- FL
2	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	39.50 FL	*- FL
3	1		*FRONT BUMPER COVER	Distorted/Mounting Cracked	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mounting Cracked	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Not Necessary	698.30 FL	*- FL
12	1		*RADIATOR FAN	Not Necessary	792.95 FL	*- FL
13	2		BLADE,COWLING,MOTOR ASSY			
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
15	2		*HORN UNIT (LH/RH)	Not Necessary	147.60 FL	*- FL
16	1		*AIRCON CONDENSER	Not Necessary	927.50 FL	*- FL
17	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
18	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
19	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
20	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
21	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
22	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
23	1		*BOOT LID LOCK LOWER	Not Necessary	31.70 FL	*- FL
24	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
25	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
26	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
27	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
28	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
29	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
30	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
31	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
32	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
33	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	*- FL
34	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
35	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
36	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
37	1		*REAR BUMPER SPONGE	Serviceable	118.40 FL	*- FL
38	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
39	2		*TAIL LAMP (LH/RH)	Ns Mounting Cracked/Os Cracked	1,395.60 FL	*1,395.60 FL
40	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL

Report was unsubmitted during this print-out.

## Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
42	1		*REAR PANEL LOWER PANEL	Necessary	495.50 FL	*495.50 FL
43	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
44	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
45	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
46	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
47	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
48	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
49	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
50	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
51	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
52	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
53	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
54	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>22,304.65</b>	<b>14,019.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>4,336.79</b>	<b>2,690.72</b>
<b>Total Parts (\$\$)</b>	<b>17,967.86</b>	<b>11,328.58</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	900.00
2	SPRAY PAINTING CHARGE	New	1,250.00	700.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	50.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
7	TUFF KOTE	New	50.00	40.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX EXHAUST PIPE	New	300.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,500.00</b>	<b>1,740.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;