

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref

: D19005995MFSH

Date: 11th October 2019

Our Ref

: CS/FCI19016542/R1vf3s2

M/s Ms First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGB 5888D ACCIDENT ON 15/09/2019 INSURED VEHICLE SHB 2991X

Instruction was received to inspect the vehicle Reg. No. SGB 5888D. The inspection was conducted on 19/09/2019 at the premises of M/s Mova Automotive Pte Ltd, 15 Fan Yong Road Singapore 629792.

The following vehicle information was recorded:

Registration Number

: SGB 5888D

Make/Model

: Toyota Wish 1.8 A

Year of Registration

: 2006

Body Colour

: Black

Chassis Number

: ZNE100280220

Engine Capacity

: 1794 cc

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is \$\$21,428.50 (Sin Dollars: Twenty-One Thousand Four Hundred Twenty-Eight and Fifty Cents only.) (Exclude check items \$\$4,372.50Nett) (Details see photographs enclosed).



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

| | (a) | If the | vehicle | to be | "Total | Loss" |
|--|-----|--------|---------|-------|--------|-------|
|--|-----|--------|---------|-------|--------|-------|

| M | ar | ket | Va | ne |
|---|----|-----|----|----|

S\$ 13,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 7,815.00)

Nett Liability

S\$ 5,185.00

S\$ 5,185.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

(Exclude check items S\$4,372.50 Nett)

S\$ 21,428.50

Nett Liability

S\$ 21,428.50

(a) - (b) =

(S\$ 16,243.50)

The amount of estimated saving of S\$16,243.50 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS

AMSOE,AMIRTE,AMSAE-A,M.MATAI

Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mèch), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.