Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016563/KDA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLF8348X

Insured Vehicle No: SDS636T Vehicle No:

Date of Loss: 07/09/2019 TP Nature of Claim: Claim No: 9284724741SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLF8348X Reg No:

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR928118

Reg. Date: 13/09/2016 (Man. Year: 2016) Chassis No: JTDKB3FUX03531364

Metallic Pearl White Colour: Odometer: 269087 km

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

1798 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm Front Right Side: Rear Right Side: Yokohama 8 mm Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,829.90	136.95	1,692.95	92.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,025.71	612.41	413.30	40.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,855.61	749.36	2,106.25	73.76
+ GST 7.00/7.00% (S\$)	199.89	52.46	147.43	73.76
Nett Amount (S\$)	3,055.50	801.82	2,253.68	73.76
+ Car Rental (2.0 x S	S\$76.95/day) (S\$)	153.90		
+ Doo	/Search Fee (S\$)	7.45		
1	Nett Liability (S\$)	963.17		

INSPECTION

Date of Assignment: 19/09/2019

23/09/2019 Inspected At: 385 SIN MING DRIVE Date Inspected:

Repairer: Esteem Performance Pte Ltd

(HQ)

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	497.50 FL	*- FL
2	1		*LEFT RETAINER	Serviceable	112.70 FL	*- FL
3	1		*RIGHT RETAINER	Serviceable	112.70 FL	*- FL
4	1		*R/R BUMPER CORNER	Serviceable	149.70 FL	*- FL
5	1		*R/R SIDE PANEL	Repair	883.60 FL	*- FL
6	1		*R/R WHEELHOUSE CVR	Repair	92.30 FL	*- FL
7	1		*RR BUMPER CLIP	Not Necessary	40.00 FL	*- FL
8	1		*R/R UNDERSHIELD	Not Necessary	30.00 FL	*- FL
9	1		*R/R HUB CAP	Cracked	195.65 FL	*195.65 FL
10	1		*R/R TYRE R/R TYRE	Serviceable	350.00 FS	*-FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	2,464.15	195.65
- List Item Discount on L Items 30.00/30.00% (S\$)				634.25	58.70	
				Total Parts (S\$)	1,829.90	136.95
			Report was unsubmitt	ed during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	79.0 WU X 50.00 SGD/H	New	395.00	140.00
2	FIXED RATE	New	120.00	0.00
3	LABOUR COST 73.0 WU X 50.00 SGD/H	New	365.00	345.00
4	MATERIAL COST	New	145.71	127.41
		Gross Labour Cost (S\$)	1,025.71	612.41

Report was unsubmitted during this print-out.

< END OF ESTIMATES >