

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016579/GGA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLV7923H	Insured Vehicle No :	SH6194S
Date of Loss: 17/09/2019	Nature of Claim: TP	Claim No: MCT19090384

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7923H		
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Engine No:	2ZR8256638
Reg. Date:	16/01/2018 (Man. Year: 2017)	Chassis No:	ZWR800287002
Colour:	Black	Odometer:	186742 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,714.00	1,978.60	1,735.40	46.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	760.00	250.00	24.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,724.00	2,738.60	1,985.40	42.03
+ GST 7.00/7.00% (\$\$)	330.68	191.70	138.98	42.03
Nett Amount (\$\$)	5,054.68	2,930.30	2,124.38	42.03
+ Loss of Use (4.0 x S\$80.00/day) (\$\$)		320.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,257.75		

INSPECTION

Date of Assignment:	18/09/2019		
Date Inspected:	19/09/2019	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2020)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV7923H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,819.00 F	*1,209.00 FL
2	1		*REAR BUMPER	Deformed	1,650.00 F	*1,190.80 FL
3	1		*WINDSCREEN MOULDING	Necessary	125.00 F	*125.00 FL
4	1		*CLIPS/REPAIRER STUDS RR BUMPER & TAILGATE	Necessary	45.00 FS	*45.00 FS
5	1		*WINDSCREEN SEALANT (REAR)	Necessary	75.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,714.00	2,609.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	631.20
Total Parts (\$\$)	3,714.00	1,978.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/REFIX WINDSCREEN REAR	New	150.00	100.00
2	DISMANTLE /ASSEMBLY OF TAILGATE & REAR BUMPER	New	260.00	260.00
3	SPRAY PAINTING OF TAILGATE (2X) & REAR BUMPER	New	600.00	400.00
Gross Labour Cost (S\$)			1,010.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >