

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19016583/GTD3Q2

**Date:** 08/12/2020

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30622918000	
<b>Claimant Vehicle No :</b> SLM7211B	<b>Insured Vehicle No :</b> YN6662E	
Date of Loss: 16/09/2019	Nature of Claim: TP	Claim No: SNM19D204392C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SLM7211B</b>		Engine No: 2NR8742563
Make & Model: TOYOTA AXIO, 1.5 (A)		Chassis No: NRE1610026397
Reg. Date: 06/04/2017 (Man. Year: 2016)		Odometer: 49261 km
Colour: Silver		
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): <b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size: 185/60R15	Rear Tyre Size: 185/60R15
Front Left Side: Nexen 6 mm	Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm	Rear Right Side: Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,551.98	3,079.90	1,472.08	32.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,000.00	1,030.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,581.98</b>	<b>4,079.90</b>	<b>2,502.08</b>	<b>38.01</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	460.74	285.59	175.15	38.01
<b>Nett Amount (\$\$)</b>	<b>7,042.72</b>	<b>4,365.49</b>	<b>2,677.23</b>	<b>38.01</b>

#### INSPECTION

Date of Assignment: 19/05/2020		
Date Inspected: 19/09/2019	Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair: 4.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2020)
<b>Parts:</b> 143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLM7211B)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH (LED)	Cracked	655.00 FL	*548.40 FL
2	1		*TAILLAMP GASKET	Necessary	35.00 FL	*35.00 FL
3	1		*BOOT	Bent	775.00 FL	*775.00 FL
4	1		*BOOT EMBLEM	Necessary	82.60 FL	*59.20 FL
5	1		*BOOT BADGE COROLLA	Necessary	50.20 FL	*50.20 FL
6	1		*BOOT BADGE AXIO	Necessary	52.70 FL	*45.00 FL
7	1		*BOOT BADGE G	Necessary	41.20 FL	*41.20 FL
8	1		*BOOT BADGE RS	Necessary	56.50 FL	*56.50 FL
9	1		*BOOT BADGE TRD SPORTIVO	Necessary	106.13 FS	*60.00 FS
10	1		*BOOT LOWER MOULDING	Necessary	262.50 FS	*150.00 FS
11	1		*REAR BUMPER	Deformed	1,180.60 FL	*682.70 FL
12	1		*REAR BUMPER PROTECTOR (CHROME)	Necessary	349.50 FS	*220.00 FS
13	1		*REAR BUMPER LOGO TRD SPORT	Necessary	107.25 FS	*60.00 FS
14	1		*BOOT SPOILER (CARBON FIBER)	Cracked	450.00 FS	*250.00 FS
15	1		*BOOT INNER SAFETY REFLECTIVE STICKERS	Necessary	60.00 FS	*10.00 FS
16	1		*REAR BUMPER SPOILER (CARBON FIBER)	Necessary	550.00 FS	*300.00 FS
17	1		*REAR BUMPER INNER INFRA DISTANCE SENSOR STICKER	Necessary	350.00 FS	*250.00 FS
18	1		*REAR NUMBER PLATE (CHROME)	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,284.18</b>	<b>3,653.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	732.20	573.30
<b>Total Parts (\$)</b>	<b>4,551.98</b>	<b>3,079.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE,REWIRING ETC	New	120.00	60.00
2	TO DISMANTLE/TRANSFER BOOT FITTINGS/ANCILLARY ACCESSORIES	New	100.00	60.00
3	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	50.00	0.00
4	LABOUR CHARGE-PANEL BEATING,REPAIRING OF TAILLAMP PANEL,REAR FENDER,END PANEL AND PARTS REPLACEMENT	New	600.00	300.00
5	TO DISMANTLE/REFIT BOOT SPOILER,SUPPLY ADHENSIVE,DOUBLE SIDED TAPE,DRILLING ETC	New	80.00	40.00
6	TO DISMANTLE/REFIT REAR BUMPER SPOILER,SUPPLY ADHENSIVE,DOUBLE SIDED TAPE,DRILLING ETC	New	80.00	40.00
7	TO RESPRAY AFFECTED AREAS	New	600.00	500.00
8	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	400.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,030.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >