

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016584/KQD3E2

Date: 29/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30621719033

**Claimant
Vehicle No :** SLK6606M

**Insured
Vehicle No :** GG9000X

Date of Loss: 14/09/2019

Nature of Claim: TP

Claim
No: SNM19D204375C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6606M**

Make & Model: HONDA JAZZ, 1.5 (A)

Engine No: L15B31190751

Reg. Date: 23/01/2017 (Man. Year: 2016)

Chassis No: JHMGK5850HX201075

Colour: Metallic Blue

Odometer: 38423 km

Engine Capacity: 1498 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,907.10	2,527.50	379.60	13.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	850.00	1,320.00	60.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,077.10	3,377.50	1,699.60	33.48

INSPECTION

Date of Assignment: 18/11/2019

Date Inspected: 30/09/2019 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
BLOCK 10, SECTOR C SIN MING
ROAD INDUSTRIAL ESTATE, #01-10
SINGAPORE 575645.

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$499.60 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts:	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6606M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	594.70 F	*594.70 F
2	1		*FRONT BUMPER RETAINER	Cracked	14.70 F	*14.70 F
3	2		*FRONT BUMPER CLIPS	Necessary	10.00 F	*10.00 F
4	1		*FRONT HEADLAMP ASSY/LH	Cut	1,036.70 F	*1,036.70 F
5	1		*FRONT HEADLAMP LOWER BRACKET/LH	*Check	38.00 F	*- F
6	1		*FRONT FENDER/RH	Bent	425.00 F	*425.00 F
7	1		*FRONT FENDER INNER SHIELD/LH	Distorted	81.50 F	*81.50 F
8	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	12.00 F	*12.00 F
9	1		*FRONT FENDER 1/4 GLASS LH	*Check	281.60 F	*- F
10	1		*FRONT GRILLE	Mtg Cracked	294.70 F	*294.70 F
11	1		*FRONT GRILLE EMBLEM	Necessary	54.70 F	*54.70 F
12	1		*FRONT GRILLE CLIPS	Necessary	3.50 F	*3.50 F
13	1		*1/4 GLASS SEALANT	*Check	60.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,907.10** **2,527.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO FOCUS HEADLAMP.}	New	30.00	20.00
2	TO CHECK WIRING FUNCTIONS.}	New	60.00	0.00
3	TO REPAIR & SPRAY RIM.	New	120.00	0.00
4	TO COMPUTERISE WHEEL ALIGNMENT.	New	120.00	0.00
5	TO REPAIR, PANEL BEAT, RE-ALIGN ON FRT BONNET, LEFT AFFECTED DOOR & LABOUR TO REPLACE THE ABOVE PARTS.	New	800.00	400.00
6	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.	New	120.00	30.00
7	TO PUTTY, PRIMER & SPRAY PAINT ON LEFT FRT FENDER, DOOR, TOUCH UP ON FRT BONNET USING 2K PAINT.	New	800.00	400.00
8	LABOUR TO REPLACE & REPLACE THE 1/4 GLASS IN ORDER TO FACILATE REPLACEMENT OF LEFT FRT FENDER (*Check)	New	120.00	0.00
Gross Labour Cost (\$\$)			2,170.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >