

Kahin

FCL

CS/FCI 19016606 / KTsf352

ASSIGNMENT

25.9.2019

PC6083R

22.11.2019

From:

To:

Veh No:

Type: M.Car / M.Cycle / B.G. / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

Truck / Trailer or

OD: TP / NS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No: PC6083R

Make:

Yu Tong

C.C. 6610

at Workshop no: Woodland Transport

Colour:

White / Blue

A/C: Insured / Std / NI / NA

of: Chang Airport - Terminal 4, (Coachbay)

Sp. Reading

235146

T/Radio: Insured / Std / NI / NA

Insured:

Eng No:

L2YTAGF 6161069627

Policy No:

C/No:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: Contact James Tan: 96157644

Modi: Nil / S/Rim / STD Rim or

(Policy Condition) 10:30am
Call James after Reach

Tyre Size:

F: 275 / 70 R225

R:

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A+ Fine

Est. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent?: Yes or No

R/Bal.

4

mm

R/Bal.

4.4

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

4

mm

L/Bal.

9.4

mm

Est. Repairs:

days

Res: Yes or No

D.O.A.

13/9/19

D.O.L.

25/9/19

Lum Sum:

%

3 Val: Yes or No

Survey held at

Chang Airport TX Coach Bay

CA / REV / REP / 24 HRS

mup)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear als

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 8 NOV 2019

Re-open case for finalise

File pass to typist after re-open

215 B 1,250/- @ 3 days

C \$680/- Red - 35%

17/1/2020

(Confirmed with Chen)

21/1/2020

On/Off Report:

☐ : Preli. Report

Days of Repair:

3

22/01/20

☒ : Final Report

Resurvey No. of Trip:

On/Off Report:

Add Fee:

☐ Site Insp. 15☐ Interview 15☐ Tech. Insp. 15☐ Total 45

Survey Fee

Transcription

24 HRS 10

15 min

15 min

15 min

100

50

27

177

Person Contacted:

23/1/20 \$1,250/- L/S

23/1/20 re-open ref only, 1st close date 11/11/19

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 22 January 2020 1:17 pm
To: Chan Soo Lye
Cc: SUR
Subject: RE: PC6083R AFTER REPAIR PHOTOS AND FINAL REPAIR COST

Hi Chan,

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

"Wishing you a Happy and Prosperous Lunar New Year"



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan Soo Lye <slchan@woodlandstransport.com.sg>
Sent: Wednesday, 22 January 2020 12:37 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PC6083R AFTER REPAIR PHOTOS AND FINAL REPAIR COST


Hi Ms Shirley,

Confirmed LS \$1250-00 and 3 days.

Thank you.

Best Regards

Chan Soo Lye



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629564 Tel: 65595984 Fax: 68622163
Company Registration Number: 200505706E

Quotation

DATE: 18/09/19
VEHICLE NO: PC0083R
DRIVER: TAY THIAM POH
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/09/1061
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 13/09/19
REF No: JW-0919-511

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR LHS CORNER BUMPER	1	384	384.00
2	REVERSER SENSOR	1	46	46.00
Labour Costs				
1	TO REMOVE AND REPLACE REAR BUMPER LHS CORNER PORTION. PANEL BEAT REAR LHS PANEL AND REPLACE REAR SENSOR	1	500	500.00
2	REPLACE REAR BUMPER STICKER AND SIDE PANEL STICKER.	1	600	600.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING REAR BUMPER AND SIDE PANEL.	1	400	400.00
TOTAL:				1,930.00
Total Amount				SGD 1,930.00

Remarks:
ESTIMATE QUOTATION

[Signature]
18/9/19
Signature of Workshop Dpt

[Signature]
18/9/19
Signature of Department Head

Signature of Claim Department

Kalvin (CIC)
25/9/19 10:35L
3 days.
Lumpsum Repair
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Photos taken & submitted to confirmation
- To provide a copy of the "Without Prejudice" bank
- An original copy of the "Without Prejudice" bank
- A copy of the "Without Prejudice" bank to the insurance company
- To be submitted to the insurance company

Administered by: [Signature]
Date: [Signature]

345.60
391.60
1200
1591.60
4/5
1250
3 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016606/T1sf3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-01-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7054M	Veh. Inspected	PC 6083R
Policy No.		Coverage (\$)	0.00
Claim No.	D19005945MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	20/09/2019

2. Vehicle Particulars & Condition

Make & Model	YUTONG	c.c	6690
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	LZYTAGE61G1069627	Colour	WHITE / PURPLE
Odometer	235946	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	AUFINE	4 mm
L/H Front Tyre	275/70 R22.5	AUFINE	4 mm
R/H Rear Tyre	275/70 R22.5 (D)	AUFINE	4/4 mm
L/H Rear Tyre	275/70 R22.5 (D)	AUFINE	4/4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/09/2019	Inspection Date	25/09/2019
Survey held at	CHANGI AIRPORT TERMINAL 4 (COACHBAY)		
Repairer	WOODLANDS TRANSPORT SERVICE PTE. LTD.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6083R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LHS CORNER BUMPER	DEFORMED	384.00	384.00
	LESS 10% DISCOUNT		-	-38.40
			384.00	345.60
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	46.00	46.00
			46.00	46.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE REAR BUMPER LHS CORNER PORTION.PANEL BEAT REAR LHS PANEL AND REPLACE REAR SENSOR.		500.00	400.00
	REPLACE REAR BUMPER STICKER AND SIDE PANEL STICKER.		600.00	500.00
	TO SPRAY PAINTING REAR BUMPER AND SIDE PANEL.		400.00	300.00
			1,500.00	1,200.00
	GRAND TOTAL		1,930.00	1,591.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00
---	--	--	-----------------

Report Ref No. CS/FCI19016606/T1sf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.