

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19016613/FTF3E2

Date: 18/11/2019

REFERENCE

Insured/Claimant: MR LI YUZHAO Policy No: DMPCSN1918311900

Date of Loss: 17/09/2019 Nature of Claim: OD Claim No: SNM19D204394C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ1681H**

Make & Model: MERCEDES-BENZ GLC250, 2.0 4MATIC COUPE (A)

Engine No: 27492031578210

Reg. Date: 23/04/2019 (Man. Year: 2018)

Chassis No: WDC2539462F490439

Colour: Grey

Odometer: 4848 km

Engine Capacity: 1991 cc

Market Value/New Car Price: S\$168,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,356.64	15,082.94	273.70	1.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,990.00	740.00	19.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,086.64	18,072.94	1,013.70	5.31
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	18,336.64	17,322.94	1,013.70	5.53
+ GST 7.00/7.00% (S\$)	1,283.56	1,212.61	70.95	5.53
Nett Amount (S\$)	19,620.20	18,535.55	1,084.65	5.53

INSPECTION

Date of Assignment: 19/09/2019

Date Inspected: 20/09/2019 Inspected At:

9A SERANGOON NORTH AVE 5

Repairer : Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2019)
Parts:	M1-SUV	MERCEDES-BENZ GLC250 2.0 4MATIC COUPE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ1681H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	1,140.00 F	*1,140.00 F
2	1		*FRONT BONNET HINGE LH (WCP)	Bent	126.00 F	*126.00 F
3	1		*FRONT BONNET HINGE RH (WCP)	Bent	126.00 F	*126.00 F
4	1		*FRONT BONNET INSULATOR (WCP)	Bent	180.00 F	*180.00 F
5	14		*INSULATOR CLIP (WCP)	Necessary	84.00 F	*84.00 F
6	2		*FRONT BONNET SPRING (WCP)	Broken	40.80 F	*40.80 F
7	1		*FRONT BONNET UPPER LOCK (WCP)	Jammed	48.00 F	*48.00 F
8	1		*FRONT BONNET EMBLEM (WCP)	Necessary	44.40 F	*44.00 F
9	2		*GROMMET (FOR EMBLEM) (WCP)	Necessary	4.80 F	*4.80 F
10	1		*RADIATOR GRILLE (WCP)	Broken	156.00 F	*156.00 F
11	1		*FRONT GRILLE OUTER GARNISH (MATT SILVER) (WCP)	Cracked	174.00 F	*174.00 F
12	1		*FRONT GRILLE CHROME TRIM, TOP LH (WCP)	Cut	42.00 F	*42.00 F
13	1		*FRONT GRILLE CHROME TRIM, TOP RH (WCP)	Cut	42.00 F	*42.00 F
14	1		*FRONT GRILLE CHROME TRIM, BOTTOM LH (WCP)	Cut	42.00 F	*42.00 F
15	1		*FRONT GRILLE CHROME TRIM, BOTTOM RH (WCP)	Cut	42.00 F	*42.00 F
16	1		*FRONT GRILLE EMBLEM SUPPORT (WCP)	Broken	45.60 F	*45.60 F
17	1		*FRONT GRILLE EMBLEM MERCEDES STAR (WCP)	Cracked	62.00 F	*62.00 F
18	1		*#320 FRONT GRILLE UPPER AIR GUIDE / AIR DEFLECTION (WCP)	Crushed	44.40 F	*44.00 F
19	1		*FRONT BUMPER (WCP)	Buckled	816.00 F	*816.00 F
20	1		*FRONT BUMPER INNER SPONGE / IMPACT ABSORBER (WCP)	Broken	86.40 F	*86.40 F
21	1		*FRONT BUMPER CENTER RETAINER (WCP)	Crushed	132.00 F	*132.00 F
22	1		*FRONT BUMPER SIDE BRACKET RH (WCP)	Necessary	48.00 F	*48.00 F
23	1		*FRONT BUMPER SIDE MOUNTING RAIL LH (WCP)	Not Necessary	9.60 F	*- F
24	1		*FRONT BUMPER SIDE MOUNTING RAIL RH (WCP)	Not Necessary	9.60 F	*- F
25	1			Bent	300.00 F	*300.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT SUPPORT PANEL ASSY (WCP)			
26	1		*FRONT SUPPORT PANEL TOP COVER (WCP)	Bent	228.00 F	*228.00 F
27	1		*FRONT SUPPORT PANEL (LOCK) BRACKET LH (WCP)	Broken	72.00 F	*72.00 F
28	1		*FRONT SUPPORT PANEL (LOCK) BRACKET RH (WCP)	Broken	72.00 F	*72.00 F
29	2		*FRONT BONNET LOCK (WCP)	Short Circuit	88.80 F	*88.80 F
30	1		*HEAD LIGHT LOWER BRACKET LH (WCP)	Broken	42.00 F	*42.00 F
31	1		*HEAD LIGHT LOWER BRACKET RH (WCP)	Broken	42.00 F	*42.00 F
32	1		*RETAINING HOOK / CENTER ROD (WCP)	Bent	48.00 F	*48.00 F
33	1		*ELECTRIC FAN ASSY (WCP)	Cut	1,032.00 F	*1,032.00 F
34	1		*RADIATOR (WCP)	Twisted / Dented	648.00 F	*648.00 F
35	1		*LOW TEMPERATURE RADIATOR (WCP)	Dented / Twisted	600.00 F	*600.00 F
36	1		*AIRCON CONDENSER (WCP)	Cracked	840.00 F	*840.00 F
37	1		*RADIATOR SUPPORTING FRAME LH (WCP)	Not Necessary	72.00 F	*- F
38	1		*RADIATOR SUPPORTING FRAME RH (WCP)	Not Necessary	72.00 F	*- F
39	1		*HEAD LIGHT LH (WCP)	Broken	1,680.00 F	*1,680.00 F
40	1		*HEAD LIGHT RH (WCP)	Broken	1,680.00 F	*1,680.00 F
41	1		*FRONT FENDER LH (WCP)	Bent	516.00 F	*516.00 F
42	1		*FRONT FENDER RH (WCP)	Bent	516.00 F	*516.00 F
43	20		*FRONT FENDER INNER LINER CLIPS (WCP)	Necessary	72.00 F	*72.00 F
44	1		*FRONT WINDSCREEN SIDE MOULDING RH (WCP)	Broken	108.00 F	*89.00 F
45	2		*FRONT BONNET LOCK STRIKER (WCP)	Bent	43.20 F	*43.20 F
46	2		*STRUT (WCP)	Bent	132.00 F	*132.00 F
47	1		*REINFORCEMENT (WCP)	Bent	250.00 F	*250.00 F
48	1		*BONNET LOCK CABLE (WCP)	Broken	50.00 F	*50.00 F
49	2		*AIR DUCT RADIATOR (WCP)	Crushed	66.00 F	*66.00 F
50	1		*RADIATOR REFLECTOR (WCP)	Not Necessary	55.00 F	*- F
51	1		*TOP INTAKE AIR DUCT (WCP)	Broken	120.00 F	*120.00 F
52	1		*INNER SHIELD (LH) FRONT (WCP)	Torn	85.00 F	*85.00 F
53	1		*COOLANT HOSE (FROM COOLANT PUMP TO INTERCOOLER) (WCP)	Cut	75.00 F	*75.00 F
54	1		*VENT PIPE (WCP)	Bent	70.00 F	*70.00 F
55	1		*VENT LINE (WCP)	Bent	85.00 F	*85.00 F
56	1		*BONNET DOOR SWITCH LH (WCP)	Broken	24.00 F	*24.00 F
57	1		*BONNET DOOR SWITCH RH (WCP)	Broken	24.00 F	*24.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
					Sub Total (S\$)	13,353.60
					+ Margin on L,N Items 15.00/15.00% (S\$)	2,003.04
						13,115.60
					Total Parts (S\$)	15,356.64
						15,082.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR KNOCKING, REPLACE, REMOVE AND RE-ADJUST FRONT ACCIDENT AREAS & ETC	New	1,200.00	1,000.00
2	TO TUFF KOTE & UNDERSEAL MATERIAL	New	250.00	120.00
3	TO REMOVE, REFIX, REPLACE FRONT RADIATOR, FRONT AIR-CON CONDENSER, FRONT AIR-CON FAN ASSY, FRONT AIR-CON LIQUID TUBE & ETC	New	120.00	100.00
4	TO DIAGNOSE FAULTY CODE & RESET PROGRAMMING	New	180.00	100.00
5	TO REFILL AIR-CON GAS & VACUUM	New	100.00	80.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	50.00
7	TO TOWING CHARGES	New	100.00	80.00
8	TO REMOVE & REFIX FRONT BUMPER PACKING SEASON & ETC	New	80.00	60.00
9	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT FENDER LH, FRONT FENDER RH, FRONT BUMPER AND FRONT DOOR LH & ETC	New	1,600.00	1,400.00
Gross Labour Cost (\$\$)			3,730.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >