Adjuster Report Page 1 of 6

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### **VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

**Our File No:** CC3/AIG19016616/R1VF3E2

**Date:** 09/09/2020

REFERENCE

Singapore 079120

Insured/Claimant: GAO KANG Policy No: 1900152865

Date of Loss: 17/09/2019 Nature of Claim: OD Claim No: 8879020892SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN7489A

Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB051783

Reg. Date: 27/08/2019 (Man. Year: 2018) Chassis No: WAUZZZF10KD010053

Colour: Green Odometer: 751 km

Engine Capacity: 2995 cc Market Value/New Car Price: \$\$366,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 275/50 R20 Rear Tyre Size: 275/50 R20
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,095.36	24,824.00	41,271.36	62.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,434.00	11,644.00	13,790.00	54.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	91,529.36	36,468.00	55,061.36	60.16
- Excess (S\$)	4,400.00	4,400.00	0.00	0.00
(S\$)	87,129.36	32,068.00	55,061.36	63.19
+ GST 7.00/7.00% (S\$)	6,099.06	2,244.76	3,854.30	63.19
Nett Amount (S\$)	93,228.42	34,312.76	58,915.66	63.19

**INSPECTION** 

Date of Assignment: 20/09/2019

Date Inspected: 19/09/2019 Inspected At: 24 BENOI SECTOR

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

Adjuster Report Page 2 of 6

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 6

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	3,189.00 FS	*2,551.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	342.00 FS	*253.60 FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Missing	109.00 FS	*86.80 FS
4	1		*FRONT BUMPER FRAME - LH	Cracked	74.00 FS	*59.20 FS
5	1		*FRONT BUMPER COVER - LH	Cracked	74.00 FS	*59.20 FS
6	1		*FRONT BUMPER COVER - CENTRE	Serviceable	253.00 FS	*-FS
7	1		*FRONT BUMPER TRIM - CENTRE	Serviceable	371.00 FS	*-FS
8	1		*FRONT BUMPER GRILLE	Serviceable	231.00 FS	*-FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	265.00 FS	*-FS
10	1		*FRONT BUMPER UNDERRUN BAR	Serviceable	735.00 FS	*-FS
11	1		*FRONT BUMPER TRIM	Cracked	493.00 FS	*394.00 FS
12	1		*FRONT BUMPER TRIM	Cracked	223.00 FS	*178.00 FS
13	1		*FRONT BUMPER TOWING COVER	Serviceable	60.00 FS	*-FS
14	1		*DECORATIVE FRAME - LH	Scratched	305.00 FS	*243.60 FS
15	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Deformed	398.00 FS	*318.00 FS
16	1		*ULTRASOUND SENSOR SUPPORT - LH	Necessary	26.00 FS	*20.80 FS
17	1		*RADIATOR GRILLE	Serviceable	2,269.00 FS	*-FS
18	1		*RADIATOR GRILLE COVER	Serviceable	66.00 FS	*-FS
19	2		*RADIATOR GRILLE COVER CAP	Serviceable	126.00 FS	*-FS
20	1		*RADIATOR GRILLE BRACKET	Serviceable	85.00 FS	*-FS
21	2		*RADIATOR GRILLE COVER - LH / RH	Serviceable	278.00 FS	*-FS
22	1		*FRONT CAMERA	Serviceable	852.00 FS	*-FS
23	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	156.00 FS	*-FS
24	1		*FRONT BUMPER CARRIER	Serviceable	791.00 FS	*-FS
25	1		*FRONT BUMPER COVER	Serviceable	119.00 FS	*-FS
26	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	40.00 FS	*31.84 FS
27	2		*FRONT BUMPER SUPPORT - LH / RH	Serviceable	66.00 FS	*-FS
28	1		*FRONT BUMPER BRACKET - LH	Cracked	31.00 FS	*24.16 FS
29	1		*CAUTION SIGN	Not Necessary	13.00 FS	*-FS
30	1		*PEDESTRIAN PROTECTION WARNING SIGN	Not Necessary	13.00 FS	*-FS
31	1		*AIRCON STICKER	Not Necessary	7.00 FS	*-FS
32	1		*HORN - LH LOW TONE	Cut	157.00 FS	*125.20 FS
33	1		*HORN BRACKET - LH LOW TONE	Bent	27.00 FS	*21.20 FS
34	1		*FRONT PARKING AID SENSOR - OUTER	Serviceable	231.00 FS	*-FS
35	1		*FRONT PARKING AIR SENSOR - INNER	Serviceable	231.00 FS	*-FS
36	4		*FRONT PARKING AID SEAL RING	Necessary	12.00 FS	*10.24 FS
37	1		*SET FRONT BUMPER WIRING	Cut	582.00 FS	*465.60 FS
38	1		*FRONT FENDER - LH	Bent	2,110.00 FS	
39	1		*FRONT FENDER ATTACHMENT PARTS	Serviceable	60.00 FS	*-FS
40	1		*FRONT FENDER BRACKET - LH	Serviceable	39.00 FS	*-FS
41	1		*FRONT FENDER BRACKET - LH	Serviceable	59.00 FS	*-FS
42	1		*FRONT FENDER BRACE	Bent	135.00 FS	*108.00 FS
43 44	1		*S-LINE INSCRIPTION  *FRONT WHEEL HOUSING LINER - LH	Necessary Serviceable	113.00 FS	*90.00 FS *- FS
	1				232.00 FS	
45 46	1		*REAR WHEEL HOUSING LINER - LH	Cut	232.00 FS	*185.60 FS
40	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT	Necessary	66.00 FS	*52.48 FS
47	1		*FRONT SPOILER - LH	Serviceable	62.00 FS	*- FS
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 6

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*BONNET	Repair	4,511.00 FS	*- FS
49	1		*BONNET ATTACHMENG PARTS	Serviceable	114.00 FS	*-FS
50	2		*BONNET LID HINGE - LH / RH	Serviceable	312.00 FS	*-FS
51	2		*BONNET GAS FILLED STRUT BRACKET - LH / RH	Serviceable	78.00 FS	*- FS
52	2		*BONNET GAS FILLED STRUT BRACKET - LH / RH	Serviceable	265.00 FS	*-FS
53	1		*FENDER SEAL - LH	Serviceable	56.00 FS	*-FS
54	1		*HEADLAMP COVER - LH	Serviceable	93.00 FS	*-FS
55	2		*BONNET STRIKER - LH / RH	Serviceable	218.00 FS	*-FS
56	1		*BONNET BOWDEN CABLE - CENTRE	Serviceable	53.00 FS	*-FS
57	2		*BONNET LID LOCK WITH MICRO SWITCH	Serviceable	391.00 FS	*-FS
58	1		*BONNET LID LOCK CABLE	Serviceable	67.00 FS	*-FS
59	1		*BONNET RELEASE LEVER	Serviceable	13.00 FS	*-FS
60	2		*FRONT WHEEL COVER - LH / RH	N/S Missing / O/S Necessary	1,044.00 FS	*834.40 FS
61	1		*MAIN BEAM HEADLIGHT MOUNTING - LH	Cracked	107.00 FS	*85.60 FS
62	1		*HEADLIGHT BRACKET - LH	Serviceable	48.00 FS	*-FS
63	1		*LED HEADLIGHT WITH MATRIX BEAM - LH	Broken	11,694.00 FS	
64	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Serviceable	685.00 FS	*-FS
65	1		*P.C BOARD	Serviceable	858.00 FS	*-FS
66	1		*HEADLAMP FAN	Serviceable	363.00 FS	*-FS
67	1		*HEADLIGHT LIFT CYLINDER BRACKET - LH	Serviceable	22.00 FS	*-FS
68	1		*HEADLIGHT HOSE - LH	Serviceable	35.00 FS	*-FS
69	1		*HEADLIGHT LIFT CYLINDER - LH	Serviceable	181.00 FS	*-FS
70	3		*HEADLIGHT PIPE	Serviceable	126.00 FS	*-FS
71	1		*HEADLIGHT PUMP	Serviceable	147.00 FS	*-FS
72	1		*WINDSCREEN WASHER SYSTEM PUMP - UPPER / LOWER	Serviceable	118.00 FS	*-FS
73	1		*WASHER PUMP INSULATOR	Serviceable	19.00 FS	*-FS
74	1		*WASH WATER RESERVOIR	Serviceable	202.00 FS	*-FS
75	1		*COOLANT RADIATOR LOCK CARRIER	Cracked	1,100.00 FS	*880.00 FS
76	4		*READY MIX COOLANT	Necessary	165.00 FS	*131.84 FS
77	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	74.00 FS	*59.04 FS
78	1		*CHARGE AIR COOLER	Bent	855.00 FS	*684.00 FS
79	1		*CHARGE AIR COOLER COVER	Cracked	19.00 FS	*14.56 FS
80	1		*CHARGE AIR COOLER PRESSURE HOSE	Serviceable	188.00 FS	*-FS
81	1		*CHARGE AIR COOLER PRESSURE HOSE	Serviceable	87.00 FS	*-FS
82	1		*CHARGE AIR TUBE	Serviceable	246.00 FS	*-FS
83	1		*CHARGE AIR COOLER AIR GUIDE	Cracked	79.00 FS	*62.72 FS
84	1		*CHARGE AIR TUBE	Serviceable	189.00 FS	*-FS
85	2		*REAR BUMPER	Not Necessary	3,390.00 FS	*-FS
86	1		*REAR BUMPER FIXING PARTS	Not Necessary	154.00 FS	*-FS
87	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	68.00 FS	*-FS
88	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	327.00 FS	*-FS
89	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR	Not Necessary	66.00 FS	*-FS
90	2		*REAR WHEEL COVER - LH / RH	Not Necessary	688.00 FS	*-FS
91	1		*REAR DOOR WHEEL COVER - LH	Not Necessary	179.00 FS	*-FS
92	1		*REAR DOOR - LH	Not Necessary	3,570.00 FS	*-FS
93	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	157.00 FS	*-FS
94	1		*BONDING AGENT	Not Necessary	45.00 FS	*-FS
95	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*-FS
96	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	191.00 FS	*-FS
97	1		*OUTER DOOR SEAL	Not Necessary	234.00 FS	*-FS
			Report was unsubmitted during th	is print-out.		

Adjuster Report Page 5 of 6

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*REAR DOOR CATCH	Not Necessary	96.00 FS	*-FS
99	1		*OUTER DOOR SEAL - LH	Not Necessary	174.00 FS	*- FS
100	1		*SILL PANEL SEAL	Not Necessary	234.00 FS	*-FS
101	1		*REAR DOOR COVER - LH	Not Necessary	464.00 FS	*- FS
102	1		*EXTERIOR DOOR HANDLE - LH	Not Necessary	320.00 FS	
103	1		*REAR DOOR HANDLE CAP - LH	Not Necessary	36.00 FS	
104	1		*REAR DOOR HANDLE HOUSING	Not Necessary	16.00 FS	
	1		*DOOR HANDLE SENSOR - LH	Not Necessary	237.00 FS	
106	1		*REAR DOOR MOUNTING BAR - LH	Not Necessary	118.00 FS	
107			*ROOF MOLDING - LH	Not Necessary	493.00 FS	
108	1		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	Not Necessary	191.00 FS	*-FS
109	1		*REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	Not Necessary	327.00 FS	*- FS
110	1		*FRONT ALUMINIUM RIM - LH	Cut	1,471.00 FS	*1,176.80 FS
	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*-FS
112	1		*FRONT WISHBONE LINK - LH	Bent	379.00 FS	*302.80 FS
113	1		*FRONT SUSPENSION GUIDE - LH	Bent	949.00 FS	*758.80 FS
	1		*FRONT CONTROL ARM - LH UPPER	Bent	297.00 FS	*237.60 FS
	1		*REAR CONTROL ARM - LH UPPER	Bent	297.00 FS	*237.60 FS
116	1		*WHEEL BEARING HOUSING - LH	Bent	683.00 FS	*546.40 FS
117	1		*CONTROL ARM SWIVEL JOINT	Bent	204.00 FS	*162.80 FS
118	1		*WHEEL HUB	Bent	451.00 FS	*360.40 FS
119	1		*DOUBLE ANGLED BALL BEARING WITH FLANGE	Bent	237.00 FS	*189.20 FS
120	1		*SUSPENSION FORKS - LH	Serviceable	345.00 FS	*-FS
121	1		*COUPLING ROD	Serviceable	123.00 FS	
122	1		*DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS	Serviceable	2,267.00 FS	
123	1		*GAS SHOCK ABSORBER	Serviceable	1,532.00 FS	*-FS
124	1		*GAS STRUT - LH	Serviceable	1,249.00 FS	*-FS
125	1		*TIE ROD END - LH	Bent	186.00 FS	*148.80 FS
126	1		*FRONT NO PLATE	Serviceable	40.00 FS	*-FS
127	1		*SUNDRIES	Necessary	800.00 FS	*201.36 FS
128	1		*TRACK ROD FRONT LHS	Bent	88.80 FS	*88.80 FS
129	1		*REFRIGERANT LINE	Bent	186.80 FS	*186.80 FS
130	1		*REFRIGERANT PIPE	Bent	394.80 FS	*394.80 FS
131	1		*BONNET IMPACT PROTECTION - LH / RH / CENTRE (3PCS)	N/S Cut / Necessary	107.00 FS	*32.00 FS
132	1		*FLAT CONTACT HOUSING WITH CONTACT LOCKING MECHANISM	Cracked	14.96 FS	*14.96 FS
133 F=Fra		part. S=	*LHS TYRE SpcNett.	Cut	710.00 FS	*710.00 FS
			•	Total Parts (S\$)	66,095.36	24,824.00

Report was unsubmitted during this print-out.

Adjuster Report Page 6 of 6

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. TO RENEW LHS AIR CHARGED COOLER. CHECI ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New <b>(</b>	1,400.00	1,400.00
4	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	0.00
5	TO REMOVE AND RENEW LHS FRONT SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS HEADLIGHT, LHS REAR DOOR AND REAR BUMPER ASSY. TO REPAIR LHS REAR FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,000.00	3,300.00
7	TO RESPRAY FRONT BUMPER, RADIATOR FRAME, LHS FRONT FENDER, BONNET. BOTH FRONT WHEEL ARCH TRIM, LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLE DOOR COVER, LHS REAR FENDER, LHS REAR DOOR WHEE ARCH TRIM, BOTH REAR WHEEL ARCH TRIMS, REAR UPPE BUMPER AND REAR LOWER BUMPER	L	10,850.00	3,400.00
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
	Gross Labor	ur Cost (S\$)	25,434.00	11,644.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >