

REPAIR ESTIMATE*

VEHICLE NO : SH 6298B

DATE 18/9/2019 16:50

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>ora</i>			\$ 459.40
	Rear Bumper Centre Moulding Assy <i>ora</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>x 1/2</i>			\$ 47.50
	Rear Bumper Stay <i>x 500</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>x 500</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>new</i>			\$ 22.00
	<i>Rear Bumper Trim cover - cut</i>		<i>798.90</i>	
	SUB TOTAL			\$ 1,184.45
	LESS 20%			\$ 236.89
	DISCOUNTED TOTAL			\$ 947.56
	Rear No.Plake <i>ora</i>			\$ 25.00
	Rear No.Plake Trim Cover <i>x 500</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>shut</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>new</i>			\$ 50.00
				\$ 240.70
	Labour Charge			
	Panel Beating			\$ 320
	Spray Painting Charge			\$ 350.00
	Wiring Charge			\$ 250.00
	Remove/Refix Reverse Sensor			\$ 50.00
				\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 1,958.26
<p><i>Kalvin 18/9/19</i></p> <p><i>19/9/19 1045hrs</i></p> <p><i>2 Days.</i></p> <p><i>PIP</i></p> <p><i>Before Paint photo</i></p> <p><i>Larry Ng</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: