

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19016729/ASF3E2

Date: 05/08/2020

REFERENCE

Insured/Claimant:	JEOH LEO	Policy No:	
Date of Loss:	20/09/2019	Nature of Claim:	OD Claim No: 8364637228SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF7183G		
Make & Model:	AUDI TT, 2.0 COUPE (A)	Engine No:	CHH102826
Reg. Date:	28/11/2016 (Man. Year: 2015)	Chassis No:	TRUZZZFV8G1001718
Colour:	Black	Odometer:	45878 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,005.00	3,448.40	2,556.60	42.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	3,222.00	2,150.00	40.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,377.00	6,670.40	4,706.60	41.37
+ GST 7.00/7.00% (\$\$)	796.39	466.93	329.46	41.37
Nett Amount (\$\$)	12,173.39	7,137.33	5,036.06	41.37

INSPECTION

Date of Assignment:	30/09/2019		
Date Inspected:	25/09/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	3,120.00 F	*2,496.00 F
2	1		*FRONT DOOR OUTER SEAL	Necessary	185.00 F	*147.60 F
3	1		*BONDING AGENT	Not Necessary	45.00 F	*- F
4	1		*CLEANING SOLUTION	Not Necessary	65.00 F	*- F
5	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	603.00 F	*- F
6	1		*FRONT DOOR CATCH	Not Necessary	96.00 F	*- F
7	1		*EXTERIOR DOOR HANDLE - RH	Repair	331.00 F	*- F
8	1		*SILL PANEL TRIMS	Deformed	1,006.00 F	*804.80 F
9	1		*SILL PANEL TRIM ATTACHMENT PARTS	Not Necessary	254.00 F	*- F
10	1		*SUNDRIES	Not Necessary	300.00 F	*- F
					Total Parts (\$\$)	6,005.00 3,448.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
2	TO DISMANTLE AND RENEW RHS DOOR AND RHS SIDE MEMBER TRIM. REPAIR RHS REAR FENDER. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY RHS DOOR, DOOR HANDLE, RHS SIDE MEMBER TRIM AND RHS REAR FENDER	New	2,800.00	1,750.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,372.00	3,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >