

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016731/EBA3Q2

Date: 18/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700053930

Claimant
Vehicle No : SKW6629X **Insured Vehicle No :** SLS4987J

Date of Loss: 16/09/2019 Nature of Claim: TP Claim No: 2464151729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6629X		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZR529668
Reg. Date:	11/11/2015 (Man. Year: 2015)	Chassis No:	MR053REH104538264
Colour:	Grey	Odometer:	142288 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodride 5 mm	Rear Left Side:	Goodride 5 mm
Front Right Side:	Goodride 5 mm	Rear Right Side:	Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,740.87	3,724.57	4,016.30	51.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,120.00	700.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,560.87	4,844.57	4,716.30	49.33
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	9,560.87	3,900.00	5,660.87	59.21
+ GST 7.00/7.00% (S\$)	669.26	273.00	396.26	59.21
Nett Amount (S\$)	10,230.13	4,173.00	6,057.13	59.21
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,710.00		

INSPECTION

Date of Assignment: 26/09/2019

Date Inspected: 26/09/2019 Inspected At:

Hua Hong Pte Ltd (Sungei Kadut)
25D Sungei Kadut Street 1
Singapore 729332

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	511.20 FL	*511.20 FL
2	10		*FRONT BUMPER CLIP	Necessary	25.00 FL	*25.00 FL
3	1		*FRONT BUMPER RETAINER (RH)	Broken	55.10 FL	*55.10 FL
4	1		*FRONT BUMPER FOAM	Not Necessary	78.39 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Cut	148.60 FL	*148.60 FL
6	1		*FRONT FOG LAMP COVER (RH)	Scratched	135.00 FL	*135.00 FL
7	1		*FRONT FOG LAMP (RH)	Not Necessary	220.00 FL	*- FL
8	1		*FRONT GRILLE	Broken	564.00 FL	*439.00 FL
9	1		*FRONT GRILLE TOP GARNISH	Not Necessary	73.00 FL	*- FL
10	10		*FRONT GRILLE TOP GARNISH CLIP	Not Necessary	25.00 FL	*- FL
11	1		*FRONT HEADLAMP (RH)	O/S Crushed	5,632.20 FL	*2,568.00 FL
12	2		*FRONT HEADLAMP CLIP (RH)	Necessary (1 PCS ONLY)	5.00 FL	*2.50 FL
13	1		*FRONT REINFORCEMENT	Not Necessary	386.60 FL	*- FL
14	1		*FRONT FENDER (RH)	Dented	858.00 FL	*790.00 FL
15	20		*FRONT FENDER INNER SHIELD CLIP (LH/RH)	Not Necessary	50.00 FL	*- FL
16	1		*WASHER TANK	Crushed	145.00 FL	*145.00 FL
17	1		*REAR BUMPER	Repair	486.50 FL	*- FL
18	10		*REAR BUMPER CLIP	Necessary	25.00 FL	*25.00 FL
19	1		*REAR BUMPER RETAINER (LH)	Broken	72.10 FL	*72.10 FL
20	1		*EMBLEM	Necessary	30.50 FL	*30.50 FL
21	1		*LOGO (VVT)	Necessary	19.10 FL	*19.10 FL
22	1		*FRONT ENGINE UNDER COVER	Not Necessary	130.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	9,676.09	4,966.10
- List Item Discount on L Items 20.00/25.00% (\$)	1,935.22	1,241.53
Total Parts (\$)	7,740.87	3,724.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & CHARGE FRONT BUMPER ,FRONT RH HEADLAMP ,FRONT RH FENDER ,FRONT REINFORCEMENT ,REAR BUMPER ,KNOCKING & PULL STRAIGHT FRONT RH PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	900.00	500.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO SPRAY FRONT BUMPER ,FRONT REINFORCEMENT ,FRONT SUPPORT PANEL ,FRONT RH FENDER AND REAR BUMPER	New	900.00	600.00
Gross Labour Cost (\$\$)			1,820.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >