

15/9/2019

INS. CASE OWNER:

CC³ /EQI1901 6755, k1g6b52LKK:
IDAC:

Surveyor:

Kalin.

DOI:

ASSIGNMENT

20/11/19

Date / Time:

20/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBJ-2345R

Claim No.:

PM19H00662

Name of Insured:

DOR-MATIC DOOR CONTROL SYSTEM

Policy No.:

PM19H00662

Insured Tel No.:

HP:

Make / Model:

Kia

Excess Sec II :S\$

D.O.A.:

11/11/19

Place of Accident:

KAKI BMT K6:5R/01R RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: GANESAMURATHI SUNDARAKUMARI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability:

% Final ? Yes / No

SHC 5933P

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
CabINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

| Date/ Time | STAGE | DATE / PIC |
|------------|-----------------------------------|-------------------------------------|
| 4/11 | Non-Reporting ltr (1st): | |
| 19/11 | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| 16/12 | After call ltr to OI: | 7/12/19 |
| | Documentation Check List: | Handler TYPST |
| | Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | Car Rental Invoice: | <input checked="" type="checkbox"/> |
| | Towing Invoice: | <input checked="" type="checkbox"/> |
| | LTA / GIA : | <input checked="" type="checkbox"/> |
| | Medical Bill: | <input checked="" type="checkbox"/> |
| | PIR: | <input checked="" type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | LOD | <input checked="" type="checkbox"/> |
| | Payment Breakdown Form: | |
| | Post-Repair Photos: | <input checked="" type="checkbox"/> |
| | Others: | <input checked="" type="checkbox"/> |

| PRELIMINARY ADVICE | | Date/Time: | Sent By: | Confirm with: | Confirm by: |
|---|------------------------------------|------------------------------------|-----------------------------------|---------------|---------------------------|
| Repair Cost: | S\$ 4850/- | 4 days | Reduction: 43580.92 % 88 | Confirm with: | Confirm by: KALIN |
| FINAL SETTLEMENT | | Date/Time: | Confirm with: | Email: | Call: |
| Final Liability: | % 100 | (Agreed / Assessed) | BOLA S/N No.: | 27 | If NO or B 28, Ass. Lia : |
| Repair Cost: | S\$ 5189.50 | | | | |
| Loss of Rental (LOR): | S\$ 581.94 | (6 days) | x \$96.99 | | |
| Loss of Use (LOU): | S\$ - | (\$ x days) | | | |
| Loss of Income (LOI): | S\$ 300.00 | (\$ 50 x 6 days) | | | |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> | [Tick only one] | | |
| GIA/LTA Search | S\$ 7.49 | | | | |
| Medical: | S\$ - | | | | |
| Disbursement: | S\$ - | (e.g. Tow/ Independent) | | | |
| Legal Cost | S\$ - | | | | |
| Total: | S\$ 6078.93 | Global Sum S\$: | | | |
| FINAL PAYMENT | | Date/Time: | Confirm with: | Email: | Call: |
| Payee 1: | S\$ 6078.93 | Name 1: | Trans - Cab Auto Services Pte Ltd | | |
| Payee 2: (Strike if N.A.) | S\$ - | Name 2: | | | |
| Payee 3: (Strike if N.A.) | S\$ - | Name 3: | | | |

Sırayla: Kelvin

ASSIGNMENT

The U/C / Chassis frame / Body Structure affected due to collision.

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI19016755/K1gb3

Date: 23.09.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5933P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.09.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

| | | |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 40,690.92 |
| Revised Estimate Amount | : S\$ | 6,157.25 |
| "Check" Items Amount | : S\$ | - |
| Market Value | : S\$ | - |
| LTA Reimbursement Value | : S\$ | - |
| Nett Value | : S\$ | - |

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

4/5 \$4850 / 4 hrs.

Vehicle No.:

SHC 5933P

Chassis No.:

VF1ABL15AUC281004

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

19.9.19

Third Party Insurer :

EQ

Date of Registration :

24/12/2014

| | | PART | | LIST | |
|----|---|-----------------------------------|------------------|-------------|------------|
| 1 | 1 | BUMPER COVER REAR | — <i>Refined</i> | \$ | - 561.70 |
| 2 | 1 | BUMPER LOWER REAR | — <i>one</i> | \$ | - 411.90 |
| 3 | 1 | BUMPER BRACKET CTR REAR | X <i>one</i> | \$ | 98.10 |
| 4 | 1 | BUMPER BRACKET SIDE RH REAR | X <i>one</i> | \$ | 82.10 |
| 5 | 1 | BUMPER RETAINER RH REAR | X <i>one</i> | \$ | 59.80 |
| 6 | 1 | BUMPER REFLECTOR RH | X <i>one</i> | \$ | 16.60 |
| 7 | 1 | BUMPER BRACKET SIDE LH REAR | X <i>one</i> | \$ | 80.80 |
| 8 | 1 | BUMPER RETAINER LH REAR | X <i>one</i> | \$ | 54.20 |
| 9 | 1 | BUMPER REFLECTOR LH | — <i>one</i> | \$ | /16.60 |
| 10 | 1 | BUMPER BEAM REAR | — <i>Best</i> | \$ | - 547.80 |
| 11 | 1 | BUMPER BEAM BRACKET LH REAR | X <i>one</i> | \$ | 114.50 |
| 12 | 1 | BUMPER BEAM BRACKET RH REAR | X <i>one</i> | \$ | 100.90 |
| 13 | 1 | OUTER PANEL REAR (End Panel) | X <i>Refined</i> | \$ | 745.80 |
| 14 | 1 | OUTER PANEL REAR (End Panel) TRIM | X <i>one</i> | \$ | 404.56 |
| 15 | 1 | TAILLAMP RH | X <i>one</i> | \$ | 313.10 |
| 16 | 1 | TAILLAMP PANEL RH | X <i>one</i> | \$ | 401.40 |
| 17 | 1 | TAILLAMP LH | — <i>one</i> | \$ | - 401.40 |
| 18 | 1 | TAILLAMP PANEL LH | X <i>one</i> | \$ | 401.40 |
| 19 | 1 | BOOT REAR | — <i>Refined</i> | \$ | - 1,677.20 |
| 20 | 1 | BOOT FINISHER | X <i>one</i> | \$ | 344.70 |
| 21 | 1 | BOOT WHEATERSTRIP | X <i>one</i> | \$ | 178.20 |
| 22 | 1 | BOOT REFLECTOR LAMP LH | — <i>one</i> | \$ | - 277.70 |
| 23 | 1 | BOOT REFLECTOR LAMP RH | X <i>one</i> | \$ | 277.70 |
| 24 | 1 | BOOT BADGE 'RENAULT' | — <i>one</i> | \$ | - 82.40 |
| 25 | 1 | BOOT BADGE | — <i>one</i> | \$ | - 95.80 |
| 26 | 1 | BOOT STRUT LH | X <i>one</i> | \$ | 145.10 |
| 27 | 1 | BOOT STRUT RH | X <i>one</i> | \$ | 145.10 |
| 28 | 1 | BOOT HINGE LH | X <i>one</i> | \$ | 254.20 |
| 29 | 1 | BOOT HINGE RH | X <i>one</i> | \$ | 253.80 |

AAD1909-178

Tel No. : 6287 6666 Fax No. : 6257 1330

SHC 5933P

| | | | | | |
|----|---|---|---|--------------|---------------------|
| 30 | 1 | BOOT INNER TRIM BOARD | X | \$ | 611.00 |
| 31 | 1 | BOOT SWITCH | X | \$ | 113.00 |
| 32 | 1 | BOOT LOCK | X | \$ | 246.60 |
| 33 | 1 | BOOT LOCK CATCH | X | \$ | 41.70 |
| 34 | 1 | EXHAUST CAP REAR | X | \$ | 125.40 |
| 35 | 1 | EXHAUST REAR | X | \$ | 5,263.60 |
| 36 | 1 | SPARE WHEEL PANEL (Luggage Floor Panel) | X | \$ | 1,229.40 |
| 37 | 1 | SPARE WHEEL PANEL TRIM | X | \$ | 612.21 |
| | | | | TOTAL | \$ 16,787.47 |
| | | | | 10% | \$ 1,678.75 |
| | | | | | \$ 15,108.72 |

| Special Nett | | | |
|--------------|-------------------------------------|-----------|-----------------|
| 1 | 1SET PARKING AID | \$ | 700.00 |
| 2 | 1SET REAR BUMPER CLIP | \$ | 66.00 |
| 3 | 1SET BUMPER BRACKET CTR CLIP | \$ | 33.00 |
| 4 | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | 10.00 |
| 5 | 1SET BUMPER RETAINER RH CLIP RR | \$ | 20.00 |
| 6 | 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ | 10.00 |
| 7 | 1SET BUMPER RETAINER CLIP LH RR | \$ | 20.00 |
| 8 | 1SET BUMPER LOWER REAR RIVET | \$ | 22.00 |
| 9 | 1SET BUMPER LOWER REAR CLIP | \$ | 66.00 |
| 10 | 1 REAR BOOT ADVERTISEMENT STICKER | \$ | 300.00 |
| 11 | 1 REAR FENDER ADVERTISEMENT STICKER | \$ | 300.00 |
| 12 | 1 EXHAUST MOUNTING REAR | \$ | 16.00 |
| 13 | 2 REAR WINDSCREEN SEALANT | \$ | 80.00 |
| 14 | 1 WINDSCREEN MOULDING | \$ | 100.00 |
| 15 | 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | 100.00 |
| 16 | 1 BOOT INNER TRIM CLIP | \$ | 45.00 |
| 17 | 1SET BOOT FINISHER CLIP | \$ | 24.20 |
| 18 | 1 TAILLAMP CLIP LH | \$ | 5.00 |
| 19 | 1 TAILLAMP CLIP RH | \$ | 5.00 |
| 20 | 1 Rear Bumper Protector | \$ | 100.00 |
| 21 | 1 REAR LEFT TYRE | \$ | 300.00 |
| 22 | 1 REAR LEFT TYRE RIM | \$ | 380.00 |
| 23 | 1 SPARE TYRE RIM (ROUE 7J 16H 2547) | \$ | 380.00 |
| 24 | 1 SPARE TYRE | \$ | 300.00 |
| TOTAL | | \$ | 3,382.20 |

Trans-cab Auto Services Pte Ltd

AAD1909-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

| | | |
|--------------------|-----------|------------------|
| TOTAL PARTS | \$ | 18,490.92 |
|--------------------|-----------|------------------|

LABOUR

| | | |
|---|----|-------------------------|
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | 170.00 40 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | 380.00 X 11 |
| To Rust-Proofing Of The Affected Areas. | \$ | 170.00 50 |
| To Check Electrical Lighting Concerned. | \$ | 170.00 30 |
| To transfer of tire, rim and on wheel balancing. | \$ | 170.00 X 11 |
| To reinstall rear bumper parking sensor. | \$ | 170.00 30 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 9,000.00 800 |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | 170.00 30 |
| To transfer of rear windscreen glass to facilitate bodywork repair. | \$ | 170.00 X 11 |
| To check steering geometry and computer wheel alignment | \$ | 220.00 X 11 |
| To transfer of rear bumper fittings, attachment and perform water seepage test. | \$ | 380.00 X 11 |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | 380.00 X 11 |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | 170.00 X 11 |

Trans-cab Auto Services Pte Ltd**AAD1909-178**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5933P

| | | |
|--|-----------|------------------------------------|
| Putty and spray painting of the affected portion. | \$ | 9,000.00 ⁶⁶⁰ |
| To repair and realign rear exhaust pipe. | \$ | 170.00 X "1" |
| To transfer of rear fender fittings, attachment and perform water seepage test. | \$ | 380.00 X "1" |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | 170.00 X "1" |
| To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. | \$ | 380.00 X "1" |
| To supply and re-do rear luggage floor panel insulation padding. | \$ | 380.00 X "1" |
| TOTAL | \$ | 22,200.00 ✓ |
| Over All Total | \$ | 40,690.92 |

LUMP SUM (REPAIR DAY)**30 DAYS**

40691.196

Kalin 1/1/19

20/9/19 1720h

4 Days

L/S

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 878K |
| Vehicle Details | |
| Vehicle No.: | SHC5933P |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 19 Sep 2019 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE 2.0L DCI AUTO D/AB 4DR |
| Primary Colour: | Red |
| Manufacturing Year: | 2014 |
| Engine No.: | M9R8839C002087 |
| Chassis No.: | VF1ABL15AUC281004 |
| Maximum Power Output: | 127.0 kW (170 bhp) |
| Open Market Value: | \$19,998.00 |
| Original Registration Date: | 24 Dec 2014 |
| First Registration Date: | 24 Dec 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$12,498.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 23 Dec 2022 |
| PARF Rebate Amount: | \$9,373.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 23 Dec 2022 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$51,668.00 |
| COE Rebate Amount: | \$21,059.00 |
| Total Rebate Amount: | \$30,432.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 19 Sep 2019

OK

Shu Pei (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 24 September 2019 8:50 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Cecilia Chong (LKK Auto)
Subject: DM19HO02632/JT: Direct Settlement - Accident Involving GBJ2345R (OI : EQI - TBA) AND SHC5933P (TP : LKK REF - CC3/EQI19016755/K1gb3) on 19.09.2019
Attachments: Preliminary_Advice.pdf; TP ESTIMATE- MARKED.pdf; TP GIA REPORT.pdf; SAS2672707.PDF

Dear Shu Pei

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, September 23, 2019 5:24 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBJ2345R (OI : EQI - TBA) AND SHC5933P (TP : LKK REF - CC3/EQI19016755/K1gb3) on 19.09.2019

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

We have inspected TP vehicle SHC 5933P at M/s Trans-cab Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Cecilia and she can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 16 December 2019 3:50 PM
To: Ng Wai Yin
Cc: 'Jasmine Tan'
Subject: RE: YOUR REF: AAD1909-178 (OUR REF: CC3/EQI19016755/K1gb3) *** ACCIDENT INVOLVING GBJ 2345R & SHC 5933P ON 19/09/2019 ***

WITHOUT PREJUDICE

Dear Wai Yin,

We are pleased to offer total amount of \$6,078.93 (all-in) as per your LOD.

Kindly note that NO DV is required for this case.

Thus, we shall proceed to submit and close off the case at our end.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 19 November 2019 4:56 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>
Subject: RE: YOUR REF: AAD1909-178 (OUR REF: CC3/EQI19016755/K1gb3) *** ACCIDENT INVOLVING GBJ 2345R & SHC 5933P ON 19/09/2019 ***

WITHOUT PREJUDICE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ19016755/K1gb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 08-01-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | GBJ 2345R | Veh. Inspected | SHC 5933P |
| Policy No. | DMCPHQ19-000721 | Coverage (\$) | 0.00 |
| Claim No. | DM19HO02632/JT | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 20/09/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | RENAULT LATITUDE | c.c | 1995 |
| Engine No. | HIDDEN | Year of Reg. | 2014 |
| Chassis No. | VF1ABL15AUC281004 | Colour | RED / WHITE |
| Odometer | 441248 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------------|---------|
| R/H Front Tyre | 215/60 R16 | GITI COMFORT | 7 mm |
| L/H Front Tyre | 215/60 R16 | GITI COMFORT | 7 mm |
| R/H Rear Tyre | 215/60 R16 | GITI COMFORT | 7 mm |
| L/H Rear Tyre | 215/60 R16 | GITI COMFORT | 7 mm |

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.**5. General Information**

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 19/09/2019 | Inspection Date | 20/09/2019 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5933P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------|----------------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | BUMPER COVER REAR | DEFORMED | 561.70 | 561.70 |
| 1 | BUMPER LOWER REAR | CRACKED | 411.90 | 411.90 |
| 1 | BUMPER BRACKET CTR REAR | SERVICEABLE | 98.10 | - |
| 1 | BUMPER BRACKET SIDE RH REAR | SERVICEABLE | 82.10 | - |
| 1 | BUMPER RETAINER RH REAR | SERVICEABLE | 59.80 | - |
| 1 | BUMPER REFLECTOR RH | SERVICEABLE | 16.60 | - |
| 1 | BUMPER BRACKET SIDE LH REAR | SERVICEABLE | 80.80 | - |
| 1 | BUMPER RETAINER LH REAR | SERVICEABLE | 54.20 | - |
| 1 | BUMPER REFLECTOR LH | CRACKED | 16.60 | 16.60 |
| 1 | BUMPER BEAM REAR | BENT | 547.80 | 547.80 |
| 1 | BUMPER BEAM BRACKET LH REAR | SERVICEABLE | 114.50 | - |
| 1 | BUMPER BEAM BRACKET RH REAR | SERVICEABLE | 100.90 | - |
| 1 | OUTER PANEL REAR (END PANEL) | TO REPAIR SEE LABOUR | 745.80 | - |
| 1 | OUTER PANEL REAR (END PANEL) TRIM | NOT NECESSARY | 404.56 | - |
| 1 | TAILLAMP RH | SERVICEABLE | 313.10 | - |
| 1 | TAILLAMP PANEL RH | SERVICEABLE | 401.40 | - |
| 1 | TAILLAMP LH | CRACKED | 401.40 | 401.40 |
| 1 | TAILLAMP PANEL LH | SERVICEABLE | 401.40 | - |
| 1 | BOOT REAR | BUCKLED | 1,677.20 | 1,677.20 |
| 1 | BOOT FINISHER | SERVICEABLE | 344.70 | - |
| 1 | BOOT WEATHERSTRIP | SERVICEABLE | 178.20 | - |
| 1 | BOOT REFLECTOR LAMP LH | CRACKED | 277.70 | 277.70 |
| 1 | BOOT REFLECTOR LAMP RH | SERVICEABLE | 277.70 | - |
| 1 | BOOT BADGE 'RENAULT' | NECESSARY | 82.40 | 82.40 |
| 1 | BOOT BADGE | NECESSARY | 95.80 | 95.80 |
| 1 | BOOT STRUT LH | SERVICEABLE | 145.10 | - |
| 1 | BOOT STRUT RH | SERVICEABLE | 145.10 | - |
| 1 | BOOT HINGE LH | SERVICEABLE | 254.20 | - |
| 1 | BOOT HINGE RH | SERVICEABLE | 253.80 | - |
| 1 | BOOT INNER TRIM BOARD | SERVICEABLE | 611.00 | - |

Report Ref No. CC3/EQ19016755/K1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 1 | BOOT SWITCH | SERVICEABLE | 113.00 | - |
| 1 | BOOT LOCK | SERVICEABLE | 246.60 | - |
| 1 | BOOT LOCK CATCH | SERVICEABLE | 41.70 | - |
| 1 | EXHAUST CAP REAR | SERVICEABLE | 125.70 | - |
| 1 | EXHAUST REAR | SERVICEABLE | 5,263.60 | - |
| 1 | SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | SERVICEABLE | 1,229.40 | - |
| 1 | SPARE WHEEL PANEL TRIM | SERVICEABLE | 612.21 | - |
| | LESS 10% DISCOUNT | | -1,678.78 | -407.25 |
| | | | 15,108.99 | 3,665.25 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET PARKING AID (SN) | SHORTED | 700.00 | 500.00 |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | SET BUMPER BRACKET CTR CLIP (SN) | NECESSARY | 33.00 | 33.00 |
| 1 | SET BUMPER BRACKET SIDE CLIP RH RR (SN) | NECESSARY | 10.00 | 10.00 |
| 1 | SET BUMPER RETAINER RH CLIP RR (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | SET BUMPER BRACKET SIDE CLIP LH RR (SN) | NECESSARY | 10.00 | 10.00 |
| 1 | SET BUMPER RETAINER CLIP LH RR (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | SET BUMPER LOWER REAR RIVET (SN) | NECESSARY | 22.00 | 22.00 |
| 1 | SET BUMPER LOWER REAR CLIP (SN) | NECESSARY | 66.00 | 66.00 |
| 1 | REAR BOOT ADVERTISEMENT STICKER (SN) | NOT NECESSARY | 300.00 | - |
| 1 | REAR FENDER ADVERTISEMENT STICKER (SN) | NOT NECESSARY | 300.00 | - |
| 1 | EXHAUST MOUNTING REAR (SN) | SERVICEABLE | 16.00 | - |
| 2 | REAR WINDSCREEN SEALANT (SN) | NOT NECESSARY | 80.00 | - |
| 1 | WINDSCREEN MOULDING (SN) | NOT NECESSARY | 100.00 | - |
| 1 | REAR WINDSCREEN INNER SPONGE SEAL (SN) | NOT NECESSARY | 100.00 | - |
| 1 | BOOT INNER TRIM CLIP (SN) | NOT NECESSARY | 45.00 | - |
| 1 | SET BOOT FINISHER CLIP (SN) | NOT NECESSARY | 24.20 | - |
| 1 | TAILLAMP CLIP LH (SN) | NECESSARY | 5.00 | 5.00 |
| 1 | TAILLAMP CLIP RH (SN) | NOT NECESSARY | 5.00 | - |
| 1 | REAR BUMPER PROTECTOR (SN) | NOT NECESSARY | 100.00 | - |
| 1 | REAR LEFT TYRE (SN) | SERVICEABLE | 300.00 | - |
| 1 | REAR LEFT TYRE RIM (SN) | SERVICEABLE | 380.00 | - |
| 1 | SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) | SERVICEABLE | 380.00 | - |

Report Ref No. CC3/EQI19016755/K1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 1 | SPARE TYRE (SN) | SERVICEABLE | 300.00 | - |
| | | | 3,382.20 | 752.00 |
| | LABOUR | | | |
| | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | | 170.00 | 40.00 |
| | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. | NOT NECESSARY | 380.00 | - |
| | TO RUST-PROOFING OF THE AFFECTED AREAS. | | 170.00 | 50.00 |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 170.00 | 30.00 |
| | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING. | NOT NECESSARY | 170.00 | - |
| | TO REINSTALL REAR BUMPER PARKING SENSOR. | | 170.00 | 30.00 |
| | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF OUTER PANEL REAR (END PANEL). | | 9,000.00 | 800.00 |
| | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | | 170.00 | 30.00 |
| | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR. | NOT NECESSARY | 170.00 | - |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 380.00 | - |
| | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. | NOT NECESSARY | 380.00 | - |
| | TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 9,000.00 | 660.00 |
| | TO REPAIR AND REALIGN REAR EXHAUST PIPE. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 380.00 | - |
| | TO TRANSFER OF REAR LUGGAGE FLOOE PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | - |
| | TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING. | NOT NECESSARY | 380.00 | - |

Report Ref No. CC3/EQI19016755/K1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|--|---------------|---------------------------|-------------------|
| | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING. | NOT NECESSARY | 380.00 | - |
| | | | 22,200.00 | 1,640.00 |
| GRAND TOTAL | | | 40,691.19 | 6,057.25 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,850.00 |

Report Ref No. CC3/EQI19016755/K1gb3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.