

ASS. REC. BY:

REF: CS/CTE/19016804/Dtd307k

Special Instruction:

Surveyor: BryenASSIGNMENT (Office)From (Person): Chong Boun Sen

of

CTE

Date/Time:

19/9/19 @ 5:12pm

Estimated Cost:

Bill to:

OD TP FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 8381L

Insured:

GBE 5536M

at Workshop m/s

Chunni Motor

Tel:

65425119

of

10 Amk Ind. Park 2A # 01-05106

Policy No:

Claim No:

SNM/AD204415

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20/9/19 @ 10:30am

Person Contacted:

LynnVehicle INS/OUT

Date/Time	Action/Instruction
	Tolson/11 ✓
	SHC8381L-NS/INC15014692/H1/bn2
	GBE 5536M-X
	open Review pass back to me to upload photo.

D.O.A: 26/8/2015

ASSIGNMENT

COE August 2023

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 80 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 8381L Yr Regn: 2015 August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 548804 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDFU537815

C/No: KMHLB41UMGU076999

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R 16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 8 mm L/Bal. 5 mm

D.O.A. 18/09/2019 D.O.I. 20/09/2019

Survey held at Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop of

N/S Front y O/S Front y O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Teiping GBF 5536M</u>
<u>23/10/19</u>	<u>Invoice 2/3 82501 - with 8 days of rev</u> <u>(Red: 12218.96 @ 59%)</u>
RECEIVED 6 NOV 2019	

OverTime, File Pass to?



Preli. Report

1111 Typst



Final Report

OverTime, File Return to?

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S. + RS. \$

Phone

Other

TOTAL

220

220

Request Follow up

Long: 82501

TP

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 19 September 2019 5:12 PM
To: Chunni Motor
Cc: assignments
Subject: RE: Our Ref: SNM19D204415-GBE5536M-CBS & Your Ref:-SHC8381L -Accident involving veh no: SHC 8381L & GBE 5536M on 18.09.19-PRS

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Thursday, September 19, 2019 4:28 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: Our Ref: SNM19D204415-GBE5536M-CBS & Your Ref:-SHC8381L -Accident involving veh no: SHC 8381L & GBE 5536M on 18.09.19-PRS

Dear Sir,

We appoint LKK Auto Consultants.

Thank you

Regards,
Chunni Motor Work P/L

On Thu, Sep 19, 2019 at 4:21 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice
Dear Sir,
LKK
STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, September 19, 2019 4:17 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; chunnimotor@gmail.com

Subject: Our Ref: SNM19D204415-GBE5536M-CBS & Your Ref:-SHC8381L -Accident involving veh no: SHC 8381L & GBE 5536M on 18.09.19-PRS

Dear Boon Sen,

Please conduct PRS –SHC8381L – soonest possible.

File to officer in charge –Chong Boon Sen –DID 6389 6171.

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]

Sent: Thursday, September 19, 2019 3:59 PM

To: Claims Dept of CTI

Cc: Chong Boon Sen

Subject: Accident involving veh no: SHC 8381L & GBE 5536M on 18.09.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MCD619124240 / ComfortDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 19/09/2019 14:10
SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2019 14:10
Date Of Accident	18/09/2019 14:35
Exact Location Of Accident	GRANGE ROAD TWDS ORCHARD RD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8381L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	TAY KIAN CHOON
NRIC No	S1279889Z
Date Of Birth	01/01/1956
Occupation	OUTDOOR
Date Of Driving Pass	04/11/1977
Driving Experience	41 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94887412
Fax Number	
Contact Number	
EEmail Address	LOUISTAY57@GMAIL.COM

Address BLK 873 WOODLANDS STREET 81
#12-262
Postcode 730873
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE5536M
Vehicle Make/Model/Colour LORRY
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAN FOOK MENG
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage RH FRONT
No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 19.09.2019
@ 12:00 hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A - SHC 8381L
B - GBE 5536M
C - ROAD KERB

Along Grange Road TWDS Orchard Road.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18.09.2019 at about 14:35 hours I was travelling along Grange Road TWDS Orchard
Road with no passenger onboard .
While travelling on the extreme right lane , suddenly veh B (GBE 5536M) swerved into my
lane and collided into my taxi A - Front Left Portion . As the impact also caused my taxi to go
against the road kerb .
As it took place too fast I could not take evasive action to prevent the accident .
No injury in this accident .
I have company and photos and video at scene to support my claims .
Veh B (GBE 5536M) - Mr Tan Fook Meng

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19.09.2019
@ 12:00 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8381L

DATE : 19.09.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

China Taiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>st / mostly broken</i>			\$ 1,052.20
	Front Bumper Bracket (LH/RH) <i>NN</i>		\$ 24.60	\$ 49.20
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40
	Headlamp (LH/RH) <i>N/S mostly broken o/s NN</i>		\$ 1,388.00	\$ 2,776.00
	Front Fender (LH) <i>Dented</i>			\$ 566.30
	Front Fender Apron Panel (LH) <i>broken</i>			\$ 637.00
	Front Fender Shield (LH) <i>dented</i>			\$ 174.90
	Front Wheel Rim (LH/RH) <i>NS NN o/s & cut</i>		\$ 325.30	\$ 650.60
	Front Wheel Bearing <i>N/S NN o/s & D-m</i>		\$ 540.50	\$ 1,081.00
	Front Shock Absorber (Assy) (LH/RH) <i>N/S NN o/s & destroyed</i>		\$ 342.20	\$ 684.40
	Front Shock Absorber Mounting (LH/RH) <i>NN</i>		\$ 108.80	\$ 217.60
	Front Drive Shaft (LH/RH) <i>N/S NN o/s & destroyed</i>		\$ 1,030.80	\$ 2,061.60
	Rack & Pinion Assy <i>NN</i>			\$ 969.60
	STG Tie End <i>N/S NN o/s & NN</i>		\$ 62.60	\$ 125.20
	Front Suspension Lower Arm (LH/RH) <i>N/S NN o/s & destroyed</i>		\$ 529.30	\$ 1,058.60
	Knuckle Arm (LH/RH) <i>N/S NN o/s & destroyed</i>		\$ 552.00	\$ 1,104.00
	ABS Sensor <i>NN</i>		\$ 234.00	\$ 468.00
	Wiring-Engine <i>NN photo taken</i>			\$ 3,326.00
			8045.90	
			6436.72	
	SUB TOTAL			\$ 17,909.60
	LESS 20%			\$ 3,581.92
	DISCOUNTED TOTAL			\$ 14,327.68
	Front Fender Advertisement Logo (LH) <i>Nue</i>			\$ 100.00
	Front Tyre (LH/RH) <i>SVC</i>		\$ 216.00	\$ 432.00
			100.00	
				\$ 532.00
	Rear Tyre Rim (RH) <i>st</i>			\$ 325.30
	Rear Wheel Hup-Cap (RH) <i>cut</i>			\$ 107.10
	Rear Wheelbearing ING & Hub <i>broken</i>			\$ 362.00
	Rear Trailing Arm (RH) <i>broken</i>			\$ 192.00
	Rear Assist (RH) <i>broken</i>			\$ 145.70
	Rear Shock Absorber (RH) <i>broken</i>			\$ 276.30
	Rear Shock Absorber Mounting (RH) <i>NN</i>			\$ 81.30
	Stabilizer Bar <i>NN</i>			\$ 199.60
	Stabilizer Link <i>NN</i>			\$ 85.90
	Rear Upper Arm (RH) <i>broken</i>			\$ 335.75
	Rear Lower Arm (RH) <i>broken</i>			\$ 353.80
	Rear Knuckle Arm (RH) <i>broken</i>			\$ 545.60
			2643.55	
			2114.84	
	SUB TOTAL			\$ 3,010.35
	LESS 20%			\$ 602.07
	DISCOUNTED TOTAL			\$ 2,408.28

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Tyre (RH) S/C			\$ 216.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 40.00
	Tuff Kote			\$ 45.00
	Remove/Refix Undercarriage (FRT)			\$ 120.00
	Remove/Refix Undercarriage (RR)			\$ 120.00
	Four Wheel Alignment			\$ 80.00
	Remove/Refix Aircon & Refill Gas			\$ 80.00
	Remove/Refix Dashboard photo taken			\$ 200.00
	Remove/Refix Fuse Box photo taken			\$ 100.00
	Re-set Frt & Rear ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 250.00
	TOTAL LABOUR			\$ 2,985.00
	ESTIMATE TOTAL			\$ 20,468.96
	20/09/2019 @ 0945hrs NA Antennal 2/5mm LKK Auto 8 days.	1/S	1670.00 8250/- 10321.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8381 L

Technician:

Mileage: 548804

Time Printed 20.9.19 10:14 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°03'		-3°00' 3°00'
4°06'		-0°19' 5°41'
1°41'		-1°30' 1°30'
19°27'		
18°25'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°30'		-3°00' 3°00'
3°57'		-0°19' 5°41'
-2°40'		-1°30' 1°30'
16°30'		
17°00'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-1°33'		-3°00' 3°00'
0°08'		-3°00' 3°00'
2°57'		-3°00' 3°00'
-0°59'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°22'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°48'		-3°30' 2°30'
3°10'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°27'		-3°00' 3°00'
3°19'		-3°00' 3°00'
-1°30'		-3°00' 3°00'

...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2019		01 Nov 2019 11:43 Edit Adj Rpt	S\$8,250.00 Edit Estimates	S\$8,250.00 View Rpt		Pending for Survey Report Cancel Case























































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC8381L	Date of Loss:	18/09/2019 14:00 - :59 [49 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204415C02	Policy/Cover Note No.:	DMCVSN30791818000						
Vehicle Reg. No. (Insured):	GBE5536M	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$0.00						
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












































Claim Documents

*SHC8381L (SNM19D204415C02)
[GBE5536M]
TP
COMFORT TRANSPORTATION PTE LTD
Sep 18 2019 2:00PM
[-]
Chunni Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/09/19 15:42	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	19/09/19 14:21	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	19/09/19 14:22	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
19	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
20	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
21	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
22	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
23	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
24	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
25	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
26	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
27	01/11/19 13:00	General View		Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
					<input checked="" type="checkbox"/>
28	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
29	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
30	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
31	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
32	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
33	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
34	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
35	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
36	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
37	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
38	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
39	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
40	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
41	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
42	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
43	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
44	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
45	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
46	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
47	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
48	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
49	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
50	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
51	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
52	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
53	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
54	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
55	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
56	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
57	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
58	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
59	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
60	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
61	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
62	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
63	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
64	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
65	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
66	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
67	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
68	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
69	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
70	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
71	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
72	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
73	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
74	01/11/19 13:00	General View		Load JPG	<input checked="" type="checkbox"/>
75	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	01/11/19 13:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
83	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	01/11/19 13:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
138	01/11/19 13:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
139	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	01/11/19 13:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
172	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
173	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
174	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
175	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
176	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
177	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
178	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
179	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
180	01/11/19 13:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/09/19 15:42	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/09/19 15:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/09/19 14:21	Accident Photo	 Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		ComfortDelGro Engineering Pte Ltd (Loyang)			<input checked="" type="checkbox"/>
2	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	19/09/19 14:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	19/09/19 14:22	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	19/09/19 15:42	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016804/DTD3E2

Date: 18/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30791818000

Claimant
Vehicle No : SHC8381LInsured
Vehicle No : GBE5536M

Date of Loss: 18/09/2019

Nature of Claim: TP

Claim
No: SNM19D204415C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8381L

Make & Model: HYUNDAI I40, 1.7 D (A)

Engine No: D4FDFU537815

Reg. Date: 13/08/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMGU076999

Colour: Blue

Odometer: 548804 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,483.96	8,651.56	8,832.40	50.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,985.00	1,670.00	1,315.00	44.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,468.96	10,321.56	10,147.40	49.57
Approved Total (Overridden) (S\$)		8,250.00		
(S\$)	20,468.96	8,250.00	12,218.96	59.70
+ GST 7.00/7.00% (S\$)	1,432.83	577.50	855.33	59.70
Nett Amount (S\$)	21,901.79	8,827.50	13,074.29	59.70

INSPECTION

Date of Assignment: 01/11/2019

Date Inspected: 20/09/2019 Inspected At:

BLK 10, ANG MO KIO IND PK 2A
#01-05/06

Repairer : Chunni Motor Pte Ltd (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8381L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Bent / Mtg Broken	1,052.20 FL	*1,052.20 FL
2	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
3	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
4	1		*HEADLAMP (LH/RH) (O/S NOT NECESSARY)	N/S Mtg Broken/O/SOLD Damaged	2,776.00 FL	*1,388.00 FL
5	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
6	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
7	1		*FRONT FENDER SHIELD (LH)	Deformed	174.90 FL	*174.90 FL
8	1		*FRONT WHEEL RIM (LH/RH)	N/S Not Necessary / O/S Cut	650.60 FL	*325.30 FL
9	1		*FRONT WHEEL BEARING	N/S Not Necessary /O/S Damaged	1,081.00 FL	*540.50 FL
10	1		*FRONT SHOCK ABSORBER (ASSY) (LH/RH)	N/S NotNecessary/O/SDistorted	684.40 FL	*342.20 FL
11	2		*FRONT SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	217.60 FL	*- FL
12	1		*FRONT DRIVE SHAFT (LH/RH)	N/S NotNecessary/O/SDistorted	2,061.60 FL	*1,030.80 FL
13	1		*RACK & PINION ASSY	Not Necessary	969.60 FL	*- FL
14	2		*STG TIE END	Not Necessary	125.20 FL	*- FL
15	1		*FRONT SUSPENSION LOWER ARM (LH/RH)	N/S NotNecessary/O/SDistorted	1,058.60 FL	*529.30 FL
16	1		*KNUCKLE ARM (LH/RH)	N/S NotNecessary/O/SDistorted	1,104.00 FL	*552.00 FL
17	2		*ABS SENSOR	Not Necessary	468.00 FL	*- FL
18	1		*WIRING-ENGINE	Not Necessary	3,326.00 FL	*- FL
19	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
20	2		*FRONT TYRE (LH/RH)	Serviceable	432.00 FS	*- FS
21	1		*REAR TYRE RIM (RH)	Bent	325.30 FL	*325.30 FL
22	1		*REAR WHEEL HUP-CAP (RH)	Cut	107.10 FL	*107.10 FL
23	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
24	1		*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL
25	1		*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
26	1		*REAR SHOCK ABSORBER (RH)	Distorted	276.30 FL	*276.30 FL
27	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
28	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
29	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
30	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
31	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
32	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
33	1		*REAR TYRE (RH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **21,667.95** **10,789.45**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **4,183.99** **2,137.89**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					17,483.96	8,651.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	WIRING CHARGE	New	40.00	30.00
4	TUFF KOTE	New	45.00	30.00
5	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	120.00	120.00
6	REMOVE / REFIX UNDERCARRIAGE (RR)	New	120.00	80.00
7	FOUR WHEEL ALIGNMENT	New	80.00	60.00
8	REMOVE / REFIX AIRCON & REFILL GAS	New	80.00	0.00
9	REMOVE / REFIX DASHBOARD	New	200.00	0.00
10	REMOVE / REFIX FUSE BOX	New	100.00	0.00
11	RE-SET FRT & REAR ABS SYSTEM }	New	200.00	150.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	250.00	0.00
Gross Labour Cost (S\$)			2,985.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >