



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536,
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SMM 4545 X

arts (a) Cost / List Price Items

Plus/Less 51

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

otal Parts Cost

about

otal

Finalized
3035.83
758.96
2276.87

\$ 1400.00 3,260.00
3676.87 ✓ ok

Not Authorized
Permy Bepem

he above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 24/9/11P



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

are Parts

icle No. :
e & Model :
ssis No :

SMM 4545 X

TOYOTA CAMRY

JTNB23HK603026090

Submit By :

Carmen Lim

Year Manufacture :

Engine No. :

Cost / List

o.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sm</i>	2	421.74		X
2	Rear number plate <i>Sm</i>	1	48	S.N	X
3	Rear No.plate lamp LH <i>Sm</i>	1	135.40		X
4	Rear No.plate lamp RH <i>Sm</i>	1	135.40		X
5	Rear bumper <i>Bu</i>	1	655.71		✓
6	Rear bumper clip <i>mc</i>	10	40		✓
7	Rear bumper side retainer LH <i>Sm</i>	1	135.70		X
8	Rear bumper side retainer RH <i>Sm</i>	1	135.70		X
9	Rear bumper bracket LH <i>R</i>	1	95.70		X
10	Rear bumper bracket RH <i>R</i>	1	95.70		X
11	Rear bumper sponge <i>NSP</i>	1	Not in use		X
12	Rear bumper reinforcement <i>Ry</i>	1	368.70		✓
13	Rear bumper reflector LH <i>Sm</i>	1	65.80		X
14	Rear bumper reflector RH <i>Sm</i>	1	65.80		X
15	Bootlid <i>Ry</i>	1	1175.70		✓
16	Bootlid lock <i>R</i>	1	363.95		X
17	Bootlid hinge LH <i>R</i>	1	146.07		X
18	Bootlid hinge RH <i>R</i>	1	146.07		X
19	Bootlid emblem <i>mc</i>	1	59.70		✓
20	Wording "camry" <i>mc</i>	1	60.90		X
21	Wording "hybrid" <i>mc</i>	1	48.31		✓
22	Bootlid garnish <i>Sm</i>	1	330.95		X
23	Bootlid reflector LH <i>Sm</i>	1	448.70		X

te: If any of the quoted parts are recommended to be repaired, then an additional labour charge

be charged accordingly under supplementary.

are Parts

icle No. :

ke & Model :

assis No :

SMM 4545 X

TOYOTA CAMRY

JTNB23HK603026090

Submit By :

Year Manufacture :

Engine No. :

Cost / List

Carmen Lim

0

lo.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Bootlid reflector RH <i>sn</i>	1	440.70		X
25	Tail end panel <i>R</i>	1	761.90		X
26	Tail end panel garnish <i>cm</i>	1	387.81		—
27	Tail end panel garnish clip <i>sn</i>	10	37		—
28	Boot weatherstrip <i>sn</i>	1	704.90		✓
29	Tail lamp LH <i>sn</i>	1	495.30		X
30	Tail lamp RH <i>sn</i>	1	495.30		X
31	Spare tyre well panel <i>R</i>	1	952.70		X
32	Spare tyre board <i>sn</i>	1	485.90		X
33	Exhaust pipe <i>R</i>	2	897.40		X
34	Exhaust mouting <i>sn</i>	2	47.80.		X
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

ite: If any of the quoted parts are recommended to be repaired, then an additional labour charge
l be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Arig Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMM 4545 X** Submit By : **Carmen Lim**
Make & Model : **TOYOTA CAMRY** Year of Manufacture : **0**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	500 600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	200
4	To remove & refit reverse sensor	\$120.00	500
5	To tuff coat	\$150.00	?
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	600
7	To remove & refit exhaust system to assist work load. <i>nn</i>	\$150.00	X
8	To transfer boot mechanism to new boot	\$120.00	600
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1400 ✓