



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SMM 4545 X

**Parts** (a) Cost / List Price Items \_\_\_\_\_  
Plus/Less \_\_\_\_\_  
**Total of Cost / List** \_\_\_\_\_  
(b) Nett Price Items \_\_\_\_\_  
Less \_\_\_\_\_  
**Total of Nett Item** \_\_\_\_\_  
(c) **Special Nett Items** \_\_\_\_\_  
**Total Parts Cost** \_\_\_\_\_  
**Labour** \$ **3,260.00**  
**Total** \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Not Authorized  
Resurvey B4PRIM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 24/9/11P at 11:00

### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 24/9/11P



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SMM 4545 X**  
Make & Model : **TOYOTA CAMRY**  
Chassis No. : **JTNB23HK603026090**

Submit By : **Carmen Lim**  
Year Manufacture :  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	2			X
2	Rear number plate <i>Sn</i>	1			X
3	Rear No.plate lamp LH <i>Sn</i>	1			X
4	Rear No.plate lamp RH <i>Sn</i>	1			X
5	Rear bumper <i>Bu</i>	1			✓
6	Rear bumper clip <i>Mc</i>	10			✓
7	Rear bumper side retainer LH <i>Sn</i>	1			X
8	Rear bumper side retainer RH <i>Sn</i>	1			X
9	Rear bumper bracket LH <i>R</i>	1			X
10	Rear bumper bracket RH <i>R</i>	1			X
11	Rear bumper sponge	1			?
12	Rear bumper reinforcement <i>Ry</i>	1			✓
13	Rear bumper reflector LH <i>Sn</i>	1			X
14	Rear bumper reflector RH <i>Sn</i>	1			X
15	Bootlid <i>Ry</i>	1			✓
16	Bootlid lock	1			?
17	Bootlid hinge LH <i>R</i>	1			X
18	Bootlid hinge RH <i>R</i>	1			X
19	Bootlid emblem <i>Mc</i>	1			✓
20	Wording "camry" <i>nn</i>	1			X
21	Wording "hybrid" <i>Mc</i>	1			✓
22	Bootlid garnish <i>Sn</i>	1			X
23	Bootlid reflector LH <i>Sn</i>	1			X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. :

**SMM 4545 X**

Submit By :

**Carmen Lim**

Make &amp; Model :

TOYOTA CAMRY

Year Manufacture :

0

Chassis No. :

JTNB23HK603026090

Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Bootlid reflector RH <i>Sn</i>	1			X
25	Tail end panel	1			?
26	Tail end panel garnish <i>cm</i>	1			—
27	Tail end panel garnish clip <i>ku</i>	10			—
28	Boot weatherstrip <i>ku</i>	1			✓
29	Tail lamp LH	1			?
30	Tail lamp RH	1			?
31	Spare tyre well panel <i>R</i>	1			X
32	Spare tyre board <i>Sn</i>	1			X
33	Exhaust pipe <i>R</i>	2			X
34	Exhaust mouting <i>Sn</i>	2			X
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SMM 4545 X** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA CAMRY** Year of Manufacture : **0**

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	500-600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$150.00	?
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
7	To remove & refit exhaust system to assist work load. ~ ~	\$150.00	X
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.