



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003221
INV Date 16/04/2020
Reference CC6/CTI19016825/Uea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GU 3053J
Insured Veh. XE 4516S
Claim No. SNM19D204517
Policy No. DMCVSN1839341800
Accident Date 24/09/2019
Inspection Date 24/09/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19016825/Uea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 4516S	Veh. Inspected	GU 3053J
Policy No.	DMCVSN1839341800	Coverage (\$)	0.00
Claim No.	SNM19D204517	Excess (\$)	0.00
Assign From		Assign Date	24/09/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi L300 (M)	c.c	2477
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JMAJNP15VYA001250	Colour	WHITE
Odometer	224623	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14	CONDOR	6 mm
L/H Front Tyre	185 R14	CONDOR	6 mm
R/H Rear Tyre	185 R14	CONDOR	6 mm
L/H Rear Tyre	185 R14	CONDOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/09/2019	Inspection Date	24/09/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 3053J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BADLY DENTED	1,105.00	988.00
1	TAILGATE OUTER HANDLE	BENT / TWISTED	365.00	245.00
1	TAILGATE INNER LOCK	DENTED / JAMMED	295.00	260.00
1	TAILGATE WEATHERSTRIP	TWISTED	311.00	265.00
1	TAILGATE INNER TRIM BOARD	TORN	345.00	288.00
1	TAILGATE REAR WIPER ARM	BENT	105.00	105.00
1	TAILGATE REAR WIPER MOTOR	BENT / JAMMED	680.00	466.00
1	REAR BUMPER	BENT	655.00	453.00
2	REAR BUMPER SIDES @205.00	DISTORTED	410.00	410.00
2	REAR BUMPER SIDE HOLDERS @\$38.00	N/S BENT	76.00	38.00
1	REAR END PANEL OUTER	DENTED / BENT	625.00	425.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	925.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,488.00	-
2	REAR FENDERS @\$1405.00	N/S BADLY DENTED / BUCKLED/O/STO REPAIR SEE LABOUR	2,810.00	991.00
1	REAR FENDER OUTER RAILING N/S	NOT NECESSARY	322.00	-
2	TAILLAMPS @\$305.00	CRACKED	610.00	610.00
2	TAILLAMP HOUSING PANELS @\$299.00	N/S BADLY DENTED	598.00	255.00
1	TAILLAMP INNER HOUSING PANEL N/S	BADLY DENTED	211.00	199.00
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	299.00	-
1	REAR SPARE TYRE BRACKET HOOK	NOT NECESSARY	102.00	-
2	TAILLAMP DAMPERS @\$302.00	NOT NECESSARY	604.00	-
	LESS 10% DISCOUNT		-	-599.80
			12,941.00	5,398.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN RUBBER (50%) (\$232.00) (SN)	NECESSARY	322.00	116.00

Report Ref No. CC6/CTI19016825/Uea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
			342.00	130.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		120.00	60.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM .		100.00	60.00
	TO SPRAY RUST PROOFING.		180.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER,REAR FLOOR PANEL AND REAR FENDERS RH.		2,000.00	1,400.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	900.00
			4,280.00	2,530.00
GRAND TOTAL			17,563.00	8,058.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CC6/CTI19016825/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.