

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016833/KDA3Q2

Date: 19/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079349-01

Claimant
Vehicle No : JMX3838 **Insured Vehicle No :** SJY4727K

Date of Loss: 23/09/2019 **Nature of Claim:** TP **Claim No:** 0026548724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | JMX3838 | Engine No: | 2KD6760807 |
| Make & Model: | TOYOTA HIACE, 2.5 (M) | Chassis No: | PN1HS02P804007553 |
| Reg. Date: | 30/05/2011 (Man. Year: 2011) | Odometer: | 284504 km |
| Colour: | White | | |
| Engine Capacity: | 2494 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|----------------|
| Front Tyre Size: | 195 R15X8 | Rear Tyre Size: | 195 R15X8 |
| Front Left Side: | Maxxis 9 mm | Rear Left Side: | GREEN-MAX 9 mm |
| Front Right Side: | Maxxis 9 mm | Rear Right Side: | GREEN-MAX 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 5,539.72 | 3,390.52 | 2,149.20 | 38.80 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,920.00 | 1,540.00 | 1,380.00 | 47.26 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,459.72 | 4,930.52 | 3,529.20 | 41.72 |
| Approved Total (Overridden) (S\$) | | 3,900.00 | | |
| Nett Amount (S\$) | 8,459.72 | 3,900.00 | 4,559.72 | 53.90 |
| + Loss of Use (5.0 x S\$40.00/day) (S\$) | | 200.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| + Other Costs (S\$) | | 140.00 | | |
| Nett Liability (S\$) | | 4,242.00 | | |

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019 Inspected At: Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|-------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Bent | 728.80 FL | *728.80 FL |
| 2 | 1 | | *REAR BUMPER SIDE RETAINER | O/S Cracked | 98.40 FL | *49.20 FL |
| 3 | 4 | | *REAR BUMPER LOWER BRACKET | Distorted | 117.20 FL | *117.20 FL |
| 4 | 1 | | *REAR END PANEL | Bent | 562.20 FL | *562.20 FL |
| 5 | 1 | | *REAR END PANEL TOP TRIM | Serviceable | 283.10 FL | *- FL |
| 6 | 1 | | *REAR TAIL LAMP ASSY | Cracked | 582.10 FL | *582.10 FL |
| 7 | 1 | | *TAIL LAMP APRON PANEL | Repair | 268.70 FL | *- FL |
| 8 | 1 | | *REAR TAIL DOOR | Bent | 1,554.80 FL | *1,554.80 FL |
| 9 | 1 | | *REAR TAIL DOOR LOCK | Dented | 257.00 FL | *257.00 FL |
| 10 | 1 | | *REAR TAIL DOOR LOCK CATCH | Repair | 68.00 FL | *- FL |
| 11 | 1 | | *REAR TAIL DOR WEATHERSTRIP | Serviceable | 379.00 FL | *- FL |
| 12 | 2 | | *REAR TAIL DOOR DAMPER | Serviceable | 712.40 FL | *- FL |
| 13 | 1 | | *REAR TAIL DOOR CENTRAL LOCK ACTUATOR | Serviceable | 297.60 FL | *- FL |
| 14 | 1 | | *REAR TAIL DOR OUTER GARNISH | Serviceable | 284.50 FL | *- FL |
| 15 | 1 | | *EMBLEM LOGO | Necessary | 67.80 FL | *67.80 FL |
| 16 | 1 | | *SET REVERSE SENSOR | Dented | 220.00 FS | *200.00 FS |
| 17 | 1 | | *TUBE WINDSCREEN GLASS SEALANT | Necessary | 65.00 FS | *40.00 FS |
| 18 | 1 | | *SET REVERSE SENSOR | Repeated | 220.00 FS | *- FS |
| 19 | 1 | | *TUBE WINDSCREEN GLASS SEALANT | Repeated | 65.00 FS | *- FS |
| 20 | 1 | | *REAR END CORNER PANEL R/H | Bent | 364.70 FL | *281.60 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 7,196.30 | 4,440.70 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,656.58 | 1,050.18 |
| Total Parts (\$\$) | 5,539.72 | 3,390.52 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS | New | 1,400.00 | 600.00 |
| 2 | TO REMOVE AND REFIT TAILGATE ACCESSORIES | New | 60.00 | 60.00 |
| 3 | TO REMOVE AND REFIT REVERSE SENSOR | New | 80.00 | 50.00 |
| 4 | TO REMOVE REAR WINDSCREEN GLASS | New | 140.00 | 120.00 |
| 5 | TO APPLY WATERPROOF SEALANT ON JOINTED PANELS | New | 150.00 | 30.00 |
| 6 | TO CHECK WIRING SYSTEM | New | 40.00 | 20.00 |
| 7 | TO SPRAY PAINTING ON AFFECTED AREAS | New | 900.00 | 600.00 |
| 8 | TO APPLY RUST PROOFING | New | 150.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 2,920.00 | 1,540.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >