

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016834/KPS3Q2

Date: 02/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SME7305U	Insured Vehicle No :	SHA1363X
Date of Loss: 23/09/2019	Nature of Claim: TP	Claim No: MCT19090536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7305U	Engine No:	LEB5609339
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB71074392
Reg. Date:	12/10/2018 (Man. Year: 2018)	Odometer:	50054 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,400.00	6,804.48	13,595.52	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,610.00	920.00	26.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,930.00	9,414.48	14,515.52	60.66
+ GST 7.00/7.00% (S\$)	1,675.10	659.01	1,016.09	60.66
Nett Amount (S\$)	25,605.10	10,073.49	15,531.61	60.66
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
Nett Liability (S\$)		11,357.49		
Global Sum Settlement (S\$)		11,300.00		

INSPECTION

Date of Assignment:	24/09/2019	
Date Inspected:	24/09/2019 Inspected At:	MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME7305U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,550.00 FL	*1,320.00 FL
2	1		*TAILGATE WEATHERSTRIP	Cut	165.00 FL	*143.00 FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	115.00 FL	*115.00 FL
4	1		*TAILGATE LAMP RH	Mtg Cracked	650.00 FL	*368.00 FL
5	1		*TAILGATE LAMP LH	Mtg Cracked	650.00 FL	*368.00 FL
6	1		*TAILGATE H LOGO	Necessary	95.00 FL	*95.00 FL
7	1		*TAILGATE CHROME MOULDING	Cracked	410.00 FL	*410.00 FL
8	1		*TAILGATE FREED EMBLEM	Necessary	95.00 FL	*68.20 FL
9	1		*TAILGATE HYBRID EMBLEM	Necessary	105.00 FL	*68.20 FL
10	1		*TAILGATE INNER TRIM	Mtg Cracked	460.00 FL	*391.70 FL
11	10		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FL	*50.00 FL
12	1		*TAILGATE LOCK	Jammed	295.00 FL	*186.20 FL
13	1		*TAILGATE LOCK COVER	Serviceable	180.00 FL	*- FL
14	1		*TAILGATE LOCK CATCH	Dented	150.00 FL	*45.00 FL
15	1		*TAIL LAMP LH	Serviceable	750.00 FL	*- FL
16	1		*TAIL LAMP RH	Serviceable	750.00 FL	*- FL
17	1		*REAR BUMPER	Bent	1,150.00 FL	*1,150.00 FL
18	1		*REAR BUMPER RETAINER LH	Serviceable	65.00 FL	*- FL
19	1		*REAR BUMPER RETAINER RH	Serviceable	65.00 FL	*- FL
20	8		*REAR BUMPER CLIP	Necessary	32.00 FL	*32.00 FL
21	1		*REAR BUMPER REFLECTOR RH	Serviceable	75.00 FL	*- FL
22	1		*REAR BUMPER REFLECTOR LH	Serviceable	75.00 FL	*- FL
23	1		*END PANEL	Bent	515.00 FL	*515.00 FL
24	1		*END PANEL TOP GARNISH	Dented	95.00 FL	*95.00 FL
25	6		*END PANEL TOP GARNISH CLIPS	Necessary	60.00 FL	*60.00 FL
26	1		*HYBRID BATTERY	Serviceable	12,000.00 FL	*- FL
27	1		*REAR BUMPER REVERSE SENSOR	Dented	400.00 FS	*200.00 FS
28	1		*REVERSE CAMERA	Serviceable	600.00 FS	*- FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
30	1		*REAR END FLOOR PANEL	Bent	1,150.00 FL	*1,150.00 FL
31	1		*REAR END BOTTOM PANEL	Bent	350.00 FL	*300.70 FL
32	1		*FLOOR MAT	Deformed	1,650.00 FL	*950.80 FL
33	1		*TAILGATE INNER HANDLE COVER	Deformed	28.00 FL	*28.00 FL
34	1		*REAR FENDER INNER TRIM	Cracked	320.00 FL	*295.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,230.00	8,445.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,830.00	1,641.12
Total Parts (\$\$)	20,400.00	6,804.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ANTIRUST COATING	New	150.00	60.00
2	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,500.00	1,200.00
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	New	100.00	60.00
5	TO REMOVE & REFIT TAILGATE INNER COMPONENTS TO FACILITATE REPAIR	New	120.00	60.00
6	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	120.00
7	TO REMOVE & REPLACE BUMPER SENSORS	New	80.00	50.00
8	TO CHECK & RECONNECT ALL WIRING	New	100.00	20.00
9	TO RESET ECU AFTER REPLACE HYBRID BATTERY	New	180.00	120.00
10	TO SPRAY PAINT ON THE AFFECTED AREA	New	1,000.00	800.00
Gross Labour Cost (S\$)			3,530.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >