

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016836/AYD3E2

Date: 15/05/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30376119000

Claimant Vehicle No : SLB654K

Insured Vehicle No : GBJ5354U

Date of Loss: 13/09/2019

Nature of Claim: TP

Claim No: SNM19D204338C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB654K**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4028560

Reg. Date: 28/03/2016 (Man. Year: 2015)

Chassis No: RU11108557

Colour: Blue

Odometer: 44523 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,305.48	2,384.32	1,921.16	44.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,030.00	970.00	48.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,305.48	3,414.32	2,891.16	45.85
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	6,305.48	2,700.00	3,605.48	57.18
+ GST 7.00/7.00% (S\$)	441.38	189.00	252.38	57.18
Nett Amount (S\$)	6,746.86	2,889.00	3,857.86	57.18

INSPECTION

Date of Assignment: 25/09/2019

Date Inspected: 25/09/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Ubi)
320 UBI ROAD 3
Singapore 408649

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 May 2020)

Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB654K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,162.20 FL	*- FL
2	1		*FRONT HEAD LAMP RH	Cracked	2,366.00 FL	*1,820.00 FL
3	1		*FRONT FENDER RH	Dented	755.00 FL	*755.00 FL
4	1		*FRONT FENDER WHEEL ARCH RH	Deformed	199.00 FL	*199.00 FL
5	1		*FRONT BUMPER	Repair	598.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	27.00 FL	*- FL
7	15		*FRONT BUMPER CLIPS	Not Necessary	68.25 FL	*- FL
8	1		*FRONT FENDER COWLING RH	Torn	170.00 FL	*170.00 FL
9	8		*FRONT FENDER COWLING CLIPS	Necessary	36.40 FL	*36.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,381.85	2,980.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,076.37	596.08
Total Parts (\$\$)	4,305.48	2,384.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKET AND ETC	New	100.00	30.00
2	TO KNOCK & REPAIR RHF FENDER INNER PANEL & TO REMOVE FRONT BONNET, RHF HEADLAMP, RHF FENDER, RHF FENDER ARCH, FRONT BUMPER	New	950.00	400.00
3	TO PUTTY & SPRAY PAINT FRONT BONNET, RHF FENDER, INNER PANEL, FRONT BUMPER AND AFFECTED AREA	New	950.00	600.00
Gross Labour Cost (S\$)			2,000.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >