

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19016846/KDA3Q2

**Date:** 03/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700006498-02

**Claimant Vehicle No :** SKK2828C **Insured Vehicle No :** SKF4013A

Date of Loss: 23/09/2019 Nature of Claim: TP Claim No: 0407534139SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKK2828C</b>		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 COUPE AMG (A)	Engine No:	27492030891812
Reg. Date:	22/09/2017 (Man. Year: 2016)	Chassis No:	WDC2533462F183959
Colour:	Metallic Black	Odometer:	33461 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,039.53	4,019.53	20.00	0.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,170.00	670.00	36.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,879.53</b>	<b>5,189.53</b>	<b>690.00</b>	<b>11.74</b>
<b>+ GST 7.00/7.00% (S\$)</b>	411.57	363.27	48.30	11.74
<b>Nett Amount (S\$)</b>	<b>6,291.10</b>	<b>5,552.80</b>	<b>738.30</b>	<b>11.74</b>
<b>+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)</b>		642.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,196.80</b>		

### INSPECTION

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At: 9A SERANGOON NORTH AVE 5  
Repairer: Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,303.25 FL	*2,303.25 FL
2	1		*REAR TAILGATE AMG EMBLEM	Necessary	208.65 FL	*208.65 FL
3	1		*REAR BUMPER	Buckled	1,111.50 FL	*1,111.50 FL
4	12		*REAR BUMPER CLIPS	Necessary	69.60 FL	*69.60 FL
5	1		*REAR BUMPER LOWER COVER	Dented / Distorted	633.70 FL	*633.70 FL
6	2		*REAR WINDSCREEN STOPPER	Necessary	30.00 FL	*30.00 FL
7	10		*REAR TAILGATE INNER TRIM CLIPS	Necessary	65.00 FL	*65.00 FL
8	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,481.70</b>	<b>4,461.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	442.17	442.17
<b>Total Parts (\$)</b>	<b>4,039.53</b>	<b>4,019.53</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES TO REPAIR ,REPLACE ,REMOVE & READJUST REAR ACCIDENT AREAS &ETC	New	500.00	400.00
2	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT ,REAR WINDSCREEN RUBBER & ETC	New	150.00	120.00
3	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC	New	700.00	500.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR ,REAR REVERSE CAMERA & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	TO REMOVE AND REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL CONDITIONS	New	150.00	60.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	30.00
7	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,840.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**