

ASS. REC. BY:

REF: CS3/MSG19016260/Pcf302

Special Instruction:

\*Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Jowyn Tan Nui Ling of MS16 Date/Time: 23.9.19 9.39 a.m.

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: JRM 3513 Insured: YP 20315

at Workshop m/s Equator Brotherhood Tel: 90113391

of 25 Kaka Bukit Road &amp; #03-79 Synergy

Policy No: 28799615 Claim No: 601056

Sum Insured: Excess:

Make of Veh: D.O.A. 24.7.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 23.9.19 10.43 a.m. Person Contacted: Willy H.O.P. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	JRM 3513-X
	YP 20315-X
	Dismantle: 27/9/2019.
	No GIA.

murin

ASS. REC. BY:

REF:

MS19

PRS

## ASSIGNMENT

From:

Date:

25.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JRM 3513

at Workshop m/s

Equator Brotherhood

of

25 Kaki Bukit Road 4 #03-79 Singny

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

JRM 3513

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Y15Zr

c.c 150

Colour

red &amp; black

A/C: Insured / Std / NI / NA

Sp. Reading

can't start

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

DmyUGO151096020354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 80/90 R17

R: 130/90 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

-

mm

L/Bal.

-

mm

D.O.A.

D.O.I.

25/9/2019

Survey held at

Equator Brotherhood

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$2000 - \$3000

Repair days: 5 days

7/10/2019

RECEIVED 17 OCT 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

120

Transportation:

S + RS, SI

Photos

Others

TOTAL

131

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Wheel end (\$)

Rep. Form:

PRE

Lump Sum / L.B. / C.

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jul 2019		25 Sep 2019 09:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	L H CONSTRUCTION AND MACHINERY LEASING PTE LTD, Co. Reg. No.: 200809157H		
Main Claimant:	PUNITHAN GANESAN, ID: G6581679U		
Vehicle Reg. No.:	JRM3513	Date of Loss:	24/07/2019 08:00 - :59 [6 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 601056	Policy/Cover Note No.:	28799615 (Comprehensive) Coverage: 08/10/2018 - 07/10/2019
Vehicle Reg. No. (Insured):	YP2031S	Policy No. (Claimant):	
		Excess:	
Repairer:	Equator Brotherhood (KAKI BUKIT) 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/09/2019]		
Driver/Custodian (Insured):	SELVARAJI PALANIVEL (), NRIC: G7833957N, Tel: +6587714250 Email:		
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: 9011 3391.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS								View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jul 2019		25 Sep 2019 09:39 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

























































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	L H CONSTRUCTION AND MACHINERY LEASING PTE LTD, Co. Reg. No.: 200809157H								
Main Claimant:	PUNITHAN GANESAN, ID: G6581679U								
Vehicle Reg. No.:	JRM3513	Date of Loss:	24/07/2019 08:00 - :59						
Claim Type:	TP / 601056	Policy/Cover Note No.:	28799615 (Comprehensive) Coverage: 08/10/2018 - 07/10/2019						
Vehicle Reg. No. (Insured):	YP2031S	Policy No. (Claimant):							
		Excess:							
Repairer:	Equator Brotherhood (KAKI BUKIT) 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Imm.Advice due 26/09/2019]								
Driver/Custodian (Insured):	SELVARAJI PALANIVEL (), NRIC: G7833957N, Tel: +6587714250 Email:								
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: 9011 3391.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*JRM3513 (601056)  
 [YP2031S]  
 TP  
 PUNITHAN GANESAN  
 Jul 24 2019 8:00AM  
 [L H CONSTRUCTION AND MACHINERY LEASING PTE LTD]  
 Equator Brotherhood

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
2	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
3	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
9	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
13	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
14	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
15	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
16	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
17	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
18	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
19	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
20	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
21	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
22	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
23	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
24	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
25	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
26	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
27	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
28	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
29	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
30	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
31	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
32	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
33	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
34	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
35	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
36	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
37	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
38	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
39	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
40	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
41	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
42	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>
43	25/09/19 17:24	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/19 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	17/10/19 09:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
101	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
102	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
103	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
104	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
105	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
106	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
107	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
108	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
109	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
110	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
111	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
112	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
113	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
114	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
115	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
116	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
117	17/10/19 09:48	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/09/19 17:24	PRI		Load PDF	
2	24/09/19 17:32	Disagree on SJE		Load PDF	
3	26/09/19 11:33	PRI - clear version		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19016860/FCF3E2

Date: 21/10/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28799615

## Claimant

Vehicle No : JRM3513

Insured Vehicle No : YP2031S

Date of Loss: 24/07/2019

Nature of Claim:

TP

Claim No: 601056

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: JRM3513

Make &amp; Model: YAMAHA T135, 135cc

Engine No: HIDDEN

Reg. Date: (Man. Year: )

Chassis No: PMYUG0510G0020354

Colour: Red/Black

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 80/90 R17

Rear Tyre Size:

130/90 R17

Front Left Side: Pirelli 3 mm

Rear Left Side:

Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 25/09/2019

Date Inspected: 25/09/2019 Inspected At:

Equator Brotherhood (KAKI BUKIT)

25 Kaki Bukit Road 4, #03 -79

Synergy @ KB

Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 21 Oct 2019)

**Parts:** N/A YAMAHA T135 135cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for JRM3513)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >