

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III19016882/KPA3Q2

**Date:** 07/09/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHD9836E	<b>Insured Vehicle No :</b>	SH7055D
Date of Loss: 21/09/2019	Nature of Claim: TP	Claim No: MCT19090515

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9836E</b>		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C001156
Reg. Date:	25/04/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC277444
Colour:	Metallic White/Red	Odometer:	580307 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,521.65	503.39	13,018.26	96.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,180.00	845.00	14,335.00	94.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,701.65</b>	<b>1,348.39</b>	<b>27,353.26</b>	<b>95.30</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>(S\$)</b>	28,701.65	1,100.00	27,601.65	96.17
<b>+ GST 7.00/7.00% (S\$)</b>	2,009.12	77.00	1,932.12	96.17
<b>Nett Amount (S\$)</b>	<b>30,710.77</b>	<b>1,177.00</b>	<b>29,533.77</b>	<b>96.17</b>
<b>+ Loss of Use (3.0 x S\$40.00/day) (S\$)</b>		120.00		
<b>+ Car Rental (3.0 x S\$81.13/day) (S\$)</b>		243.39		
<b>(S\$)</b>		1,540.39		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>770.20</b>		
<b>Global Sum Settlement (S\$)</b>		<b>770.00</b>		

### INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019 Inspected At:

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9836E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Serviceable	747.20 FL	*- FL
2	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
3	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
4	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
5	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	*- FL
6	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
7	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
8	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
9	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
10	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
11	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
12	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
13	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
14	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
15	1		*BONNET	Repair	1,312.70 FL	*- FL
16	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
17	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
18	1		*BONNET HINGE RH	Serviceable	237.40 FL	*- FL
19	1		*BONNET LOCK	Repair	152.80 FL	*- FL
20	1		*BONNET CABLE	Serviceable	55.20 FL	*- FL
21	1		*BONNET CABLE COVER	Serviceable	80.60 FL	*- FL
22	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	*- FL
23	1		*BONNET SEAL INNER	Serviceable	70.10 FL	*- FL
24	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*- FL
25	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
26	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL
27	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
28	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
29	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
30	1		*DOOR CHECK FRONT RH	Serviceable	194.77 FL	*- FL
31	1		*DOOR WEATHERSTRIP FRONT RH	Serviceable	410.27 FL	*- FL
32	1		*DOOR SEAL FRONT RH	Serviceable	72.82 FL	*- FL
33	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
34	1		*BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
35	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
36	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
37	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
38	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
39	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
40	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
41	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
42	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
43	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
45	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
46	1		*SET SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
47	1		*WINDSCREEN SEALANT	Not Necessary	109.20 FS	*- FS
48	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
49	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
50	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
51	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
52	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
53	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
54	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
55	1		*FRONT RH WHEEL HUB CAP	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,836.87</b>	<b>547.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,315.22	43.71
<b>Total Parts (\$)</b>	<b>13,521.65</b>	<b>503.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	300.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
9	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
13	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,180.00</b>	<b>845.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >