

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG19016886/KGA3Q2  
**Date:** 17/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447999
<b>Claimant Vehicle No :</b>	SHD5876R	<b>Insured Vehicle No :</b>	SKZ2745D
Date of Loss:	15/09/2019	Nature of Claim:	TP
		Claim No:	0726226266SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD5876R</b>	Engine No:	2ZR2B99847
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU803079270
Reg. Date:	17/01/2019 (Man. Year: 2018)	Odometer:	111940 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,758.44	447.82	9,310.62	95.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,170.00	755.00	10,415.00	93.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,928.44</b>	<b>1,202.82</b>	<b>19,725.62</b>	<b>94.25</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,464.99</b>	<b>84.20</b>	<b>1,380.79</b>	<b>94.25</b>

<b>Nett Amount (S\$)</b>	<b>22,393.43</b>	<b>1,287.02</b>	<b>21,106.41</b>	<b>94.25</b>
<b>+ Loss of Use (1.5 x S\$50.00/day) (S\$)</b>		75.00		
<b>+ Car Rental (1.5 x S\$113.40/day) (S\$)</b>		170.10		
<b>(S\$)</b>		1,532.12		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>766.06</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>773.51</b>		
<b>Global Sum Settlement (S\$)</b>		<b>770.00</b>		

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	509.10 FL	*509.10 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
3	1		*FRONT HEAD LAMP (LOWER) LH	Serviceable	907.75 FL	*- FL
4	1		*FRONT HEADLAMP LH	Serviceable	2,909.04 FL	*- FL
5	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	492.30 FL	*- FL
6	1		*MOTOR ,HEADLAMP LEVELING ,LH	Serviceable	413.10 FL	*- FL
7	1		*FRONT FENDER LH	Repair	963.80 FL	*- FL
8	1		*LINER ,FRONT FENDER ,LH	Serviceable	200.70 FL	*- FL
9	1		*GRILLE SUB ASSY ,RADIATOR	Serviceable	341.60 FL	*- FL
10	1		*GRILLE ,RADIATOR ,LOWER NO.1	Serviceable	167.90 FL	*- FL
11	1		*FRONT BONNET	Repair	969.00 FL	*- FL
12	1		*HINGE ASSY ,HOOD,LH	Repair	58.00 FL	*- FL
13	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Repair	583.30 FL	*- FL
14	1		*REINFORCE SUB-ASSY ,ROCKER OUTER LH	Repair	572.10 FL	*- FL
15	1		*FRONT WHEEL RIM	Serviceable	1,570.55 FS	*- FS
16	1		*FRONT WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
17	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
18	1		*CLIP, FRONT FENDER LINER	Not Necessary	22.00 FS	*- FS
19	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
20	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
21	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
22	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
23	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>12,058.54</b>	<b>575.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,300.10	127.28
<b>Total Parts (\$)</b>	<b>9,758.44</b>	<b>447.82</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,500.00	300.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
10	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
12	TO TRANSFER OF FRONT BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>11,170.00</b>	<b>755.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >