

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19016900/KKA3Q2

**Date:** 07/10/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100219067  
**Claimant**  
**Vehicle No :** SMC916M **Insured Vehicle No :** SJX8367U  
Date of Loss: 13/09/2019 Nature of Claim: TP Claim No: 4676150298SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC916M**  
Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6554217  
Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: GP71211706  
Colour: Metallic Grey Odometer: 124277 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15  
Front Left Side: Nexen 7 mm Rear Left Side: Nexen 7 mm  
Front Right Side: Nexen 7 mm Rear Right Side: Nexen 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,620.44	45.00	2,575.44	98.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	350.00	1,450.00	80.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,420.44</b>	<b>395.00</b>	<b>4,025.44</b>	<b>91.06</b>
<b>+ GST 7.00/7.00% (S\$)</b>	309.43	27.65	281.78	91.06
<b>Nett Amount (S\$)</b>	<b>4,729.87</b>	<b>422.65</b>	<b>4,307.22</b>	<b>91.06</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>610.10</b>		
<b>Global Sum Settlement (S\$)</b>		<b>600.00</b>		

#### INSPECTION

Date of Assignment: 24/09/2019  
Date Inspected: 25/11/2019 Inspected At: Esteem Performance Pte Ltd (HQ)  
Blk 5033 Ang Mo Kio Ind Park 2, #01-259  
Singapore 569536

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,100.00 FL	*- FL
2	10		*FRONT BUMPER CLIP	Not Necessary	40.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	470.90 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	25.40 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	25.40 FL	*- FL
6	1		*FRONT BUMPER BRACKET LH	Repair	58.00 FL	*- FL
7	1		*FRONT BUMPER BRACKET RH	Repair	58.00 FL	*- FL
8	1		*FRONT EMBLEM	Not Necessary	33.40 FL	*- FL
9	1		*FRONT GRILLE	Not Necessary	445.00 FL	*- FL
10	1		*FRONT GRILLE UPPER CHROME	Not Necessary	412.50 FL	*- FL
11	1		*FRONT GRILLE LOWER CHROME	Not Necessary	270.70 FL	*- FL
12	1		*FRONT BUMPER LOWER GRILLE	Serviceable	190.00 FL	*- FL
13	1		*FRONT BUMPER LOWER GRILLE LH	Serviceable	45.00 FL	*- FL
14	1		*FRONT BUMPER LOWER GRILLE RH	Serviceable	45.00 FL	*- FL
15	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,264.30</b>	<b>45.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	643.86	0.00
<b>Total Parts (\$)</b>	<b>2,620.44</b>	<b>45.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER,BONNET,SUPPORT PANEL)	New	800.00	150.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER,BONNET,SUPPORT PANEL)	New	800.00	200.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	0.00
4	TO TUFF COAT	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >