

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19016901/KDS3Q2**Date:** 07/04/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant**Vehicle No :** SKR5197H**Insured Vehicle No :** SJU7117Y

Date of Loss: 23/09/2019

Nature of Claim: TP

Claim No: 9816933730SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKR5197H**

Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)

Engine No: P520253531

Reg. Date: 12/02/2015 (Man. Year: 2014)

Chassis No: JM6BM42A8F0166176

Colour: Metallic Grey

Odometer: 94267 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Yokohama 8 mm

Rear Left Side:

Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,016.16	3,896.16	120.00	2.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,390.00	490.00	26.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	5,896.16	5,286.16	610.00	10.35
Approved Total (Overridden) (\$)		4,200.00		
(\$)	5,896.16	4,200.00	1,696.16	28.77
+ GST 7.00/7.00% (\$)	412.73	294.00	118.73	28.77
Nett Amount (\$)	6,308.89	4,494.00	1,814.89	28.77
+ Car Rental (7.0 x \$100.00/day) (\$)		700.00		
(\$)		5,194.00		
Liabe Amount (50.00%) (\$)		2,597.00		
+ Doc/Search Fee (\$)		15.00		
Nett Liability (\$)		2,612.00		
Global Sum Settlement (\$)		2,600.00		

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 25/09/2019 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,

#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	439.00 FL	*439.00 FL
2	1		*FRONT FENDER SHIELD	Distorted	135.00 FL	*135.00 FL
3	10		*FRONT FENDER SHIELD CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*FRONT DOOR RH	Bent	1,061.50 FL	*1,061.50 FL
5	1		*FRONT DOOR STICKER	Necessary	175.00 FL	*175.00 FL
6	1		*FRONT DOOR TOP HINGE	Repair	150.00 FL	*- FL
7	1		*FRONT DOOR LOWER HINGE	Distorted	145.00 FL	*145.00 FL
8	1		*FRONT WHEEL RIM	Dented	1,101.70 FL	*1,101.70 FL
9	1		*FRONT SHOCK ABSORBER	Bent	360.00 FL	*360.00 FL
10	1		*FRONT KNUCKLE ARM	Bent	402.00 FL	*402.00 FL
11	1		*FRONT KNUCKLE ARM BEARING	Necessary	368.00 FL	*368.00 FL
12	1		*FRONT KNUCKLE ARM BEARING HUB	Bent	125.00 FL	*125.00 FL
13	1		*FRONT LOWER ARM	Distorted	508.00 FL	*508.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,020.20	4,870.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,004.04	974.04
Total Parts (\$\$)	4,016.16	3,896.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /TRANSFER DOOR FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	100.00	60.00
3	TO DISMANTLE /REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	200.00	160.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT FENDER INNER PANEL WHEEL HOUSING ,FRONT DOOR PILLAR ,ROCKER PANEL AND PARTS REPLACEMENT	New	600.00	500.00
6	TO RESPRAY AFFECTED AREAS	New	750.00	550.00
Gross Labour Cost (\$\$)			1,880.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >